


COMPONENTS OF MANUFACTURING PROCESSES



**NARMADHA T
DIPENDRA KUMAR**

Components of Manufacturing Processes

Components of Manufacturing Processes

Narmadha T
Dipendra Kumar



BOOKS ARCADE

KRISHNA NAGAR, DELHI

Components of Manufacturing Processes

Narmadha T
Dipendra Kumar

© RESERVED

This book contains information obtained from highly regarded resources. Copyright for individual articles remains with the authors as indicated. A wide variety of references are listed. Reasonable efforts have been made to publish reliable data and information, but the author and the publisher cannot assume responsibility for the validity of all materials or for the consequences of their use.

No part of this book may be reprinted, reproduced, transmitted, or utilized in any form by any electronic, mechanical, or other means, now known or hereinafter invented, including photocopying, microfilming and recording, or any information storage or retrieval system, without permission from the publishers.

For permission to photocopy or use material electronically from this work please access booksarcade.co.in

BOOKS ARCADE

Regd. Office:

F-10/24, East Krishna Nagar, Near Vijay Chowk, Delhi-110051

Ph. No: +91-11-79669196, +91-9899073222

E-mail: info@booksarcade.co.in, booksarcade.pub@gmail.com

Website: www.booksarcade.co.in

Year of Publication 2023

International Standard Book Number-13: 978-93-90762-93-4



CONTENTS

Chapter 1. Basic Metals and Alloys	1
— <i>NARMADHA T</i>	
Chapter 2. Production Systems	14
— <i>Dr. Ashuthosh Pattanaik</i>	
Chapter 3. Atomic Structure and the Elements	26
— <i>Dr. Arunkumar D T</i>	
Chapter 4. Fluid Properties.....	41
— <i>Dr. Nagaraj Patil</i>	
Chapter 5. Die Forging with Power Hammers	53
— <i>Karthik N</i>	
Chapter 6. Ring Rolling.....	69
— <i>Dr. Sujai S</i>	
Chapter 7. Procedures of Bending	83
— <i>Dr. Ranganathaswamy M K</i>	
Chapter 8. Allowances for Patterns	94
— <i>Mr. Dipendra Kumar</i>	
Chapter 9. Making of Molds	111
— <i>Mr. Sanjeet Kumar</i>	
Chapter 10. Metals for Casting	119
— <i>Mr. Dipendra Kumar</i>	

CHAPTER 1

Basic Metals and Alloys

NARMADHA T,

Assistant Professor, Department of Computer Science Engineering,
Faculty of Engineering and Technology,
JAIN (Deemed-to-be University), Karnataka – 562112. India.
Email Id: - narmadhat2021@gmail.com

Materials are the driving force behind technical advancements and the essential components of manufacturing. Materials are all over us, and we utilise them in many ways. Understanding different sorts of materials and their qualities might help one appreciate the materials and production technique used. Mechanical qualities (such as strength, hardness, and toughness), thermal properties (conductivity), optical absorption (refractive index), electrical properties (resistance), and so on are examples of material properties. However, we will only focus on mechanical qualities, which are crucial in industrial processes as well as in daily life, and we use these phrases often. To understand mechanical characteristics, first understand the behaviour of the material when exposed to a force that produces deformation; this may be studied using the 'stress-strain diagram'.

Stress-Strain Diagram

Consider a rod with an initial length L_0 and an area A_0 that is subjected to a force F . Stress is defined as force per unit area, while strain is defined as the change in length (ΔL) divided by the starting length. As a result, $\text{Stress} = F/A_0$.

$$\text{Strain} = \Delta L / L_0$$

Figure 1.1 depicts the stress-strain curve for a material (say, mild steel). The stress-strain variation is linear up to proportionality point A. Hooke's law is still valid at this moment.

i.e., $\sigma = E \epsilon$, where E is the Young's modulus, also known as the modulus of elasticity. Beyond point A and up to point B, the material remains elastic, which means it returns to its former state when the forces operating on it are eliminated.




Figure 1.1 Stress-strain curve for ductile material.

If the specimen is strained beyond point B, permanent set occurs and we reach the plastic deformation area. Even when the force that caused the strain is gone, the strain remains in the plastic deformation zone. While the force is raised further, the test specimen extends even when the tension is not increased. This is known as the yield point. In reality, there are two yield points C and D, which are known as the upper and lower yield points.

With more stressing, a condition known as residual stress or work hardening occurs.

The material gets stronger and harder, with a rise in load bearing capability. As a result, the test specimen can withstand higher stress. Point E is attained by gradually increasing the force pressing on the specimen. This is the highest point on the stress-strain curve and reflects the most stress. As a result, it is referred to as the material's ultimate tensile strength (UTS). It is equal to the greatest load applied divided by the test specimen's initial cross-sectional area (A_0). The impact of increasing load on the gauge area of the test specimen must be considered here. The cross-sectional area of the specimen decreases as plastic deformation rises. However, the initial cross-sectional area is taken into account when calculating stress in the stress-strain graph. As a result, the point of breakage F seems to occur at a lower stress level than the UTS point E. Following UTS point E, the cross-sectional area of the test specimen is sharply reduced, and a "neck" forms in the centre of the specimen, eventually breaking in two parts as the neck grows thinner and thinner. When the decreased cross-sectional area of the test specimen is considered, the actual breaking stress is substantially larger than the UTS.

The ultimate tensile strength (at point E) of a material is a measure of its strength. However, in the eyes of a design engineer, the yield point is more significant since the structure he creates must sustain forces without giving. The yield stress (at point D) is usually two-thirds of the UTS, and this is known to as the materials yield strength. In practice, a tensile test is performed on a tensile tester or a universal to determine UTS. Machine for testing. The tensile test piece has been standardised so that tests performed in various facilities on another material provide equal results. Depicts a standard test item. This curve has no yield point, and the test specimen breaks abruptly with no discernible necking or extension. In the lack of a yield point, the idea of "proof-stress" has emerged for quantifying brittle material yield strength. 0.2% proof-stress, for example, is the stress at which the test specimen suffers a permanent extension equal to 0.2% of its original gauge length and is indicated by 0.2.

The tensile test and the stress-strain curve have been detailed in some depth above because they may provide a lot of helpful information about other characteristics of the material. It should be noted why most tensile testing machines have the capability of performing a compressive strength test as well.

Ductility and Malleability

Both of these traits are related to the material's plasticity. Malleability refers to the ability of plastic to deform under compressive stresses, while ductility refers to the capacity of plastic to deform under tensile loads. A bendable substance is capable of being pounded into thin sheets and even thinner foils. Wires may be formed from a ductile material. "Percentage elongation" is a ductility metric. Two punch marks are created on the stem of the tensile test piece before the tensile test commences. The distance between these markers is measured and is referred to as gauge length. When the tensile test component breaks into two pieces, the two pieces are recovered and positioned as near together as feasible. The distance between the two punch marks is now measured and recorded once again. Let's

High % elongation readings imply that the material is particularly ductile. Low values imply that the material is brittle and ductile. Mild steel typically has a percentage elongation of 20% or more.

Brittleness

Brittleness is the polar opposite of ductility. It is a quality held in large quantities by glass and other ceramics. When a piece of glass is dropped on a hard surface, it shatters and breaks into multiple fragments. Brittleness is caused by the material's inability to sustain stress loads. Glass, of course, is an extreme example of fragile material.

Strength and Resilience

A material with a high modulus of elasticity is considered to be stiff, whereas one with a low modulus of elasticity is said to be robust. Consider a material that is subjected to tensile stress within its elastic range.

If the material has a high Young's modulus (the modulus of elasticity equivalent to tensile stress), it will not stretch very far. It will act as though it were a "stiff" material. The slope of the line OA (Fig. 1.1) will be greater in this instance. The trait of resilience is diametrically opposed to stiffness. Under comparable stress conditions, a beam composed of stiff material will deflect less than one made of resilient material.

Toughness and Impact Power

Toughness and impact strength are traits that are related or comparable (although these are some differences as mentioned later). They reflect the material's capacity to absorb energy prior to failure/fracture. If we adjust the size of the y-axis, plot force on it, and display real elongation on the x-axis instead of strain, we will get a force-elongation curve instead of a stress-strain curve. The curve's form will not change; just the scales of the x and y axes will vary. The region under this curve now represents the energy necessary to fracture the material.

The more the energy, the greater the material's toughness. Toughness is determined by the combination of strength and percentage elongation. This feature is particularly essential since it allows a material to tolerate both elastic and plastic stresses. Toughness increases with increasing impact strength. Dynamic loads are employed in real impact testing, and the force is delivered to the specimen via a sharp notch.

Two tests have been developed to assess a material's impact strength (as also its toughness). These tests are known as the IZOD test and the Charpy test. The IZOD test is briefly discussed below. This specimen is mounted vertically in the IZOD testing equipment. The test specimen is then hit with a blow from just a swinging pendulum falling from a set height 22 mm above the notch. The pendulum's mass is known. Because the height from which the pendulum drops to hit the blow is also known, we can calculate the energy stored there in pendulum (m.g.h.)

The pendulum goes on after hitting and shattering the test piece at the notch, and the height to which it rises on the opposite side of the test piece is documented and measured. The remaining energy in the pendulum may therefore be determined. The difference in energy between the initial energy in the pendulum and the energy left over after breaking this test specimen is presumed to have been consumed in the breaking of the test specimen. This is considered as the impact strength of the specimen's substance. To get an accurate result, a friction correction factor at the pendulum bearing is used.

Hardness

Hardness is a critical material attribute. Hardness is a measure of wear resistance and resistance to abrasion or scratching. A hard substance is also resistant to being penetrated by another body. In the past, a hardness scale was constructed, and diamond, the hardest known substance, was placed at the top of this scale. Glass and other elements were placed at the bottom of the scale. A basic scratch test was utilised as the criteria. If one substance could scratch another, the former was regarded harder compared to the latter and was ranked higher on the hardness scale.

Several hardness tests have been developed in contemporary times. The most common are the Brinell hardness test, the Rockwell hardness test, and the Vicker's hardness test. All of these tests are based on the material's resistance to penetration into the surface of the test specimen by a specially designed and manufactured "indenter" under specified load. Because a harder material provides greater resistance, the indenter cannot penetrate its surface to the same depth as it would if the test specimen were made of a softer substance. Thus, the hardness of a material is measured by the depth of the imprint created by the indenter into the test specimen or the area of the imprint left by the indenter into the specimen.

Fracture of Material

When a specimen is exposed to stress that exceeds its strength, it fails and eventually fractures into two or more fragments. We have previously discussed fractures of both ductile and brittle material during the discussion of the tensile test. The cross-sectional area is reduced in the vicinity of the broken region. Brittle fracture happens rapidly when a minor break in the material's cross-section evolves into a complete fracture. However, such a fracture does not exhibit considerable plastic deformation. Actually, an expert metallurgist may derive many fascinating information about the likely origin of the fractured surface and the both macro and micro metallurgical investigation of the fractured specimen. Aside from ductile and brittle fractures, there are also fractures generated by material fatigue and creep.

Fatigue Failure

Materials often fail or fracture at stress levels considerably below their strength if the force is either alternating or fluctuating regularly an example will demonstrate this. Consider the case of a two-wheeled axle.

The axle supports the weight of the automobile while also rotating with the wheels. Because of its weight, the axle deflects somewhat, creating compressive stress in the top half and tensile stress in the bottom half of the cross-section. However, since it rotates, every 180° revolution, the bottom half becomes the upper half and vice versa. As a result of the axle's rotation, the type of stress at every point in the axle alternates between compression and tension.

A changing stress cycle indicates that the amplitude of the stress changes on a regular basis but the sign remains constant. When a material is exposed to many million cycles of either alternating or variable stress, it becomes exhausted and fails, even though the magnitude of such pressures is far smaller than its strength. Fortunately, there is an alternating and fluctuating stress level that the material can endure without failing even if exposed to an unlimited number of cycles.

This is known as the endurance limit. A designer ensures that a component prone to fatigue in service is constructed in such a way that its real stress level stays below the endurance limit.

An inspection of a fatigue fracture reveals three different zones.

They are as follows:

The site of crack initiation, which is the location where the crack may have started, such as a notch like a key passage or a material defect like an impurity, or even a surface flaw. The fracture propagation area during service. This region is often defined by circular ring-like scratch marks with the site of fracture start in the centre. Remaining cross-sectional area with symptoms of unexpected breaking. As the crack propagates over time, the remaining cross-sectional area becomes too tiny to bear the load and cracks abruptly.

Creep Failure

Material failure may occur even under sustained stresses within the material's strength. This occurs when the submitted components are exposed to sustained loads over an extended period of time, particularly when they are treated to high temperature conditions. Stays in boilers and steam are two frequent instances. Turbine blades, furnace components, and so forth. Such failures are known as creep failures because the significant efforts have been made to deform plastically under such circumstances, although at a very slow pace. However, after lengthy periods of time, the influence of creep might become noticeable, resulting in component failure.

Manufacturing

Manufacturing may be described in two ways in the present context: technologically and economically. Manufacturing, from a technological standpoint, is the use of physical and chemical processes to change the geometry, characteristics, and/or appearance of a particular starting material in order to create parts or products; manufacturing also involves the assembling of many components to create goods. Manufacturing processes require a mix of equipment, tools, power, and labour. Manufacturing is nearly often done in a series of activities. Each process moves the substance closer to its ultimate condition.

Manufacturing, is the economic transformation of resources into things of higher value via one or more processing and assembly procedures. The fundamental idea is that manufacturing adds value to a material by altering its form or qualities, or by mixing it with other similarly changed materials.

The manufacturing activities done on the material have increased its value. Value is added when iron ore is transformed into steel. Value is added when sand is converted into glass. Value is added when petroleum is processed into plastic. And it becomes much more beneficial when plastic is moulded into the intricate geometry of a patio chair. Manufacturing and production are often used interchangeably. According to the author, production encompasses more than just manufacturing. For example, one may talk of "crude oil production," but "crude oil manufacturing" sounds out of place. However, in the domain of items such as metal components or vehicles, any term seems to be acceptable.

Manufacturing Products

Manufacturing is a vital economic activity carried out by businesses that sell goods to clients. A company's production method is determined by the sort of product it produces. \Industries of Production Industry is made up of businesses and organizations that manufacture or provide products and services. Primary, secondary, and tertiary industries may be distinguished. Agriculture and mining are examples of primary industries that develop and utilize natural

resources. Secondary industries turn the main industries' products into consumer and capital goods. The primary activity in this sector is manufacturing, although construction and electricity utilities are also covered. The service of the economy is made up of tertiary industries. Manufactured Goods Manufacturing sectors' final products are classified into two categories: consumer goods and capital goods. Automobiles, personal computers, televisions, tires, and tennis rackets are examples of consumer goods. Capital goods are items acquired by businesses in order to manufacture products and deliver services. Aircraft, computers, telecommunications equipment, medical equipment, trucks and buses, railroad trains, machine tools, and construction equipment are examples of capital goods. The service industry buy the majority of these capital items. Manufacturing accounts for around 15% of GDP in the United States, while services account for approximately 75% of GDP. However, the produced capital goods acquired by the service sector are the industry's enablers. The service industries could not exist without capital goods.

Other manufactured things, in addition to end products, include the materials, components, and supplies utilised by the firms that create the final products. Sheet steel, bar stock, metal stampings, machined components, plastic moldings and extrusions, cutting tools, dies, moulds, and lubricants are examples of these commodities. As a result, the manufacturing sectors are comprised of a complex infrastructure comprised of many types and layers of intermediary providers with whom the ultimate customer never interacts.

This book is more concerned with individual components pieces and completed products—than with continuous processes. Metal stampings are distinct items, yet the sheet-metal coil from which they are manufactured is continuous (almost). Many discrete items, such as extrusions and electrical wire, begin as continuous or semi continuous products. Long pieces trimmed to size are created in practically continuous lengths. A better example of a constant cycle is an oil refinery (Figure 1.2).




Figure 1.2 represents the product variety and production quantity

Product Variety and Production Quantity The number of items produced by a factory has a significant impact on the organization of its personnel, facilities, and operations. Annual production amounts may be divided into three categories: low production, quantities ranging from 1 to 100 parts per year; medium production, quantities ranging from 100 to 10,000 units per year; and large production, quantities ranging from 10,000 to millions of units. The limitations. The boundaries between the three ranges are rather arbitrary (in the author's opinion). These limits may fluctuate by a two orders of magnitude or more depending on the kind of product.

The number of units produced yearly of a certain product category is referred to as production quantity. Some plants that produce a multitude of diverse product categories, each in small or medium amounts. Other facilities focus on mass manufacturing of a single product type. It is informative to distinguish product variety from manufacturing quantity as a parameter. Product diversity refers to the many product designs or kinds manufactured at the facility. Varied items have different forms and sizes, perform different purposes, are aimed at different markets, have more elements than others, and so on. Each year, the number of distinct product kinds manufactured may be tallied. When the factory produces a large number of product varieties, it shows a wide range of products.

In terms of manufacturing operations, there is an inverse relationship between product diversity and production quantity. When a factory's mass customization is high, its production number is likely to be low; meanwhile, when production quantity is large, product variety is low. Manufacturing facilities often specialize in a combination of output amount and product diversity that falls somewhere along the diagonal band. Although product variety has been defined as a quantitative parameter (the number of different product types manufactured by the plant or company), this parameter is much less precise than production quantity because the number of different designs does not capture details on how much the designs differ. The differences between a car and an air conditioner are significantly bigger than the differences between an air conditioner and just a heat pump. There are variances between individual models within each product group.

Automobile business, the level of product variances might be minimal or large. Although the body shapes and other design aspects are almost identical, each of the United States' automakers builds automobiles with two or three distinct nameplates at the same assembly facility. The firm manufactures heavy vehicles at several facilities.

Manufacturing Capability

A manufacturing plant is a collection of processes and technologies (as well as people) intended to convert a restricted range of inputs into higher-value goods. The topic of contemporary manufacturing is made up of these three basic blocks: materials, processes, and systems. These variables are very interdependent. A manufacturing business cannot accomplish everything. It must only accomplish certain things, and those things must be done properly. Manufacturing capacity refers to a company's and each of its facilities' technological and physical constraints. This capacity has many aspects that may be identified: (1) technical processing capabilities, (2) physical product size and weight, and (3) manufacturing capacity. Capability for Technological Processing The accessible set of manufacturing processes is a plant's (or company's) technical processing capabilities. Certain plants are effective.

Others do machining activities, while others roll steel billets into sheet stock and yet others construct autos. A machine shop cannot roll steel, and a rolling mill cannot construct automobiles. The operations that these plants can execute are the fundamental property that differentiates them. Material type is intimately connected to technological processing capabilities. Particular manufacturing procedures are better suited to certain materials, while others are better suited to others. The factory specialises in particular material types by specialising in a certain process or collection of operations. The competency of technological processing involves not only the physical procedures, but also the experience of plant staff in

various processing technologies. Companies must focus on product design and manufacturing that is suitable with their technical processing capabilities.

Physical Product Restrictions

The physical product imposes a second element of production competence. The size and weight of the goods that can be accommodated in a plant with a certain set of procedures is restricted. Large, hefty items are difficult to transport. To carry these items, the factory must be outfitted with cranes with the necessary weight capability. Smaller pieces and large-quantity items may be conveyed via conveyor or other ways. The physical capacity of the production equipment is also limited by product size and weight. There are several sizes of production machinery. To process bigger pieces, larger machinery must be employed. Production and material handling equipment must be designed for goods of a certain size or weight range.

Capacity for Production

The production amount that can be generated in a particular time period is a third restriction on a plant's manufacturing capabilities (e.g., month or year). This quantity restriction is known as plant capacity or production capacity, and it is defined as the greatest rate of output that a plant may attain given anticipated operating circumstances. The operational circumstances pertain to the number of shifts per week, the number of hours per shift, the plants direct labour manning levels, and so on. These elements are inputs to the manufacturing facility. How much production can the factory create given these inputs.

Plant capacity is often quantified in terms of output units, such as the number of cars produced by a complete assembly plant or the yearly tonnes of steel produced by a steel mill. The outcomes are homogenous in these circumstances. In circumstances when the output units are not uniform, other criteria, such as available labor hours of industrial output in a machine shop that produces a range of components, may be more relevant measurements. The three primary topic areas of this book are materials, processes, and systems, which are the fundamental building blocks of production.

Materials in Manufacturing

Most engineering materials fall into one of three categories:

1. Metals
2. Ceramics
3. Polymers

Their chemistries vary, as do their mechanical and physical qualities, and these variances influence the manufacturing procedures that may be employed to make goods from them. There are, in addition to the three main groups, Metals used in metalworking are often alloys made of two or more elements, at least one of which is metallic. Metals and alloys are classified into two types: ferrous and nonferrous.

Metals containing iron Steel and cast iron are examples of ferrous metals, which are based on iron. These metals are the most significant commercially, accounting for more than three-quarters of global metal tonnage. Pure iron has few economic use, but when alloyed with carbon, it has more applications and profit than any other metal. Steel and cast iron are iron and carbon alloys.

Steel is an iron-carbon alloy with a carbon content ranging from 0.02% to 2.11%. It is the most significant category of ferrous metals. Its composition often incorporates additional alloying

elements, including as manganese, chromium, nickel, and molybdenum, to improve the metal's characteristics. Steel is used in construction (bridges, I-beams, and nails), transportation (trucks, railways, and railroad rolling stock), and consumer items. Cast iron is an iron-carbon (2% to 4%) alloy used in casting (mainly sand casting). Silicon is also contained in the alloy (in concentrations ranging from 0.5% to 3%), and additional elements are often added to achieve acceptable qualities in the cast portion. Cast iron is available in numerous forms, the most common of which being grey cast iron; its uses include blocks and heads for internal combustion engines. Metallic nonferrous metals other metallic elements and their alloys are included in nonferrous metals. In virtually every situation, alloys are more valuable economically than pure metals.

Aluminum, copper, gold, magnesium, nickel, silver, tin, titanium, zinc, and other metals are examples of nonferrous metals.

Ceramics

A ceramic is a compound that contains both metallic (and semi metallic) and nonmetallic components. Nonmetallic elements include oxygen, nitrogen, and carbon. Ceramics are made from both traditional and contemporary materials. Clay (abundantly available, consisting of fine particles of hydrous aluminum silicates and other minerals used in making brick, tile, and pottery); silicon (the basis for nearly all glass products); and alumina and silicon carbide (two abrasive materials used in grinding) are examples of traditional ceramics. Some of the previous ingredients, such as alumina, are used in current ceramics, and their qualities are increased in different ways using modern processing processes.

Newer ceramics include carbides, which are metal carbides like tungsten carbide and titanium carbide that are extensively utilized as cutting tool materials, and nitrides, which are metal and semimetal nitrides like titanium nitride and boron nitride that are used as cutting tools and grinding abrasives. Ceramics may be separated into two types for processing: crystalline ceramics and glasses. The two categories need different production procedures. Crystalline ceramics are made from powders in a variety of methods and then fired (heated to temperatures below the melting point to create bonding between the particles). Glass ceramics (specifically, glass) may be melted and cast, then molded using techniques such as classic glass blowing.

Polymers

A polymer is a substance composed of mer-like repeating structural units whose atoms share electrons to produce enormously big molecules. Polymers are often composed of carbon combined with one or more additional elements such as hydrogen, nitrogen, oxygen, and chlorine. Polymers are classified into three types: thermoplastic polymers, thermosetting polymers, and elastomers. Thermoplastic polymers may be exposed to many heating and cooling cycles without significantly affecting the polymer's molecular structure. Polyethylene, polystyrene, polyvinylchloride, and nylon are examples of common thermoplastics. Thermosetting polymers chemically convert (cure) into a hard structure when cooled from a heated plastic state, thus the name. Phenolic, amino resins, and epoxies are examples of this class.

Despite the name, several of these polymers cure by methods other than heating. Elastomers are polymers with substantial elastic properties, thus the name. Natural rubber, neoprene, silicone, and polyurethane are among them.

Composites

Composites are not actually a distinct material category; they are combinations of the other three. A composite is a material made up of two or more phases that are produced independently and then bonded together to acquire qualities that are superior to the components. The word phase refers to a homogenous mass of material, such as an aggregation of grains in a solid metal with same unit cell structure. A composite's typical structure consists of particles or fibres of one phase mixed in a second component known as the matrix. Composites are present in nature (for example, wood) and may be manufactured synthetically. Glass fibres in a polymer matrix, such as fiber-reinforced plastic; polymer fibres of one type in a matrix of a second polymer, such as an epoxy; and ceramic in a metal matrix, such as tungsten carbide in a cobalt binder to form a cemented carbide cutting tool, are of greater interest. The properties of a composite are determined by its components, their physical forms, and how they are mixed to make the final substance. Some composites combine great strength with low weight, making them ideal for aviation components, vehicle bodywork, boat hulls, tennis rackets, and fishing rods. Other composites, such as cemented carbide cutting tools, are strong, hard, and capable of preserving these features at high temperatures.

Manufacturing Processes

A manufacturing process is a planned method that results in physical and chemical modifications to a beginning work material in order to increase its value. A manufacturing process is often carried out as a unit operation, which means it is a single step in the series of actions necessary to change a starting material into a finished product. Manufacturing activities are classified into two types: processing operations and assembly operations. A processing procedure moves a work material from one stage of completion to a later stage that is closer to the ultimate intended result. It adds value to the beginning material by modifying its shape, qualities, or appearance. In general, processing activities are conducted on discrete work parts, however specific processing processes (for example, painting a spot-welded vehicle body) are also relevant to assembled objects. An assembly operation unites two or more components to form a new entity known as an assembly, subassembly, or other word for the joining process (e.g., a welded assembly is called a weldment) depicts a taxonomy of manufacturing processes. Many of the production techniques discussed in this work may be seen on the accompanying DVD. Throughout the text, alerts are given on these video segments. Some of the fundamental methods employed in contemporary production stretch back to antiquity.

Processing Operations

More than one processing activity is necessary to turn the beginning material into the final form. The procedures are carried out in the precise order necessary to accomplish the geometry and conditions specified in the design specification. Processing activities are classified into three types:

- (1) Shaping operations
- (2) Property-enhancing operations
- (3) Surface processing operations

Various approaches are used in shaping operations to change the geometry of the beginning work material. Casting, forging, or machining are examples of common shaping methods. Property-enhancing procedures increase the value of a material by increasing its physical qualities while

preserving its form. The most frequent example is heat treatment. Surface processing activities are used to clean, treat, coat, or deposit substance onto the work's outside surface. Coatings are often used in plating and painting.

Forming Procedures

The majority of shape processing processes use heat, mechanical force, or a combination of these to modify the morphology of the work material. The shaping processes may be classified in a variety of ways. This book's categorization is based on the status of the initial material, and there are four categories:

- (1) Solidification processes, when the starting material is a heated liquid or semifluid that cools and solidifies to form the part geometry;
- (2) Particulate processing, in which the starting material is a powder, and the powders are formed and heated into the desired geometry;
- (3) Deformation processes, in which the starting material is a ductile solid (usually metal) that is deformed to shape the part; and
- (4) Material removal processes, in which the starting material is a ductile solid.

The initial material is a solid (ductile or brittle), from which material is removed to create the appropriate shape in the resultant portion. The initial material is heated enough in the first category to turn it into a liquid or highly plastic (semifluid) state. Almost any material may be handled in this manner. Metals, ceramic glasses, and polymers can all be heated to high enough temperatures to become liquids.

When the material is in a liquid or semifluid state, it may be poured or otherwise pushed to flow into a mould cavity and allowed to solidify, forming a solid shape that matches the cavity. The majority of these procedures are known as casting or moulding. Metals are referred to as casting, whereas polymers are referred to as moulding. Despite the fact that these two materials are so different, the procedures used to form them in particle processing are very similar. The most popular method is pressing and sintering, in which the powders are first pressed into a die cavity under high pressure and then heated to fuse the individual particles together. Deformation methods shape the beginning workpart by applying pressures that surpass the material's yield strength. To be created in this manner, the material must be sufficiently ductile to prevent fracture during deformation. To promote ductility (and for other reasons), the work material is often heated to a temperature below the melting point before forming. Metalworking is most closely related with deformation processes, which include activities like as forging and extrusion.

Material removal methods are activities that remove surplus material from the initial workpiece to get the required geometry. Machining activities such as turning, drilling, and milling are the most essential processes in this category, as shown in These procedures are most typically used on solid metals and are carried out using cutting tools that are tougher and stronger than the work metal. Another prevalent technique in this area is grinding. Nontraditional material removal technologies employ lasers, electron beams, chemical erosion, electric discharges, and electrochemical energy to remove material rather than cutting or grinding equipment.

It is preferable to reduce waste and junk when turning a beginning work part into its final shape. Certain shaping procedures are more efficient in terms of material conservation than others. Because of the way they function, material removal techniques (such as machining) tend to

waste material. At least in terms of the unit operation, the material eliminated from the initial form is waste. Other processes, like as casting and molding procedures, often turn almost 100% of the starting material into the finished product. Net shape methods are manufacturing techniques that convert virtually all of the starting material into product with no further machining to obtain final component geometry. Processes for Improving Property The second primary kind of component processing involves enhancing the mechanical or physical qualities of the work material. Except in rare situations, these techniques do not change the contour of the component. Heat treatments, such as different annealing, are the most significant property-enhancing techniques.

Surface Preparation Cleaning, surface treatments, and coating and thin film deposition are all examples of surface processing procedures. Cleaning involves both chemical and mechanical methods for removing dirt, oil, and other pollutants from the surface. Surface treatments include mechanical techniques like shot peening and sand blasting, as well as physical processes like diffusion and ion implantation. Coating and thin film deposition techniques add a material coating to the work part's outer surface. Electroplating, aluminum anodizing, organic coating (painting), and porcelain enameling are all common coating procedures. Physical vapour deposition and chemical vapor deposition are two thin film deposition methods used to create incredibly thin coatings of diverse substances.

Several surface-processing processes have been modified to manufacture semiconductor materials into microelectronic integrated circuits. Chemical vapor deposition, physical vapour deposition, and oxidation are examples of these processes. They are used to form the nanoscale circuit by applying them to extremely localised locations on the surface of a short piece of silicon or other semiconductor material.

Assembly Operations

Assembly is the second most fundamental sort of manufacturing activity, in which two or more independent pieces are linked to produce a new entity. The new entity's components are permanently or semi permanently linked. Welding, brazing, soldering, and adhesive bonding are all permanent connecting procedures. They link components that cannot be readily detached. Certain mechanical assembly techniques exist to attach two (or more) elements in a junction that can be easily disassembled. Traditional techniques in this category include the use of screws, screws, and other threaded fasteners. Other mechanical assembly methods, such as rivets, press fitting, and expansion fits, provide a more solid connection. In the assembly of electrical devices, special joining and fastening procedures are utilized. Some of the procedures are similar to or modifications of previous processes, such as soldering. Electronics assembly is largely concerned with the connection of components such as electronic circuit packages to printed circuit boards in order to create the complicated circuits seen in many of today's devices.

Production Machines and Tooling

Manufacturing processes are carried out with the assistance of equipment and tools (and people). The Industrial Revolution saw the widespread use of machines in production. Metal cutting machines began to be invented and extensively utilized about this period. These were known as machine tools, and they were power-driven machinery used to operate cutting instruments that were previously handled by hand. The same general concept applies to modern machine tools, except that the power is electromagnetic rather than water or steam, and the degree of accuracy and automation is considerably higher nowadays. Machine tools are among the most adaptable of

all manufacturing machinery. They are utilized to create not just consumer product parts, but also elements for other manufacturing machinery. The machine tool is the mother of all machinery, both historically and reproductively.

Presses for stamping operations, forge hammers for forging, rolling mills for rolling sheet metal, welding machines for welding, and insertion machines for putting electronic components onto printed circuit boards are examples of other manufacturing machinery. The name of the procedure is generally followed by the name of the equipment. Production equipment might be generic or specialised. General purpose equipment is more adaptable to a wide range of tasks. It is commercially open for investment by any manufacturing business. Special purpose equipment is often intended to mass-produce a certain item or product. Mass production economics support huge expenditures in specialised equipment to attain high efficiency and low cycle times. This is not the sole need for specialised equipment, but it is the most important. Another explanation might be because the procedure is one-of-a-kind and commercial equipment is not accessible. Some businesses with specialised processing needs create their own equipment.

Tooling that customises production machines for a specific item or product is frequently required. In many circumstances, the tooling must be custom-designed for the exact component or product configuration. It is intended to be swapped when used with general purpose equipment. The tooling for each workpart type is attached to the machine, and the production run is started. When the run is over, the tooling is modified to accommodate the following work part type.

When utilised with specialised machines, the tooling is often designed as an integrated element of the machine. Because the specialpurpose machine is likely to be used for production, the tooling may never need to be changed until worn components or worn surfaces are replaced.

CHAPTER 2

Production Systems

Dr. Ashutosh Pattanaik

Assistant Professor, Mechanical Engineering

Faculty of Engineering and Technology, JAIN (Deemed-to-be University), Ramanagara District,
Karnataka - 562112, India.

Email Id: - p.ashutosh@jainuniversity.ac.in

A manufacturing company must have procedures in place that enable it to efficiently complete its sort of production in order to function successfully. People, equipment, and procedures intended for the mix of materials and processes that comprise a firm's manufacturing activities comprise production systems. The division of production systems into two categories: (1) projects and (2) manufacturing support systems.

The physical equipment and the layout of equipment in the plant are referred to as production facilities. Manufacturing safety nets are the methods that a corporation uses to manage production and address technical and logistical issues that arise while procuring supplies, transferring work through the facility, and ensuring that products satisfy quality requirements. People are included in both categories. These systems are made to function by people. In general, direct labour employees are in charge of running manufacturing equipment, whereas professional staff workers are in charge of manufacturing support.

Production Facilities

The factory and its manufacturing, material handling, and other equipment comprise the production facilities. As the components and/or assemblies are being manufactured, the equipment comes into direct physical touch with them. The facilities come into contact with the product. The plant layout also includes the way the equipment is positioned in the factory. Manufacturing systems, such as an automated production line or a machine cell consisting of an industrial robot and two machine tools, are often arranged into logical groups of equipment. A manufacturing corporation strives to build its production systems and arrange its facilities in the most efficient manner possible to suit the specific objective of each facility, some kinds of production facilities have come to be regarded as the most suitable method to arrange for a specific combination of product diversity and output quantity. For each of the three yearly production quantity categories, different kinds of facilities are needed.

Low-Quantity Manufacturing The term work shop is often used to define the kind of manufacturing facility in the low-quantity range (1-100 units/year). A work shop produces small quantities of specialised and customised goods. Space capsules, prototype aeroplanes, and customised equipment are some examples of complicated items. A work shop's equipment is general-purpose, while the labour force is highly skilled. To cope with the large range of product variants encountered, a work shop must be structured for optimum flexibility (hard product variety). If the product is huge and heavy, and hence difficult to transport, it is usually manufactured or assembled in a single site.

Rather of transporting the product to the equipment, workers and processing equipment are transported to the product. This is referred to as a fixed-position arrangement. In a pure condition, the product is produced in a single site throughout its whole life. Ships, aeroplanes, trains, and heavy equipment are examples of such items. In fact, these items are often produced in enormous modules at a single site, and the finished modules are then hauled together for final assembly utilising high-capacity cranes.

Individual components of these huge goods are often manufactured in factories where the equipment is organised according to function or kind. This configuration is known as a process layout. The lathes are in one department, the milling machines in another, and so on. Separate components, each needing a different operation sequence, are routed through departments in the specific order required for processing, frequently in batches. The process plan is known for its adaptability; it can handle a wide range of operating sequences for various component configurations. Its downside is that the equipment and processes for producing a component are not efficient.

Medium-Scale Production Depending on the product variety, two kinds of facilities are defined in the medium-quantity range (100-10,000 units yearly). When product diversity is limited, the traditional strategy is batch production, in which a batch of one product is produced, then the manufacturing equipment is switched over to make a batch of the next product, and so on. Because the equipment's production rate exceeds the demand rate for any particular product type, the same equipment may be used across many goods.

It takes time to change tooling and set up the equipment between manufacturing runs. This setup time is wasted production time, which is one of the drawbacks of batch manufacturing. Batch manufacturing is often employed in make-to-stock circumstances. Items are produced to refill inventory that has already been steadily depleted as a result of demand. The equipment is often laid up in a process configuration, if product variation is limited, an alternate method to medium-range manufacturing is conceivable. In this instance, significant transitions from one product type to the next may not be required. It is often feasible to organise the production system such that groups of comparable goods may be manufactured on the same equipment without substantial setup time.

Cells are made up of many workstations or equipment that process or assemble various components or products. This method of production is often related with the phrase cellular manufacturing. According to group technology principles, each cell is intended to create a restricted number of component configurations; that is, the cell specialises in the manufacturing of a particular set of related parts.

High Productivity Mass production refers to high-quantity manufacturing (10,000 to millions of units per year). The product is in great demand, and the manufacturing system is committed to producing just that particular item. There are two types of mass manufacturing: quantity production and flow line production. The mass manufacture of single components on single pieces of equipment is referred to as quantity production. Standard machines (e.g., stamping presses) are often outfitted with unique tooling (e.g., dies and material handling devices), thus committing the equipment to the manufacture of a single item type. The process layout and cellular layout are two common layouts used in quantity manufacturing. Flow line manufacturing entails arranging many pieces of equipment or workstations in a sequential order, and the work units are physically moved through the sequence to produce the product. To enhance efficiency,

the workstations and equipment are precisely tailored for the product. The arrangement is known as both a product layout, and the workstations are positioned accordingly. Either one single line, or as a collection of linked line segments. Typically, work is transported between stations via motorized conveyor. Each station completes a little portion of the entire job on each product unit.

The assembly line, which is connected with items such as automobiles and home appliances, is the most well-known example for flow line manufacturing. The pure example of flow line manufacturing happens when the goods produced on the line are identical. Every product is the same, and the line is known as a single model manufacturing line. To effectively sell a product, it is often advantageous to create feature and model variants so that individual clients may choose the precise products that appeals to them. The feature distinctions are an example of soft product diversity from the standpoint of manufacturing. The phrase "mixed-model production line" refers to scenarios in which the goods produced on the line vary only slightly. An example is modern automotive assembly. Variations in choices and trim reflect multiple models and, in many instances, separate nameplates of the same fundamental automobile design as they roll off the manufacturing line.

Manufacturing Support Systems

A corporation must organize itself to develop procedures and equipment, plan and manage production orders, and meet product quality criteria in order to run its facilities effectively. Manufacturing support systems the personnel and processes that a corporation uses to manage its production operations carry out these duties. The majority of these support systems do not have direct touch with the product, but they plan and regulate its movement through the production. Manufacturing support services are often performed in the business by individuals grouped into departments such as the following:

Engineering in manufacturing

The manufacturing engineering department is in charge of manufacturing process planning, which includes choosing which procedures should be employed to create components and assemble products. This department also designs and orders the machine tools and many other equipment utilized by the operational divisions for processing and assembly.

Production planning and management

This department is in charge of resolving the logistical issue in manufacturing, which includes ordering supplies and bought components, scheduling production, and ensuring that the operational departments have the ability to fulfil production schedules.

Quality assurance. In today's competitive market, producing high-quality goods should be a key focus for every manufacturing company. It entails creating and constructing goods that meet or exceed client expectations while adhering to standards. The QC department is in charge of most of this work.

Lean Production And Six Sigma

These are two projects targeted at increasing production efficiency and quality. They respond to client requests for items that are both cheap in cost and excellent in quality. Lean and Six Sigma are trends because they are being extensively implemented by businesses, particularly in the United States. Toyota Motors in Japan invented the Toyota Production System, which is the foundation of lean manufacturing. Its roots may be traced back to the 1950s, when Toyota started

experimenting with unusual approaches to enhance quality, decrease inventory, and boost flexibility in its operations. Simply said, lean manufacturing is "performing more work with less resources." 2 It implies that fewer personnel and less equipments are utilised to produce more in less time while maintaining greater quality in the end output. The overarching goal of lean manufacturing is waste removal. The seven types of waste in production in the Toyota Production System are:

1. Production of defective parts
2. Production of more parts than necessary
3. Excessive inventories
4. Unnecessary processing steps
5. Unnecessary movement of workers
6. Unnecessary movement and handling of materials
7. Workers waiting

Toyota's waste-reduction approaches include error-prevention measures, Pausing a process when anything goes wrong, enhanced equipment maintenance, including employees in process improvements (so-called continuous improvement), and standardised work processes. The just-in-time delivery system, which is discussed in Section on production and inventory management, was perhaps the most significant advancement. Motorola Corporation in the United States pioneered Six Sigma in the 1980s. The goal was to eliminate variability in the company's operations and products in order to improve customer satisfaction. Six Sigma is now characterized as a "quality-focused programmer that employs worker teams to complete projects targeted at enhancing an organization's operational performance" 3 S.

Globalization and Outsourcing

The globe is becoming more interconnected, resulting in a worldwide economy in which obstacles traditionally imposed by national borders have been lowered or abolished. This has resulted in greater freedom of movement of goods and services, money, technology, and people between regions and nations. Globalization is the phrase used to characterize this tendency, which was first identified in the late 1980s and has since become a dominating economic reality.

It is worth noting that formerly undeveloped countries such as China, India, and Mexico have expanded their industrial infrastructures and technology to the point that they are now significant producers in the global economy. The benefits of these three nations are their big populations (and hence vast labour pools) and cheap labour costs. Hourly wages in the United States are now an order of magnitude or more higher than in these nations, making it difficult for domestic U.S. enterprises to compete in many goods needing a high labour content. Clothing, furniture, a variety of toys, and electrical equipment are all examples. As a consequence, the United States has lost manufacturing employment while gaining similar work in foreign nations.

Outsourcing is directly tied to globalization. Outsourcing in manufacturing refers to the employment of outside contractors to execute work that was formerly done in-house. Outsourcing may be accomplished in a variety of methods, including the utilization of local vendors. Jobs in this scenario stay in the United States. Alternatively, US corporations may outsource to other nations, such that components and products that were formerly manufactured in the US are now manufactured elsewhere. In this scenario, employment in the United States are being lost. There are two types of outsourcing:

Offshore outsourcing, which involves producing items in China or other overseas locations and transporting them by cargo ship to the United States, and

Near-shore outsourcing, which involves producing items in Canada, Mexico, or Central America and shipping them to the United States by rail or truck.

Because of its fast-growing economy, the significance of manufacturing in that economy, and the degree to which U.S. corporations have outsourced labour to China, China is a nation of special relevance in this topic of globalization. To take advantage of cheap labour costs, American businesses have outsourced most of their manufacturing to China (and other east Asian nations). Despite the logistical issues and expenses of getting the items back into the US, the upshot has been cheaper costs and larger profits for the outsourcing corporations, as well as lower pricing and a broader selection of available products for US customers.

The negative impact has been the loss of high-paying manufacturing employment in the United States. Another effect of US outsourcing to China has been a decrease in the manufacturing sector's proportionate contribution to GDP. Manufacturing sectors contributed for around 20% of US GDP in the 1990s. That contribution is now less than 15%. At the same time, China's manufacturing sector has expanded (along with the rest of the economy), accounting for over 35% of Chinese GDP. Because the US GDP is nearly three times that of China, the US manufacturing sector is still greater.

China, on the other hand, is the global leader in a number of sectors. Its steel tonnage production exceeds the combined outputs of the next six greatest steel manufacturing countries (Japan, the United States, Russia, India, South Korea, and Germany, in that order).⁴ China is also the greatest manufacturer of metal castings, accounting for more tonnage than the next three major producers (US, Japan, and India, in that order). Steel manufacturing and casting are considered "dirty" businesses, and pollution is a problem not just in China, but all across the world. The following trend addresses this problem.

Environmentally Conscious Manufacturing

Waste is a fundamental element of almost all production processes (. Material removal techniques, in which chips are removed from a beginning workpiece to form the required component shape, are the most apparent examples. Almost all manufacturing activities generate waste in some form or another. Another inescapable feature of production is the need for electricity to complete any given process. That power necessitates the use of fossil fuels (at least in the United States and China), the combustion of which pollutes the environment. A product is developed at the conclusion of the production sequence and sold to a consumer. Eventually, the product wears out and is discarded, maybe in a landfill, with the related environmental deterioration. Society is paying increasing attention to the environmental effect of human activities across the globe, as well as how contemporary civilization is depleting our natural resources at an unsustainable pace. Global warming is now a significant source of worry. These issues are exacerbated by the industrial industry.

Environmentally aware manufacturing refers to initiatives that strive to find the most effective use of materials and natural resources in manufacturing while minimising negative environmental repercussions. Green manufacturing, cleaner production, and sustainable manufacturing are other titles for similar projects. They all reduce down to two essential approaches:

1. Design goods with little environmental effect
2. Design environmentally friendly methods

The appropriate starting point for environmentally responsible production is product design. Design for environment (DFE) is a phrase that is frequently used to practises that aim to address environmental effect during product design prior to manufacturing.

DFE considerations include the following:

1. Choose materials that require the least amount of energy to produce
2. Choose processes that minimize material and energy waste
3. Design parts that can be recycled or reused
4. Design products that can be easily disassembled to recover the parts
5. Design products that use the least amount of hazardous and toxic materials
6. Consider how the product will be disposed of at the end of its useful life

The materials and procedures utilized to create the product are heavily influenced by design considerations. These choices restrict the manufacturing divisions' possibilities for achieving sustainability. Various measures, however, may be used to make plant operations more ecologically friendly. Among them are the following:

1. Use good housekeeping practices keep the factory clean
2. Prevent pollutants from escaping into the environment (rivers and atmosphere)
3. Minimise waste of materials in unit operations
4. Recycle rather than discard waste materials
5. Use net shape processes
6. Use renewable energy sources when feasible
7. Provide maintenance to production equipment so that it operates at maximum efficiency
8. Invest in equipment that uses the least amount of power

The book discusses a variety of themes linked to environmentally responsible production. Section 8 covers the themes of polymer recycling and biodegradable plastics. 5. Cutting fluid filtering and dry machining to mitigate the negative impacts of polluted cutting fluids.

Microfabrication and Nanotechnology

They are often so little that they are invisible to the human eye. In severe circumstances, the things are not even visible using an optical microscope. Miniaturized products need the use of specialised manufacturing techniques. The procedures required to create components and products with feature sizes in the micrometre range 1 mm 14 103 mm 14 106 m are referred to as microfabrication.

Ink-jet printing heads, compact discs (CDs and DVDs), and microsensors utilised in automotive applications are some examples (e.g., air-bag deployment sensors). Nanotechnology refers to materials and products with feature sizes on the nanoscale scale 1 nm 14 103 mm 14 106 mm 14 109 m, which is similar to the size of atoms and molecules.

Nanotechnology-based goods include ultra-thin coatings for catalytic converters, flat screen TV panels, and cancer treatments. Microscopic and nanoscopic materials and products are likely to grow in significance in the future, both technologically and economically, and commercial production procedures are required. The goal of this article is to make the reader aware of the trend toward miniaturisation.

Ferrous Materials

Ferrous materials are those whose principal ingredient is iron, while non-ferrous materials do not include any significant amount of iron. Ferrous materials are often stronger and tougher, and they are widely employed in our everyday life. Ferrous materials have the unique attribute of being able to have their properties dramatically changed by heat treatment techniques or the addition of modest amounts of alloying elements. Ferrous materials are generally inexpensive, but they have a significant drawback. They are prone to rusting and corrosion.

Steel and Iron

The most popular engineering materials are ferrous materials, which are iron alloys such as mild steel and stainless steel. It is true that gold is the metal for kings, and iron is the king of metals. "For the growth of a country, lectures and seminars are not vital; what is important are blood and steel," Germany's Otto Von Bismark reportedly declared. Iron is a prevalent element in both blood and steel. Though iron is significant, it is most often employed in the form of its alloy, steel.

To the average person, the terms iron and steel imply the same thing. But iron and steel are not the same thing. Iron is the term given to the metal with the chemical symbol Fe, which refers to pure iron (or almost pure iron). Pure iron is rather soft and weak. Its melting point is around 1540°C. Wrought iron is the closest material in purity to iron in industry, however it is seldom utilised these days. Steel, on the other hand, is an iron-carbon alloy with a carbon content ranging from 0% to 2%. In reality, however, carbon seldom reaches 1.25-1.3%. Carbon creates cementite (Fe₃C), an intermetallic combination that is very hard, brittle, and strong. Steel is significantly stronger and harder than pure iron due to the inclusion of cementite.

Steel Classification

Steel is divided into two types:

Ordinary carbon steel and alloy steel

Plain carbon steel is steel in which carbon is the sole alloying ingredient present. Aside from carbon, various alloying elements are used in alloy steel.

Elements such as chromium, nickel, tungsten, molybdenum, and vanadium are also present and make a significant variation in steel characteristics. Before proceeding, readers should be aware that, in addition to iron and carbon, four additional elements are always present in steels. These elements are S, P, Mn, and Si. It is not feasible to remove these components from steel. However, sulphur and phosphorus have a negative impact on steel characteristics and their percentages are normally not permitted to exceed 0.05%. Similarly, the average percentages of manganese and silicon in steel are maintained below 0.8 and 0.3%, respectively, despite the fact that their influence is not damaging to steel qualities. In fact, manganese mitigates the negative effects of sulphur. The inclusion of these four components at the level mentioned does not classify ordinary carbon steel as alloy steel. However, if greater percentages of Mn and Si are purposely added to steel to change its characteristics, the resultant steels are classified as alloy steels.

Plain Carbon Steels

Because the qualities of plain carbon steels are so reliant on their carbon percentage, these steels are further divided into the following carbon percentage-only categories:

Low carbon or dead mild steel with carbon content less than 0.15%, Mild steel with carbon content between 0.15-0.3%, Medium carbon steel with carbon content between 0.3-0.7%, and High carbon steel with carbon content more than 0.7% (the highest practical limit of C% is 1.3%). Plain carbon steel gains strength and hardness while losing ductility as the carbon content rises.

Plain Carbon Steel Applications and Uses

Steel that is no longer mild. It offers excellent weldability and ductility. As a result, it is employed in welded and solid drawn tubes, thin sheets and wire rods, and so on. It is also utilized for components that are subjected to stress loading yet must have a high wear resistance. To boost wear resistance, the components must go through a case hardening process, which gives a hard surface while keeping the core supple and robust.

Steel that has been milled. It is frequently employed in structural work. If the carbon content is kept to 0.25%, it preserves extremely excellent weldability. Mild steel is used to make forgings, stampings, sheets and plates, bars, rods, and tubes.

Steel with a medium carbon content. It has less weldability but is stronger and more durable than mild steel. It is utilized in railway axles, rotors and discs, wire ropes, steel spokes, marine shafts, carbon shafts, general agricultural equipment, and other applications. Steels with a high carbon content. Cold chisels, cold working dies, hammers, boiler maker's tools, wood working tools, hand taps and reamers, filers, razors, shear blades, and other hand tools are made of it. High carbon steels may be hardened by quenching and, once hardened, can be utilised for cutting tools that are not used in hot conditions. When heated (over 150°C), they lose their firmness and become dull.

Wrought Iron

Although it may include elements of carbon, it is the purest form of iron. It is often produced using the "puddling process," and it includes a little amount of slag in addition to iron. It is exceedingly expensive, and its usage has almost entirely been displaced by cheaper steel. Wrought iron is still the primary raw material for several components, such as chain links and chain hooks. Iron railing and gates constructed of wrought iron may still be seen in historic houses.

Cast Iron

Cast irons have a carbon content more than 2%, which is the maximum limit for steels. In reality, however, the carbon percentage of most cast irons ranges between 3 and 4%. One distinguishing feature of cast metals (excluding white cast iron) is that most of the carbon content exists in free form as graphite. This fact, in great part, defines the qualities of cast iron.

Cast iron is typically manufactured in coke-fired cupola furnaces by melting a combination of pig iron, scrap cast iron, and a tiny amount (often less than 5%) of small sized steel scrap. Cast iron has a substantially lower melting point than steel. Grey cast iron is used in the majority of castings produced in a cast iron foundry. These are inexpensive and commonly used.

There are several types of cast iron. The following are examples: grey cast iron, white cast iron, malleable cast iron, nodular cast iron, and alloy cast iron.

Grey cast iron, as previously stated, is frequently employed in the form of castings. In fact, it is so common that the word "cast iron" has come to refer to grey cast iron. Because of the graphite

in the cast iron, rubbing a finger over a recently split surface of grey cast iron coats the finger with grey color. Grey cast iron has a high compressive strength but a low tension strength. It is brittle yet reasonably soft. It is relatively simple to process, and the resultant surface polish is excellent. Because of the presence of graphite, it is self-lubricating and has strong vibration dampening properties. It is more corrosion resistant than steel. Because of these features, it is widely employed in the manufacture of machine beds, slides, gear-housings, steam engine cylinders, manhole covers, drain pipes, and so on. White cast iron and malleable cast iron are also available. White cast iron contains 2 to 2.5% carbon, the majority of which is in the form of cementite. When molten cast iron is rapidly cooled and lacks graphite-promoting components like Si and Ni, carbon stays in mixed form as Fe_3C . However, white cast iron has limited use. It is very hard and has a white fracture. Only the crushing rollers are constructed of white cast iron. However, it is employed as a raw material in the manufacturing of malleable cast iron.

A sophisticated and lengthy heat treatment of white cast iron castings produces malleable cast iron. Grey cast iron is brittle and has little or no elongation. Malleable cast iron castings lose part of the brittleness of grey iron and may be used in applications that need some ductility and toughness. (Note: "Mottled iron" is a term used to describe cast iron that has a structure that is half grey and part white.) Cast iron with nodules. This cast iron is also known as spheroidal graphitic cast iron. When a tiny amount of magnesium (0.5%) is added to molten cast iron, the graphite, which is typically found in grey iron in the form of graphite flakes, changes shape and stays distributed throughout the mass of cast iron. This change in the form of graphite particles has a significant impact.

The influence on the qualities of the resultant castings is significant, and their mechanical properties increase significantly. The strength rises, the yield point rises, and the brittleness falls. Some steel components may even be replaced by such castings. Cast iron alloy. Certain alloying elements, such as nickel, chromium, molybdenum, and vanadium, may be used to enhance the characteristics of cast iron. Alloy cast irons provide superior strength, heat resistance, and wear resistance, among other advantages. Cast irons' application and usage are expanded as a result of their improved characteristics. Alloy cast irons are used to make I.C. engine cylinders, cylinder liners, piston rings, and other components.

Steel Alloys

Just as the qualities of cast iron may be much enhanced by the addition of alloying elements to its composition, the properties of plain carbon steels can be greatly improved by the addition of alloying elements. In reality, the impact of alloying is far more pronounced in the case of steels. The primary goals of alloying in steels are:

1. Heat treatment techniques may harden alloy steels to deeper depths with less deformation and fracture.
2. As with stainless steels, alloying develops corrosion resistance.
3. As in cutting tools, alloying generates the trait of red hardness.
4. As with high strength low alloy (HSLA) steels, alloying increases the strength and toughness of steels.

Some alloy steels exhibit significant resistance to grain development and oxidation at high temperatures, for example.

Chromium, nickel, tungsten, molybdenum, vanadium, cobalt, manganese, and silicon are the most common alloying elements. Alloy steels come in a wide range of grades, each designed for a particular use.

Steels made of stainless steel. Stainless steels are so-called because they do not corrode or rust readily. The most common alloying elements are chromium and nickel. Stainless steels are further classified into the three types listed below:

Stainless steel that is ferritic. Apart from iron and the standard proportions of manganese and silicon, these steels include a maximum of 0.15% carbon, 6-12% chrome, and 0.5% nickel. These steels are both stainless and reasonably priced. They are magnetic as well. These steels are now used to make one and two rupee coins. Because these steels are basically iron-chromium alloys, heat treatment cannot be used to harden them. Such steel is primarily used in the production of dairy equipment, food processing facilities, and the chemical sector, among other things.

Martensitic stainless steel

These stainless steels have 12-18% chromium but a greater amount of carbon (0.15-1.2%). Heat treatment may harden these steels, but also reduces their corrosion resistance. These steels are used to make surgical knives, hypodermic needles, bolts, nuts, screws, and blades, among other things.

Austenitic stainless steels

These are the most essential and expensive stainless steels. Nickel is added to these steels in addition to chromium. Because nickel is a powerful austenite stabilizer, the microstructure of these steels is austenitic at room temperature. The most common stainless steel is 18/8 steel. It contains 18% chromium, 8% nickel, 0.08-0.2% carbon, 1.25% manganese, and 0.75% silicon.

These steels have excellent corrosion resistance but cannot be toughened by heat treatment. They are, nevertheless, very vulnerable to "strain-hardening". In fact, because to strain hardening, machining becomes very difficult. It is widely used in home utensils, chemical factories, and other locations where excellent corrosion resistance is needed. Steels for tooling. A tool steel must be capable of becoming very hard and must also be able to sustain its hardness at high temperatures usually seen during the cutting of steel and other materials. "Red hardness" is the name given to this feature. Furthermore, tool steel should be strong and not brittle.

The most popular tool steel is known as high speed steel (HSS). Its name suggests that it can cut steel at fast rates. The temperature rises faster at high cutting speeds, although high speed steel tools can keep their hardness up to 600-625°C. The inclusion of tungsten results in the red hardness attribute. H.S.S. has a normal composition of 18% tungsten, 4% chromium, 1% vanadium, 0.75-1% carbon, and the remainder iron.

Tungsten is an expensive metal. It has been discovered that molybdenum may also give "red hardness" to steel, and that 5% molybdenum can replace 1% tungsten. Molybdenum is much less expensive than tungsten. T-series steels are made of tungsten, whereas M-series steels are made of molybdenum. A particularly valuable H.S.S. has tungsten (6%), molybdenum (6%), chromium (4%), and vanadium (2%), in addition to iron and carbon.

Super high speed steel is another name for H.S.S. It is intended for heavy-duty tools and contains 10-12% cobalt, 20-22% tungsten, 4% chromium, 2% vanadium, 0.8% carbon, and the remainder iron. In addition to H.S.S., tools are now constructed of tungsten carbide and other materials.

Steels with Special Alloys

Steels containing manganese.

To counteract the negative effects of sulphur, all steels include trace quantities of manganese. True manganese alloy steels have much more Mn. They have the ability to harden work. They are utilised for railway crossings and points, and as they are used, they grow more wear-resistant.

Nickel-based steels

Up to 50% nickel may be added to steel. Nickel makes the steel extremely corrosion resistant, nonmagnetic, and with very low coefficients of thermal expansion. These steels are utilised in turbine blades, internal combustion engine valves, and other applications.

Chromium steels Chromium protects steel from corrosion and boosts its UTS and IZOD strength. Alloy steels with chromium and nickel added are often utilised. Nickel-chromium steel wires are often used in furnaces, toasters, and heaters.

Silicon steels

A steel having 0.05% carbon, 0.3% Mn, and 3.4% silicon has exceptionally low magnetic hysteresis and is commonly used for electrical machine laminations. Silico-manganese steels are also extensively utilised in the manufacture of springs.

Heat Treatment of Carbon Steels

The heat treatment object. Heat treating metals and alloys improves their mechanical characteristics, relieves internal tensions, and improves machinability. The characteristics of carbon steels may also be dramatically affected by heat treatment methods.

Heat treatment is made up of three fundamental steps:

Bring the metal/alloy to a certain temperature. This temperature will ideally depend on the actual carbon steel composition (i.e. carbon percentage), soaking or holding the metal/alloy at that heat flux for some time, so that the temperature across the entire cross-section becomes uniform, and cooling the metal/alloy at a predetermined rate in a suitable medium such as water, oil, or air. The most crucial component is the pace of cooling.

Carbon Steels Receive Various Heat Treatments

Carbon steels go through four main heat-treatment processes

1. Annealing,
2. Normalising
3. Hardening
4. Tempering

Annealing. Annealing is used to soften the material. Internal stressors, if any, will be eliminated in addition to softening. Soaking duration should be set at 3-4 minutes for per millimetre thickness of the material's cross-section. The work item is permitted to cool within the furnace only after the electrical power or oil supply to the furnace is turned off. This allows the work item to cool at a very slow pace. Due to grain development, this process softens the material and

increases its ductility. Normalising entails heating to the same temperatures as recommended for annealing (except for high carbon steel specimens, which must be heated too much higher temperatures than recommended for annealing, especially as the carbon percentage in the sample increases), soaking, and then cooling the sample in still air. The primary goal of normalisation is to eliminate internal tensions and refine grain.

Hardening. Hardening is accomplished by heating (to the same temperatures as annealing) and soaking. Following that, the work piece is removed from the furnace and rapidly cooled in a tank of cold water or oil while being forcefully agitated in the water/oil. (This chilling process is known as "quenching.") As a consequence, the work piece hardens. To harden, however, the carbon concentration of the work piece must be at least 0.25%. As a result, dead mild steel cannot be toughened in this manner. Mild steel will also harden somewhat if it contains more than 0.25% carbon. The greater the carbon content, the higher the final hardness.

Hardened parts become very fragile, which is a significant drawback. They often fail in service. As a result, the hardening process is always followed by a tempering procedure. Tempering. Tempering entails sacrificing some hardness while losing a significant degree of brittleness gained during the hardening process. It is a trade-off between hardness and brittleness, such that a hardened component may perform usefully without failure.

Tempering entails heating the carbon steel part to temperatures ranging from 150° to 600° C (depending on how much tradeoff is necessary) and cooling the component in an oil, salt, or even air bath.

Hardening of the case. As previously stated, only carbon steels with a carbon concentration of 0.25% or above may be toughened. How is dead mild steel hardened? Case hardening is the solution. The work item is packed in charcoal and heated similarly to annealing in this technique. For a few hours, it is held at that high temperature. As a consequence, carbon penetrates the surface of the work item to a depth of a millimetre or two, depending on the heating period. The work piece now has a casing with the required carbon percentage for hardening. It is then heated and quenched as normal. As a consequence, the surface of the component hardens while the core remains soft and robust.

CHAPTER 3

Atomic Structure and the Elements

Dr. Arunkumar D T,
Assistant Professor, Mechanical Engineering
Faculty of Engineering and Technology, JAIN (Deemed-to-be University), Ramanagara District,
Karnataka - 562112, India
Email ID: - dt.arunkumar@jainuniversity.ac.in

The atom is the fundamental structural unit of matter. Each atom is made up of a positively charged nucleus surrounded by a sufficient number of negatively charged electrons to balance the charges. The atomic number and element of the atom are identified by the number of electrons. There are slightly more than 100 elements (not including a few additional created intentionally), and these elements are the chemical building blocks of all matter. There are parallels as well as variances among the components.

The Periodic, may be used to classify the elements into families and build connections between and within the families. The arrangement of components in the horizontal direction has a particular recurrence, or periodicity. Metallic elements are positioned on the left and centre of the chart, whereas nonmetals are on the right. A transition zone comprising metalloids or semimetals exists between them along a diagonal. Depending on temperature and pressure, any element may exist as a solid, liquid, or gas. They each have a natural phase at ambient temperature and atmospheric pressure; for example, iron (Fe) is a solid, mercury (Hg) is a liquid, and nitrogen (N) is a gas.

The components in the table are organised into vertical columns and horizontal rows such that commonalities between entries in the same columns occur. In the far right column, for example, are the noble gases (helium, neon, argon, krypton, xenon, and radon), all of which have high chemical stability and low reaction rates. The halogens in column VIIA (fluorine, chlorine, bromine, iodine, and astatine) have comparable characteristics (hydrogen is not among the halogens). Column IB contains noble metals (copper, silver, and gold) with comparable characteristics. Correlations in attributes occur between items within a specific column, while discrepancies exist between elements in other columns.

Many similarities and differences between elements may be explained by their atomic structures. The planetary model, the simplest model of atomic structure, depicts the electrons of the atom revolving around the nucleus at predetermined distances termed shells, the hydrogen atom (atomic number 1) has one electron closest to the nucleus in the orbit. Helium (atomic number 2) contains two protons. The atomic structures of fluorine (atomic number 9), neon (atomic number 10), and sodium are also shown in the illustration (atomic number 11). These theories suggest that there is a maximum number of electrons that can be housed in a venorbit. This seems to be accurate, and the maximum is described as Maximum number of electrons on an orbit $2n^2$ where n identifies the orbit and $n = 1$ is closest to the nucleus.

The number of electrons in the outermost shell, compared to the maximum number permitted, influences the atom's chemical affinity for other atoms to a great amount. Valence electrons are electrons in the outer shell. Because a hydrogen atom only contains one electron in its single

orbit, it easily unites with another hydrogen atom to create a hydrogen molecule H_2 . For the same reason, hydrogen quickly interacts with a variety of other elements (e.g., to form H_2O). Helium is particularly stable because the two electrons in its single orbit are the maximum permitted ($2n^2 = 2 \cdot 1^2 = 2$). Because its outermost orbit ($n=1$) contains eight electrons (the maximum permitted), neon is an inert gas.

Fluorine, unlike neon, has one less electron in its outer shell ($n=2$) than the maximum permitted and is easily attracted to other elements that may share an electron to form a more stable set. With one electron in its outermost orbit, the sodium atom seems to be divinely designed for the scenario. It significantly interacts with fluorine to generate the chemical sodium fluoride.

Bonding Between Atoms and Molecules

Atoms in molecules are kept together by many sorts of bonds that are dependent on the valence electrons. In contrast, weaker bonds draw molecules to one other, which are mainly caused by the electron arrangement in the individual molecules. Thus, there are two forms of bonding: (1) primary bonds, which are often involved with molecule production, and (2) secondary bonds, which are generally linked with molecule attraction. Primary bonds are much more powerful than secondary ones. Principal Bonds Primary bonds are distinguished by strong atom-to-atom attractions involving valence electron exchange depicts the several types of primary bonds: (a) ionic, (b) covalent, and (c) metallic. Because they include attractive interactions between atoms inside the molecule, ionic and covalent bonds are referred to as intramolecular bonds.

The atoms of one element give up their outer electron's in the ionic connection, which are then attracted to the atoms of another element, increasing their electron count in the outermost shell to eight. In general, the most stable atomic configuration (save for extremely light atoms) is eight electrons in the outer shell, and nature creates a very strong link between atoms to attain this configuration. This kind of atomic link is shown in the preceding example of the interaction of sodium and fluorine to generate sodium fluoride a more typical example is sodium chloride (table salt). Because of the electron transfer between the atoms, sodium and fluorine (or sodium and chlorine) ions are generated, giving rise to the name of this bonding. Low electrical conductivity and ductility are two properties of solid materials with ionic bonding.

Covalent bonds are formed when electrons are shared (rather than transported) between atoms in their outermost shells to form a stable set of eight. Covalent bonding may be found in fluorine and diamond. Fshows how one electron from each of two fluorine atoms is shared to generate F_2 gas (a). In the case of diamond, which is carbon (atomic number 6), each atom shares electrons with four neighbours.

This results in a highly rigid three-dimensional structure, which is not fully portrayed, and accounts for the material's very high hardness. Other types of carbon, such as graphite, lack this tight atomic structure. Covalently bonded solids have a high hardness and a poor electrical conductivity.

The atomic bonding process in pure metals and metal alloys is, of course, the metallic bond. In general, metallic atoms have too few electrons in their outermost orbits to complete the outer shells of all the atoms in, say, a particular block of metal. As a result, rather than atom-to-atom sharing, metallic bonding includes all atoms exchanging outer-shell electrons to generate a broad electron cloud that pervades the whole block. In most instances, this cloud supplies the attraction

forces that keep the atoms together and produces a strong, rigid structure. Metallic bonding offers strong electrical conductivity due to the universal sharing of electrons and their freedom to travel inside the metal. Other common qualities of metallically bonded materials include high heat conduction and ductility. While some of these concepts remain undefined, the book depends on the reader's broad grasp of material characteristics.

Bonds issued in the secondary market Secondary bonds, as opposed to primary bonds, entail attraction forces between molecules, also known as intermolecular forces. Because there is no electron transfer or sharing in secondary bonding, these bonds are weaker than primary bonds. Figure 2.6 depicts three types of secondary bonding: (a) dipole forces, (b) London forces, and (c) hydrogen bonding. Types (a) and (b) are sometimes referred to as van der Waals forces, after the scientist who examined and measured them initially.

Dipole forces form in a molecule composed of two atoms with opposing electrical charges. As a result, each molecule produces a dipole, for hydrogen chloride. Although the material is electrically neutral in its aggregate form, individual dipoles attract each other on a molecular scale if the positive and negative ends of the molecules are properly oriented. Within the material, these dipole forces produce net intermolecular bonding.

London forces are attractive forces that exist between nonpolar molecules; that is, the atoms in the molecule do not form dipoles in the sense that the previous paragraph implies. However, since electrons in orbit around the molecule move quickly, temporary dipoles emerge when more electrons are on one side of the molecule than the other, as described by Finally, hydrogen bonding occurs in molecules containing hydrogen atoms that are covalently bound to another atom (e.g., oxygen in H_2O). Because the electrons required to complete the shell of a hydrogen atom are aligned on one side of its nucleus, the opposing side has a net positive charge, which attracts electrons from adjacent molecules.

Crystalline Structures

Atoms and molecules serve as building blocks for the more macroscopic structure of matter discussed here and in the section that follows. When materials solidify from a molten state, they tend to close ranks and pack densely, forming a highly organised structure in many circumstances and a less orderly one in others. There are two essentially diverse material structures:

- (1) Crystalline and (2) Noncrystalline.

This section looks at crystalline structures, followed by noncrystalline formations. Many materials solidify from a molten or liquid state to create crystals. It is found in almost all metals, as well as numerous ceramics and polymers. A crystalline structure is one in which the atoms are arranged in three dimensions in regular and repeating patterns. Within a single crystal, the design may be duplicated millions of times. The structure may be seen as a unit cell, which is the fundamental geometric arrangement of atoms that is repeated. Consider the unit cell for the body-centered cubic (BCC) crystal structure depicted in which is a typical structure in metals.

Figure below depicts the simplest form of the BCC unit cell (a). Although this model accurately portrays the atom positions inside the cell, it does not reflect the tight packing of atoms that happens in the actual crystal, depicts the unit cell's recurring nature inside the crystal, as shown in Figure 3.1.




Figure 3.1 Simplest Form of the Bcc Unit Cell

Types of Crystal Structures

Metals have three main lattice structures: (1) body-centered cubic (BCC), (2) facecentered cubic (FCC), and (3) hexagonal close-packed (HCP), the crystal structures of the most common metals. It should be noted that various metals change structure at different temperatures. Iron, for example, is BCC at room temperature; over 912C (1674F), it converts to FCC and then back to BCC (2550F). When a metal (or other material) changes structure in this way, it is said to be allotropic.

Imperfections in Crystals

So far, microstructures have been treated as though they were perfect the unit cell repeating in the material in all directions over and again. A flawless crystal is occasionally desired for aesthetic or mechanical reasons. For example, a flawless diamond (one with no faults) is more valuable than one with blemishes. Large single crystals of silicon have suitable processing qualities for generating the tiny details of the circuit layout in the fabrication of integrated circuit chips. However, there are many reasons why the lattice structure of a crystal may not be ideal.

Imperfections often occur spontaneously as a result of the solidifying material's incapacity to continue the reproduction of the unit cell forever without interruption. Metal grain boundaries are one example. In certain circumstances, the defects are purposefully added during the production process, such as the inclusion of an alloying component to a metal to boost its strength.

Defects are the numerous flaws in crystalline substances. Imperfections or defects are aberrations from the regular pattern of the crystalline lattice structure. They are classified into three types: (1) point flaws, (2) line defects, and (3) surface defects.

Point defects are flaws in the crystal structure that include a single or a few atoms. Defects may take several forms, (a) vacancy, the most basic defect, which involves a missing atom within the lattice structure; (b) ion-pair vacancy, also known as a Schottky defect, which involves a missing pair of ions of opposite charge in a compound with an overall charge balance; (c) interstitialcy, a lattice distortion caused by the presence of an extra atom in the configuration; and (d) displaced ion, also known as

In the lattice structure, a line defect is a linked group of point defects that form a line. The dislocation is the most common line defect, and it may take two forms: (a) edge dislocation and (b) screw dislocation. an edge dislocation is the edge of an additional plane of atoms in the lattice shows a screw dislocation, which is a spiral inside the lattice structure wrapped around an imperfection line, similar to how a screw is wrapped around its axis. Both forms of dislocations may develop in the crystal structure during solidification (e.g., casting) or during a deformation

process done on the solid material (e.g., metal forming). Dislocations may help explain several features of mechanical behaviour in metals.

Surface imperfections are flaws that extend in two directions to create a boundary.

The most apparent example is the crystalline object's exterior surface, which dictates its form. The surface is a break in the lattice structure. Surface boundaries may also be found inside the material. The finest illustration of these internal surface disruptions is grain boundaries. Metallic grains will be examined shortly, but first consider how deformation happens in a crystal lattice and how the existence of dislocations aids the process.

Deformation in Metallic Crystals

When a crystal is exposed to steadily increasing mechanical stress, it deforms elastically at first. This is analogous to a tilting of the lattice structure without any changes in position among the atoms in the lattice, the lattice structure (and hence the crystal) returns to its original form when the force is released. When the stress exceeds the electrostatic forces that keep the atoms in their lattice locations, a permanent shape termed plastic deformation occurs. The atoms in the lattice have permanently shifted from their former positions, and a new equilibrium lattice has created,

The lattice deformation is one conceivable process for plastic deformation in a crystalline system, known as slip. The other is twinning, which will be described later. Slip is the relative movement of atoms on opposing sides of a lattice plane known as the slip plane. Because the slip plane must be aligned with the lattice structure (as shown in the drawing), there are certain favoured paths along which slide is more likely to occur. The number of slip directions is determined by the lattice type.

The three most frequent metal crystal forms are more intricate, particularly in three dimensions, than the square lattice s. HCP has the fewest slip directions, BCC has the most, and FCC is somewhat in the middle. At room temperature, HCP metals have little ductility and are difficult to deform. If the frequency of slip directions were the sole criteria, metals having BCC structures would seem to have the maximum ductility. Nature, on the other hand, is not that straightforward. These metals are frequently stronger than the others, complicating matters; and the BCC metals typically need larger loads to produce slide.

Indeed, several of the BCC metals have low ductility. Low carbon steel is a noteworthy exception; despite its strength, it is commonly employed with considerable commercial success in sheetmetal-forming processes due to its ductility. The FCC metals are the most ductile of the three crystal structures, with a good number of slip directions and (typically) low to moderate strength. All three from these metal formations become more ductile at higher temperatures, which is typically used to shape them. Dislocations are critical in promoting slide in metals. When a shear force is applied to a lattice structure with an edge dislocation, the material deforms.

Much more easily than in an ideal framework. This is explained by the fact that in the presence of stress, the dislocation is set in motion inside the crystal lattice, as seen in the sequence. Why is moving a dislocation across the lattice simpler than deforming the lattice itself? To attain a new equilibrium position, the atoms at the edge dislocation need a lower displacement inside the deformed lattice structure. As a result, a lower energy level is required to realign the atoms into the new locations than if the lattice did not include the dislocation. As a result, a lower stress

level is needed to cause the deformation. Because the new site has a comparable deformed lattice, atoms continue to migrate at the dislocation at the lower stress level.

The slip phenomenon and the impact of dislocations have been explored in detail here. Slip happens several times over throughout the metal when exposed to a deforming stress on a wider scale, leading it to display the known macroscopic behaviour. Dislocations are a mixed bag of good and bad news. Because of the dislocations, the metal is more ductile and quickly submits to plastic deformation (forming) during manufacture. However, from the standpoint of product design, the metal is not nearly as robust as it would be in the absence of dislocations.

Twinning is just a second kind of plastic deformation of metal crystals. Twinning is a plastic deformation process in which atoms on one side of a plane (called the twinning plane) are moved to generate a mirror copy of the opposite side of the plane. depicts the mechanism, which is critical in HCP metals. Because they are not easily slipped. Aside from structure, the rate of deformation is an important element in twinning. The slide mechanism takes longer than twinning, which may happen virtually instantly. Metals that would normally slide twin in conditions when the deformation rate is quite high. Low- carbon steel is an example of rate sensitivity; when exposed to high strain rates, it twins, but at moderate rates, it slips.

Grains and Grain Boundaries in Metals

Each grain has its own unique lattice orientation, yet the grains are positioned arbitrarily within the block as a whole. This kind of structure is known as polycrystalline. It is simple to see how such a structure is the natural condition of the material. When the block cools from its molten state and starts to solidify, individual crystal nucleation occurs at random places and orientations throughout the liquid. As these crystals develop, they eventually collide, generating a surface imperfection grain boundary at their contact. The grain border is formed by a transition zone, which may be just a few atoms thick and is not aligned with either grain. The number of nucleation sites in the molten material and the bulk cooling rate, among other parameters, define the size of the grains in the metal block. The comparatively cool walls of the mould typically provide nucleation sites in a casting process, motivating a somewhat favored grain orientation at these walls.

Cooling rate is inversely linked to grain size:

Slower cooling produces larger grain size, while faster cooling produces smaller grain size. Metal grain size is essential because it impacts mechanical characteristics. Smaller grain size is often preferred in design since it signifies greater strength and hardness. It is also desired in some industrial activities (for example, metal forming) since it provides more ductility during deformation and a smoother end product surface. The existence of grain boundaries in the metal also influences mechanical characteristics. They indicate flaws in the crystalline structure that prevent dislocations from moving freely. This helps to explain why smaller grain size—and so more grains and grain boundaries increases metal strength. Grain boundaries contribute to a metal's distinctive attribute of becoming stronger as it is bent by interfering with dislocation movement. The characteristic is known as strain hardening.

Noncrystalline (Amorphous) Structures

Many essential materials, such as liquids and gases, are noncrystalline. Noncrystalline formations exist in water and air. When a metal is melted, it loses its crystalline structure. Mercury is a liquid metal at ambient temperature, having a melting point of 38 degrees Celsius

(37F). In their solid state, important types of engineering materials have a noncrystalline structure; the word amorphous is often used to characterise these materials. This group includes glass, various polymers, and rubber. Many essential polymers are crystalline and noncrystalline mixes. Even metals may be amorphous rather than crystalline if the cooling rate during the liquid-to-solid change is quick enough to prevent the atoms from organising themselves into their preferred regular patterns. This may happen if molten metal is poured between cool, tightly spaced, revolving rollers, for example.

Noncrystalline materials are distinguished from crystalline materials by two closely linked properties: (1) the lack of long-range order in the molecules, and (2) variations in melting and thermal expansion characteristics.

The crystal structure's densely packed and repeating pattern is illustrated on the left, while the noncrystalline materials less dense whereas random arrangement of atoms is shown on the right.

When a metal melts, it demonstrates the difference. When compared to the material's solid crystalline condition, the more tightly packed atoms in the molten metal indicate an increase in volume (loss in density). When most materials are melted, they exhibit this effect. A major example is ice; liquid water is denser than solid ice. The absence of long-range order is a general property of liquids and solid amorphous materials, as seen on the right in our illustration. The melting phenomena will now be investigated in more depth, and the second significant distinction between crystalline and noncrystalline structures will be determined.

As previously stated, as a metal melts from the solid to the liquid state, its volume increases. This volumetric shift happens relatively suddenly for a pure metal at a constant temperature i.e., the melting temperature T_m . The alteration reflects a break in the slopes on each side of the plot. The metal's thermal expansion the change in volume as a function of temperature, which is generally different in the solid and liquid states is characterized by the gradual slopes. The addition of a particular amount of heat, known as the heat of fusion, is associated with the abrupt volume increase when the metal transitions from solid to liquid at the melting point, causing the atoms to lose the dense, regular arrangement of the crystalline structure. The process is reversible; it may go in either way. When molten metal is cooled to its melting temperature, the same sudden change in volume happens except that it is a reduction, and the metal emits the same amount of heat.

As the glass cools, it progressively solidifies, passing through a transition phase known as a supercooled liquid before becoming hard. It does not exhibit the abrupt volumetric shift that is typical of crystalline materials; rather, it passes through its melting temperature T_m without changing its thermal expansion slope. As the temperature drops in this supercooled liquid area, the substance becomes extremely viscous. As it cools more, a point is reached at which the supercooled liquid solidifies. This is referred to as the glass-transition temperature T_g . The thermal expansion slope has changed at this point. (The thermal contraction slope may be more accurate; nonetheless, the slope is the same for expansion and contraction.) The rate of heat flow of the solid substance is slower than that of the supercooled liquid.

The reaction of their different atomic structures to temperature changes explains the variation in behaviour between crystalline and noncrystalline materials. When a pure metal solidifies from its molten state, its atoms form a regular and repeating structure. This crystal structure is significantly more compact than the random and loosely packed liquid that gave rise to it. As a result, the solidification process causes the sudden volumetric contraction shown in Figure 2.15

for the crystalline material. Amorphous materials, on the other hand, do not attain this repetitive and tightly packed structure at low temperatures. Because the atomic structure is the same as in the liquid state, there is no dramatic volumetric shift when these materials transition from liquid to solid.

Engineering Materials

Metals almost all metals exhibit crystalline formations in their solid state. These crystal formations' unit cells are virtually invariably BCC, FCC, or HCP. Metal atoms are kept together by metallic bonding, which allows their valence electrons to roam about with relative freedom (in comparison to other forms of atomic and molecule bonding). Metals become strong and hard as a result of these structures and bonding.

Many metals, particularly the FCC metals, are extremely ductile (capable of being deformed, which is important in manufacturing). Other common metal attributes linked to structure and bonding include: strong electrical and thermal conductivity, opaqueness (resistance to light rays), and reflection (capacity to reflect light rays). Ceramics Ionic or covalent bonding, or both, define ceramic molecules.

Metallic atoms give or share their outermost electrons with nonmetallic atoms, and there is a strong attraction force inside the molecules. High hardness and stiffness (even at high temperatures), brittleness (no ductility), electrical insulation (nonconducting) characteristics, refractoriness (being thermally resistant), and chemical inertness are some of the typical features that come from these bonding methods.

Ceramics may be crystalline or noncrystalline in structure. Most ceramics have a crystal structure, while silica (SiO_2) glasses are amorphous. In certain situations, both structures may coexist in the same carbon fibre. Silica, for example, exists naturally as crystalline quartz. When this material is melted and cooled, it solidifies to create fused silica, a monocrystalline mineral.

Polymers

A polymer molecule is made up of numerous repeating mers that combine to create extremely massive molecules that are bound together by covalent bonds. Polymer elements are typically carbon+ one or more additional elements like hydrogen, nitrogen, oxygen, and chlorine.

Secondary bonding (van der Waals) maintains the molecules in the aggregate material together (intermolecular bonding). Polymers may have a glassy structure or a glassy-crystalline structure. There are distinctions between the three polymer kinds. The molecules in thermoplastic polymers are made up of long chains of mers in a linear shape. These materials can be heated and cooled without affecting their linear structure significantly. When thermosetting polymers cool from a heated plastic state, the molecules change into a hard, three-dimensional structure. When thermosetting polymers are warmed, they chemically deteriorate rather than soften. Elastomers are composed of big molecules having coiled shapes. When exposed to stress cycles, the uncoiling and recoiling of the molecules causes the aggregate material to display its typical elastic behaviour.

Polymers have the following characteristic features due to their molecular structure and bonding: low density, high electrical resistivity (some polymers are employed as insulators), and poor thermal conductivity. Polymer strength and stiffness vary greatly. Some are robust and rigid (but not to the strength and stiffness of metals or ceramics), others are exceedingly elastic.

Non-Ferrous Metals and Alloys

Nonferrous metals and alloys contain no substantial amounts of iron. Copper, aluminium, tin, lead, and zinc are the most frequent nonferrous metals utilised in engineering applications. Nickel, magnesium, and antimony are also used to alloy the nonferrous metals mentioned above.

Non-Ferrous Metals: Properties and Applications

Copper. Copper is a corrosion-resistant metal with an appealing reddish brown hue. It is an excellent heat and electrical conductor. It may also be formed into wires, sheets, and plates. As a result, it is widely employed in the electrical sector for the fabrication of armature coils, field coils, current carrying wires, household items, and so on. However, its greatest use stems from the fact that it alloys with zinc, tin, and nickel to produce brass, bronze, and cupro-nickels, all of which are extensively utilised in the engineering sector. As a result, copper is often employed in ornamental products.

In India, there is a scarcity of copper. Every year, we import at least 50-60% of our requirements.

Aluminium. Aluminium metal is difficult to get from its primary source, bauxite. However, bauxite is abundant in India, and we have a booming aluminium sector. Aluminium is also incredibly resistant to corrosion (because an adherent oxide layer protects it from further oxidation). It is yet another excellent heat and electrical conductor (although not as good as Cu). It is ductile and malleable, and it is far less expensive than copper. As a result, it has mostly supplanted copper lines in the transmission of power. It is also used to make home items like as pressure cookers. However, since it can be turned into thin foils, it is now widely employed in the beverage container and packaging industries. Its density is around one-third that of steel, hence it is also utilised for aeroplane and helicopter structures, as well as in transportation vehicles.

In India, 1, 2, 5, 10, and 20 paisa coins were formerly constructed of an aluminum-magnesium alloy. Aluminium and magnesium make a range of alloys that are tougher and stronger than aluminium. **Tin.** It has a lovely silvery white colour. It is very resistant to acid corrosion. Prior to the introduction of plastic tin coated thin plates of thin gauge, thin gauge steel sheets were utilised for the fabrication of Tin cans for storing ghee, mustard, and other oils. Tin is now mostly utilised for alloying purposes. When tin and lead are heated together, they form a succession of soft solders. Tin has a rather low melting point.

Lead. Lead is a heavy metal that appears dull grey. It offers excellent corrosion resistance and malleability. It was widely used for roof protection throughout Europe. It was also used in plumbing. It can tolerate sulphuric acid, which was formerly held in lead-lined jars. It has self-lubricating characteristics. As a result, it was utilised in lead pencils. A tiny amount of lead is sometimes added to titanium and tin bronze to give free cutting qualities.

Zinc. Zinc has a metallic blue grey look. It is very resistant to corrosion. In reality, steel sheets are often coated with a thin layer of zinc. These zinc-coated sheets are referred to as galvanised iron (G.I. sheets). For many years, the zinc coating protects steel sheets from corrosion.

Zinc has a low melting point and a high fluidity, making it appropriate for the die-casting process. Because zinc is substantially cheaper than copper or tin, brass, an alloy of copper and zinc, is much cheaper than copper or tin-bronze. In addition, zinc is employed in torch light batteries.

Alloys of Copper

Brass is a copper and zinc alloy. Commercially, there are two sorts of brasses:

1. Brass Alpha. It has up to 36% zinc and the rest is copper.
2. Alpha and beta brass. It includes 36% to 46% Zn, with the remaining being copper.
3. Brasses are classified into two phases: Alpha and Beta. Alpha-Beta brass is made up of both alpha and beta stages.
4. Brass's tensile strength and ductility improve with increasing Zn content up to 30% zinc. When the zinc concentration exceeds 30%, the tensile strength improves to 45% Zn, but

Brass ductility has significantly decreased. α -phase is significantly harder and stronger than β -phase, however it is less ductile. β -phase has high cold-formability and is utilised for wrought-to-shape items. The mechanical characteristics of α -brasses alter depending on how much cold work is done on them. α -brasses are suitable for hot working.

α -brasses are classified into two types: (i) red brasses having up to 20% Zn, and (ii) yellow brasses containing more than 20% Zn.

Red brasses are more costly and are often utilised in applications where their colour, higher corrosion resistance, or workability are obvious benefits. They are weldable and have excellent casting and machining qualities. "Gilding-brass," or gilding metal with 5% Zn, is a well-known red-brass. It is used in ornamental work. Yellow brasses are the most ductile and are utilised for the most demanding cold forging processes. By using a deep drawing method, the cartridges are manufactured from a 70% Cu, 30% Zn brass, which has become known as cartridge brass.

Other well-known brass compositions include Admiralty brass, which has 29% Zn, 1% Tin, and the remainder copper. Muntz's metal includes 40-45% Zn and the rest is copper. Naval brass is made up of 39% Zn, 1% Tin, and the rest is copper. Admiralty brass, navy brass, and muntz metal are all used in ship fittings, condenser tubes, preheaters, and heat exchangers, among other applications.

Bronzes

Although commercial bronzes may include additional components than tin, bronze is an alloy of copper and tin. In actuality, bronzes are alloys of copper with aluminium, silicon, and beryllium that may or may not include tin.

Tin bronzes have a lovely golden colour. Bronzes' tensile strength and ductility improve with increasing tin concentration, much as brasses. More than 10% tin, on the other hand, is not utilised in bronze because it results in the development of a brittle intermetallic complex, Cu_3Sn . Tin addition to copper up to 10% enhances strength, hardness, and durability significantly more than zinc addition to copper.

Tin bronzes of the following types are often used:

Phosphor-Bronze. The addition of 0.5% phosphor to tin bronze produces phosphorous bronze. Phosphorous enhances the fluidity of molten metal, allowing for delicate castings.

Leaded-Bronze. The addition of lead to tin bronze produces leaded bronze. Lead is a cause of weakness, but it also improves machinability and possesses self-lubricating characteristics. In most cases, the lead percentage does not surpass 2%.

Gun-metal. It is made up of 2% zinc, 10% tin, and 88% copper. It is a well-known piece. This bronze is used for bearing bushes, glands, pumps, and valves, among other things.

Bell metal. It is a tin bronze with a very high tin content (20-25%). When hammered with a hammer, it produces a pleasing tinkling sound.

Bronzes with no tin. The following bronzes contain no tin and are well-known commercially: Bronze made of aluminium. The composition is 14% aluminium and the remainder copper. It has high strength and corrosion resistance. The colour is golden yellow. Frequently used in costume jewellery.

Silicon bronze Composition: 1-4% silicon, with the remainder mostly copper. It is particularly resistant to corrosion. Cold workable and strain-hardenable. Used to make boiler and marine fittings.

Manganese bronze the composition is 40% zinc, 55-60% copper, and 3-5% manganese. It is simply a brass with manganese added to it. It is used to make ship propellers.

Beryllium bronze (IVT mechanical qualities and may be cold worked and toughened over time. It is primarily used for bellows, bourdon gauge tubes, and other similar applications.

CUPRO-NICKELS

Cupro-nickels are copper and nickel alloys. When melted together in any proportion, copper and nickel are entirely miscible and dissolve each other. When the alloy hardens, the solubility persists, resulting in a solid solution. Cupro-nickel is silvery white in colour and has excellent corrosion resistance. They are widely utilised in maritime fittings. They are also very strong, hard, and ductile. The rupee five coin is comprised of 75% copper and 25% nickel. Constantan is the name given to another alloy that contains 45% Ni and 55% copper. It's used to make thermocouples, low-temperature heaters, and resistors.

Alloys of Aluminium

Aluminium is a soft metal with a low tensile strength. The majority of aluminium alloys are created by alloying it with varying quantities of magnesium; these alloys are tougher and stronger. These alloys, known as L-M series alloys, may be extruded and are widely employed in structural applications.

Duralumin is a well-known aluminium alloy that contains 4% copper, 0.5% magnesium, 0.5% manganese, a trace of iron, and the remainder aluminium. It has a high specific gravity and a high strength. However, its corrosion resistance is much lower than that of pure aluminium. Duralumin is sometimes coated or clad on both sides with a thin aluminium covering. ALCLAD is a material used in the aerospace industry.

When 5-15% silicon is alloyed with aluminium, we produce temperature-resistant alloys. Castings consisting of Al-Si alloys are widely employed in the mass production of two-wheeler pistons.

Nickel Alloys I German silver. It is a cupro nickel with zinc added to it. A common composition is 60 percent copper, 30 percent nickel, and 10 percent zinc. The use of zinc reduces the cost. It is silvery in colour with a faint pale tint. It is very ductile and malleable, as well as corrosion resistant. It is used to make electrical contacts, costume jewellery, and high-quality taps, among

other things. It was also used for domestic items and currency before to the emergence of stainless steel. etc

Monel steel. It is made up of 68% nickel, 30% copper, 1% iron, and the rest manganese.

Nichrome. Nickel-chromium alloy used as a heat-resistant electrical wire in

Inconel and incoloy are alloys used in furnaces and electrical heating equipment such as geysers and electric irons. Nickel, chromium, and iron alloys are the most common. In the electrical sector.

Mechanical Properties of Materials

A material's mechanical qualities dictate how something behaves when exposed to mechanical stresses. Elastic modulus, ductility, hardness, and different strength measurements are among these qualities. Mechanical qualities are significant in design because they affect a product's function and performance.

Rely on its ability to withstand deformation under service conditions. The common goal in design is for the product / system to resist these pressures with little change in shape. This capacity is determined by factors such as elastic modulus and yield strength. In production, the goal is exactly the reverse. To change the form of the material, stresses that surpass its yield strength must be applied. Mechanical operations such as shaping and machining are successful because they generate forces that are greater than the material's resistance to deformation. As a result, the following quandary exists: Mechanical features that are desired to the designer, like as great strength, frequently make the product more complex to build. It is advantageous for the manufacturing engineer to understand the design perspective and for the designer to understand the manufacturing viewpoint.

Stress–strain relationships

Materials may be exposed to three forms of static stresses: tensile, compressive, and shear. Tensile tensions stretch the material, compressive stresses crush it, and shear stresses cause neighbouring sections of the material to move against one another. The stress-strain curve is the fundamental connection that defines the mechanical characteristics of all three kinds of materials.

Tensile Properties

The tensile test is the most often used method for investigating the stress-strain relationship, especially in metals. A force is given to the material during the test, aiming to elongate it and shrink its diameter. ASTM (American Society for Testing and Materials) standards govern the preparation of test specimens as well as the testing process itself. The usual specimen and general set of the tensile test, respectively.

The first test specimen has a length L_0 and an area A_0 . The length is measured as the distance between the gauge markings, and the area is measured as the specimen's (typically round) cross section. Shows how a metal object stretches, necks, and eventually breaks under testing. As testing progresses, the stress and the change in length of the specimen are recorded to give the data needed to determine.

As stress grows, there comes a point in the linear relationship where the material starts to give. The change in slope there at conclusion of the linear section in the picture identifies the

material's yield point Y_0 . Because the beginning of yielding is frequently difficult to notice in a test data plot (it does not usually appear as a dramatic change in slope), Y is commonly defined as the stress at which a strain offset of 0.2% off the straight line has occurred. More precisely, it is the point at which the material's stress-strain curve crosses a line parallel to the straight section of the curve but offset by 0.2%. Because the yield point is a material strength characteristic, it is also known as the yield strength (other names include yield stress and elastic limit).

The yield point denotes the transition to the plastic zone and the beginning of the material's plastic deformation. Hooke's law no longer governs the link between stress and strain. When the load is raised beyond the yield point, the specimen elongates at a considerably quicker pace than previously, causing the slope of the curve to shift significantly, as seen in Figure 3.3. Elongation is followed by a uniform decrease in cross-sectional area, which is compatible with the maintenance of constant volume. Finally, consider the applied load.

F reaches a maximum value, and the engineering stress estimated at this point is referred to as the material's tensile strength or ultimate tensile strength. It is indicated by the symbol TS , where $TS = F_{max}/A_0$. In design calculations, TS and Y are critical strength characteristics. (They're also utilised in production calculations.) Some typical yield and tensile strength values for various metals. Ceramic tensile testing is problematic, hence an alternate test is employed to determine the strength of these fragile materials. Because of viscoelasticity, polymers have different strength qualities than metals.

The load starts to drop to the right of the tensile on the stress-strain curve, and the test specimen often begins a process of localised stretching known as necking. Instead of straining evenly throughout its height, straining concentrates on a tiny area of the specimen. The region of that segment dramatically narrows (necks) until failure occurs. The fracture stress is the stress estimated right before failure.

The amount of strain that a material can withstand before failing is another mechanical attribute that is important in many industrial processes. The capacity of a material to elastic deformation stretch without fracture is a standard metric of this characteristic.

Hardness

A material's hardness is defined including its resistance to persistent indentation. A high hardness indicates that the metal is resistant to scratches and wear. Scratch is utilised in numerous technical applications, including the majority of industrial tooling. Because they are rapid and convenient, hardness tests are often used to evaluate material qualities. However, due to the variances in hardness among various materials, a number of testing procedures are applicable. Brinell and Rockwell hardness tests are the most well-known.

Brinell Hardness Test

The Brinell hardness test is commonly used for determining the hardness of metals and nonmetals ranging from low to medium. It was called after the Swedish engineer who invented it in the year 1900. A hardened steel (or cemented carbide) ball of 10-mm diameter is forced into the surface of a specimen with a weight of 500, 1500, or 3000 kg during the test. The load is then divided by the area of indentation to get the Brinell Rockwell Hardness (BHN). In the form of an equation

$$HB = \frac{2F}{\pi D_b \left(D_b - \sqrt{D_b^2 - D_i^2} \right)}$$

Where HB is the Brinell Hardness Number (BHN), F is the indentation force in kg, D_b is the diameter of the ball in mm, and D_i is the diameter of the indentation upon that surface in mm.

F depicts these dimensions. The resultant BHN have units of kg/mm², although the units are frequently ignored when the number is expressed. Because the steel ball suffers elastic deformation, which reduces the integrity of the reading, the coated carbide ball is utilised for tougher materials (over 500 BHN). Furthermore, for tougher materials, greater loads (1500 and 3000 kg) are frequently employed. Because various loads produce different findings, it is considered best practise to specify the load utilised in the test when reporting HB levels.

Effect Of Temperature On Properties

Temperature has a substantial impact on practically all material characteristics. It is critical for the designer to understand the material qualities of the product while it is in service. It is also critical to understand how temperature influences mechanical qualities in production. At high temperatures, materials lose strength while increasing ductility. As a result, most metals can be produced more readily at high temperatures than at low temperatures.

Temperature Hardness Hot hardness is a characteristic that is often used to quantify toughness at high temperatures. Hot hardness is simply a material's capacity to keep hardness at high temperatures; it is often reported as either a list of hardness values at various temperatures or as a plot showing hardness vs temperature.

Ceramics have exceptional characteristics at high temperatures. These materials are often used in high-temperature applications such as turbine components, cutting tools, and refractory materials.

To resist the friction heat of high-speed re-entry into the atmosphere, the exterior skin of a shuttle spacecraft is coated with ceramic tiles. In tooling materials used in various industrial activities, hot hardness is also desired. Most metalworking processes create significant quantities of heat energy, and the tools must be able to endure the high temps involved.

Temperature of Recrystallization The flow curve in the plastic zone describes how most metals behave at room temperature. The metal gains strength as it is stressed due to strain hardening (the strain-hardening exponent $n > 0$). However, strain hardening does not occur if the metal is heated to a sufficiently high temperature and subsequently deformed.

Instead, strain-free new grains develop, and the metal acts like a fully flexible material, with a strain-hardening exponent of $n \approx 0$. Recrystallization is the process by which new strain-free grains form, and the temperature at which it happens is about one-half the melting point ($0.5T_m$), measured on an absolute scale (R or K). This is referred to as the recrystallization temperature. Recrystallization is a time-consuming operation. The recrystallization temperature of a certain metal is often described as the temperature at which full production of new grains takes about 1 hour.

Recrystallization is a temperature-dependent metal property that may be used in manufacturing. The amount of stress that the metal can withstand is dramatically enhanced by heating it to the melting point before deformation, and the forces and power needed to carry out the operation are significantly decreased. Hot working refers to the process of forming metals at temperatures higher than the recrystallization temperature.

CHAPTER 4

Fluid Properties

Dr. Nagaraj Patil, Assistant Professor,

Department of Mechanical Engineering, Faculty of Engineering and Technology, JAIN
(Deemed-to-be University), Ramanagara District, Karnataka - 562112, India

Email Id: -nagaraj.patil@jainuniversity.ac.in

Fluids and solids react quite differently. A fluid moves; it takes on the form of the container in which it is contained. A solid has a geometric shape that is independent of its surroundings; it does not flow. Fluids encompass both liquids and gases; this section focuses on the former. Many industrial procedures are carried out on materials that have been heated from a solid to a liquid state. Metals are cast when molten; glass is created while heated and very fluid; and polymers are virtually usually fashioned as thick fluids.

Viscosity although flowing is a distinguishing feature of fluids, the inclination to flow varies depending on the fluid. The attribute that governs fluid flow is viscosity. The resistance to flow that is typical of a fluid is roughly described as viscosity. It is a measure of the internal friction that occurs when velocity gradients exist in a fluid the higher the internal friction and the greater the resistance to flow, the more viscous the fluid.

Fluidity is the reciprocal of viscosity the ease with which a fluid flows. Viscosity is defined more accurately in relation to the configuration which consists of two parallel plates separated by a distance d . One plate is fixed, the other is moving at v , and the gap between the plates is filled with fluid. When these parameters are oriented relative to an axis system, d is on the y -axis and v is on the x -axis.

The top plate's motion is resisted by force F , which is caused by the fluid's shear viscous action. By dividing F but by plate area, this force may be converted to a shear stress. A fluids and solids react quite differently. A fluid moves; it takes on the form of the container in which it is contained. A solid has a geometric shape that is independent of its surroundings; it does not flow. Fluids encompass both liquids and gases; this section focuses on the former.

Many industrial procedures are carried out on components that have been heated from a solid to a liquid state. Metals are cast when molten; glass is created while heated and very fluid; and polymers are virtually usually fashioned as thick fluids. Viscosity although flow is still a distinguishing feature of fluids, the inclination to flow varies depending on the fluid. The attribute that governs fluid flow is viscosity. The resistance to flow that is typical of a fluid is roughly described as viscosity. It is a measure of the internal friction that occurs when velocity gradients exist in a fluid the higher the internal surface roughness and that the greater the resistance to flow, the more viscous the fluid. Fluidity is the reciprocal of viscosity the ease with which a fluid flows.

Viscosity is defined more accurately in relation to the configuration which consists of two parallel plates isolated by a distance d . One plate is fixed, the other is moving at v , and the gap between the plates is filled with fluid. When these parameters are oriented relative to an axial

system, d is on the y-axis and v is on the x-axis. The top plate's motion is resisted by force F , which is caused by the fluid's shear viscous action. By dividing F but by plate area, this force may be converted to a shear stress.

Viscoelastic Behavior of Polymers

Viscoelasticity is another attribute that distinguishes polymers. Viscoelasticity is a material attribute that governs the strain it endures when exposed to stress and temperature combinations over time. It is a mix of viscosity and elasticity, as the name implies the substance in (b), on the other hand, exhibits viscoelastic behaviour. Under the given load, the strain amount progressively rises over time. When tension is removed, the material does not instantaneously revert to its previous form; rather, the strain progressively decays. If the stress had been applied and then quickly released, the material would have instantaneously reverted to its original form. However, time has entered the picture and has influenced the material's behaviour.

Using the notion of elasticity as a starting point, a basic model of viscoelasticity may be created. Hooke's law, $s = 1/E \cdot \epsilon$, expresses elasticity succinctly by relating stress to strain through a proportionality constant.

The time function $f(t)$ may be thought of as a time-dependent modulus of elasticity. It is also known as a viscoelastic modulus and may be written as $E(t)$. The shape of this time function may be complicated, with strain being a role at times. Without delving into the mathematical formulations, the impact of temporal dependence may be investigated. depicts the stress-strain behaviour of a thermoplastic polymer at varied strain rates and reveals one consistent effect. The material displays substantial viscous flow at low strain rates. At high strain rates, it becomes significantly more brittle.

Temperature influences viscoelasticity

As the temperature rises, viscous behaviour becomes more dominant in comparison to elastic behaviour. The substance transforms into a fluid. This temperature dependency for a thermoplastic polymer is.

The material exhibits elastic properties at low temperatures. The polymer becomes viscoelastic when T rises over the glass transition temperature T_g . It gets soft and rubbery as the temperature rises. It shows viscous qualities at higher temperatures. Depending on the plastic, the temperatures at which different forms of action are seen vary. Furthermore, the forms of the elasticity versus temperature curve vary according of the ratio of crystalline and amorphous structure in thermoplastic.

Thermosetting polymers and elastomers react differently than illustrated in the picture; after curing, these polymers do not soften in the same way as thermoplastic materials do at high temperatures. Instead, at high temperatures, they deteriorate (char).

Shape memory is a manifestation of viscoelastic behavior in polymer melts. As the viscous polymer melt is converted from one shape to another during processing, it "remembers" its prior shape and strives to return to that geometry. Die swell, for example, is a typical issue in polymer extrusion. This occurs when the profile of the extruded material expands in size, reflecting its inclination to revert to its larger cross section in the extruder barrel shortly before being pushed through the smaller die aperture. The features of viscosity and deformability are discussed in further depth in the section on plastic shape.

Basic Metal Forming Processes and Uses

Metal forming operations, also known as mechanical working processes, are basic shaping processes that involve the application of mechanical forces to a mass of metal or alloy. The form and size of a metal object change as a result of the action of such forces. Mechanical working procedures may accomplish the desired form and size of a machine component while saving both material and time.

Metal forming is achievable in the event of adequately malleable and ductile metals or alloys. Mechanical working necessitates "plastic deformation" of the material during processing. Frequently, work piece material is not malleable or ductile enough at room temperature, but it may become so when heated. As a result, we have both hot and cold metal forming operations.

Many metal forming methods are appropriate for processing huge amounts (i.e., bulk) of material, and their applicability is determined not only by the product's shape and size control, but also by the surface finish achieved. There are several metal forming procedures, and some provide superior geometry (i.e., shape and size) and surface polish than others. However, they are not equivalent to what machining operations can produce. In addition, hot working metal forming procedures provide superior shape, size, and surface polish than hot working processes. Hot working causes surface oxidation and decarburization, scale development, and a loss of size control owing to work piece contraction as it cools to room temperature.

Advantages of Mechanical Working Processes

Mechanical working procedures provide many benefits over traditional production processes, in addition to increased productivity. These are listed below:

Mechanical working enhances material mechanical qualities such as ultimate tensile strength, wear resistance, hardness, and yield point while decreasing ductility. "Strain hardening" is the term for this phenomena.

It causes grain flow lines to form in the portion being mechanically manipulated. When the component is in use, the grainflow enhances the strength against fracture. This is best shown by using a crankshaft as an example. If the crankshaft is machined from a big bar of steel,

In a cross-section, the particle flow lines are severed at bends, however in a crankshaft formed by forging (a mechanical working technique), the grain flow lines follow the whole contour of the crankshaft, strengthening it.

Metal grains are bent and lengthened in the direction of metal flow during mechanical action. As a result, they provide extra layer to fracture across them. As a result, mechanically treated components have greater mechanical strength in one direction, namely across the grain flow.

Difference between Hot and Cold Working

Cold working (or cold forming, as it is often known) is the failure mode of metals and alloys at temperatures lower than the recrystallisation temperature of that metal or alloy. When this occurs, the strain hardening that occurs as a consequence of mechanical functioning does not occur.

Relieved. In reality, when the metal or alloy hardens, more and more power is needed to generate additional plastic deformation. If the impact of strain hardening is not eliminated after a while, the forces used to generate plastic deformation may eventually cause cracking and material

failure. Hot working is defined as plastic deformation of metals and alloys at such temperatures that recovery and recrystallisation occur concurrently with strain hardening. This temperature is higher than the recrystallisation temperature.

Hot working done correctly will result in a fine-grained recrystallised structure of the metal or alloy. A note on recrystallisation temperature might be appropriate here. Recrystallisation temperature is a temperature range rather than a specific temperature. Its worth is determined by a number of things. Among the critical elements are:

I Metal or alloy nature: It is typically lower for metals and greater for alloys. Recrystallisation temperature is typically one-third of melting temperature for pure metals and half of melting temperature for alloys.

Quantity of cold work previously done: As the amount of strain-hardening done on the work piece grows, the recrystallisation temperature decreases.

Strain-rate: The lower the recrystallisation temperature, the faster the strain hardening. The recrystallisation temperature range for mild steel is 550-650°C. Room temperature may be used to calculate the recrystallisation temperature of low melting point metals such as lead, zinc, and tin. Strain hardening effects may be eliminated by annealing just above recrystallisation temperature.

Advantages and Disadvantages of Cold and Hot Working Processes

Cold working is done mostly at room temperature, no surface oxidation or tarnishing occurs. There is no scale formation, hence there is no material loss. In heated working conditions,

1. The inverse is true. Furthermore, heat working of steel causes partial decarburisation of the work piece surface because carbon is oxidised as CO₂.
2. Cold working improves dimensional precision and produces a brilliant surface. Cold rolled steel bars are hence known as brilliant bars, whilst hot rolled steel bars are known as black bars (they appear greyish black due to oxidation of surface).
3. Heavy work hardening occurs during cold working, which enhances the strength and hardness of bars but also implies that large pressures are needed for deformation, increasing energy consumption. This is not the case while working in a heated environment.
4. Cold working techniques cannot produce complicated forms because of their poor ductility at room temperature.
5. Cold working causes severe internal strains in the metal. If these pressures are not released, the produced component may fail early in service. There are no residual internal tensions in hot working, and the mechanically worked structure is superior to that generated by cold working.
6. At high temperatures, the strength of materials decreases. At high temperatures, its malleability and ductility improve. As a result, for hot working operations, minimal capacity equipment is necessary. In the event of hot working operations, the pressures on the working tools likewise decrease.
7. During hot working, blow holes and interior porosities are sometimes eliminated by welding action at high temperatures.

- 8 Non-metallic inclusions in the work piece are shattered. Metallic and non-metallic segregations are also minimized or eliminated in hot working because high temperatures encourage diffusion, making the composition more homogeneous over the whole cross-section.

Classification of Metal Forming Processes According To Type of Stress Employed

Primary metal working procedures are those in which bulk material, such as ingots, blooms, and billets, is broken down into appropriate forms and sizes by processes such as forging, rolling, extrusion, and so on. These procedures may be classified based on the kind of stress utilized in the material, namely:

1. Primarily compression type (Examples: forging, rolling, extrusion etc.).
2. Primarily tension type (Example: drawing).
3. Compression and tension together (Examples: deep drawing, embossing etc.).

Thermal Expansion

The density of a substance varies with temperature. The basic rule is that as temperature rises, density decreases. In other words, when temperature rises, so does the volume per unit weight. The impact of temperature on density is known as thermal expansion. It is often represented in mm/mm/C (in/in/F) as the coefficient of thermal expansion, which quantifies the displacement per degree of temperature. Because it is simpler to measure and apply, it is a length ratio rather than a volume ratio. This is consistent with the ordinary design scenario in which dimensions changes are more important than volumetric changes. The length change associated with a particular changes in temperature is given by

The coefficient of thermal expansion values indicate a linear connection with temperature. This is merely a rough estimate. Temperature has an effect not only on length but also on the thermal expansion coefficient. It rises with temperature for certain materials and lowers for others. These variations are typically not severe enough to cause worry, and numbers like those in the table are very valuable in design calculations for the temperature ranges that will be encountered in service. When a metal undergoes a phase transition, such as from solid to liquid or from one crystal structure to another, changes in the coefficient become more pronounced.

Thermal expansion is used in manufacturing processes in shrink fit and expansion fit assemblies, in which a component is heated to expand its size or chilled to reduce its size to allow insertion into another part. When the component cools to room temperature, it forms a securely fitting assembly. Because of the thermal stresses that arise in the material during these operations, thermal expansion might be a concern in heat treatment.

Melting Characteristics

The melting point of a pure element T_m denotes the temperature at which the substance transitions from solid to liquid. The freezing point is the temperature at which the reverse transition from liquid to solid happens. Melting and freezing temperatures are the same for crystalline materials such as metals. At this temperature, a particular quantity of heat energy, known as the heat of fusion, is needed to complete the change from solid to liquid. As previously explained, melting a metal particle at a certain temperature assumes equilibrium circumstances. In nature, exceptions exist; for example, when a molten metal is cooled, it may persist in the liquid state below its freezing point if crystal nucleation does not occur promptly. The liquid is considered to be supercooled when this occurs.

Other variables in the cooling process include changes in how melting happens in various materials. Most metal alloys, unlike pure metals, do not have a single melting point. Instead, melting starts at a certain temperature known as the solidus and continues as the temperature rises, eventually converting entirely to the liquid state at a temperature known as the liquidus. The alloy is a combination of solid and molten metals between the two temperatures, with the proportions of each being inversely proportional to their respective distances from the liquidus and solidus. Although most alloys act in this manner, eutectic alloys that melt (and freeze) at a single temperature are exceptions. These concerns are addressed in the phase discussion. Noncrystalline materials exhibit still another distinction in melting (glasses). These materials gradually shift from solid to liquid states. As the temperature rises, the solid substance softens progressively, eventually becoming liquid at the melting point. As the material softens, its consistency becomes more plastic (more like a fluid) as it approaches the melting point. The variations in melting qualities between pure metals, alloys, and glass. The graphs depict density variations as a function of temperature for three hypothetical materials: pure metal, alloy, and glass.

Melting is obviously important in production. Metal casting melting metal and pouring it into a mould cavity. Metals with lower melting temperatures are often simpler to cast, but if the melting temperature is too low, the metal loses its technical usefulness. Polymer melting properties are crucial in plastic moulding and other polymers shaping operations. Melting points must be known when sintering powdered metals and ceramics.

Sintering does not melt the materials, but the temperatures employed in the process must approach the melting point in order for the powders to join properly.

Thermal Properties

The impact of temperature on the volumetric characteristics of materials occupied most of the preceding section. Temperature, melting, and heat of fusion are all thermal characteristics because temperature impacts the thermal energy level of the atoms, causing material changes. The present section looks at a few more thermal characteristics, which are concerned with the storage and transfer of heat inside a material. Specific heat and heat capacity are common qualities of importance, with data provided for chosen materials.

A material's volumetric heat storage capability is often of interest. Simply multiply density by specific heat c . Thus, volumetric specific heat is defined as the amount of heat energy necessary to increase the temperature of a particular volume of material by one degree, expressed as $J/mm^3 C$ ($Btu/in^3 F$). Conduction is the most basic heat-transfer technique. It entails the transmission of thermal energy inside a substance from molecule to molecule by only thermal movements; no mass is transferred. A substance's thermal conductivity is hence its capacity to move heat through itself through this physical process. It is measured by the thermal conductivity coefficient k , which has usual values of $J/s mm C$ ($Btu/in hr F$). Metals have a high coefficient of heat conductivity, whereas ceramics and polymers have a low value. In heat transfer studies, the ratio of thermal conductivity and volumetric specific heat is commonly encountered. It is known as thermal diffusivity K and is calculated as $K = k / \rho c$.

Thermal Properties in Manufacturing

Heat production is ubiquitous in so many operations, thermal characteristics are significant in manufacturing. In certain activities, heat is the energy that drives the process; in others, heat is

produced as a byproduct of the process. For numerous reasons, specific heat is of importance. Specific heat defines the amount of heat energy required to increase the temperature to a desirable level in operations that involve heating of the material (example, casting, heat treatment, and hot metal forming),

Many procedures performed at room temperature transfer the mechanical energy needed to complete the action to heat, raising the temperature of something like the workpart. This is frequent in metal machining and cold forming. The temperature increase is proportional to the specific heat of the metal. Coolants are often employed in machining to lower these temperatures, and the heat capacity of the fluid is crucial. Because of its tremendous heat-carrying capability, water is nearly typically used as the foundation for these fluids. Thermal conductivity is used to disperse heat in industrial operations, which may be advantageous or detrimental. Much of the power necessary to run mechanical operations such as metal forming and machining is transferred to heat. In these operations, the capacity of the work material and equipment to transmit heat away from its source is particularly desired.

High thermal conductivity of the work metal, on the other hand, is undesirable in fusion welding methods such as arc welding. The heat input in these processes must be focused at the joint area in order for the metal to melt. Copper, for example, is notoriously difficult to weld due to high thermal conductivity, which enables heat to be transferred from the energy source into the work too quickly, preventing heat accumulation for melting at the joint.

Mass Diffusion

There is mass transfer in addition to heat transmission in a material. The movement of atoms or molecules inside a material or across a border between two materials in contact is referred to as mass diffusion. It may seem more intuitive that such a phenomena happens in liquids and gases, but it also occurs in solids. It occurs in pure metals, alloys, and materials with a shared interface. Atoms in a substance (solid, liquid, or gas) are constantly moving about due to thermal agitation. It is a free-roaming movement in liquids and gases with considerable thermal agitation. Atomic mobility in solids (particularly metals) is aided by vacancies and other flaws in the crystal structure.

The set of drawings in diffusion in the situation of two metals coming into close contact for the first time. Both metals have their own atomic structure at first, but over time, there is an interchange of atoms not just across the border, but also inside the distinct parts. Given enough time, the assembly of two components will eventually achieve a homogeneous composition all the way through.

Temperature has a vital role in diffusion. Thermal agitation is stronger at higher temperatures, and atoms may move about more easily. The concentration gradient dc/dx , which represents the concentration of the two kinds of atoms in a direction of interest determined by x , is another component the concentration gradient is displayed to correspond to the instantaneous distribution of atoms in the assembly. Fick's first law is a well-known connection for describing mass diffusion:

$$dm = -D \left(\frac{dc}{dt} \right) A dt$$

where dm indicates a tiny quantity of material moved, D represents the metal's diffusion coefficient, which rises quickly with temperature, dc/dx concentration gradient, A border area, and dt denotes a short time increment. The mass diffusion rate is given by an alternate.

$$\frac{dm}{dt} = -D \left(\frac{dc}{dx} \right) A$$

Although these equations are difficult to apply in computations due to the difficulty in determining D , they are useful in understanding diffusion and the factors that influence D .

Mass diffusion is employed in a variety of procedures. Diffusion is the basis for a variety of surface-hardening procedures, including hardening and nitriding. Diffusion welding is a welding procedure that is used to unite two components by forcing them together and enabling diffusion to occur over the boundary to establish a permanent bond. In electronics production, diffusion is utilised to change the surface characteristics of a semiconductor chip in extremely limited places to generate circuit details.

Resistivity and Conductivity

The mobility of charge carrier's infinitesimally tiny particles with an electrical charge is required for the passage of electrical current. These charged particles are electrons in solids. Charge carriers in a liquid solution are positive and negative ions. The presence of an electric voltage drives the movement of charge carriers, which is resisted by the intrinsic property of the material, such as atomic structure and bonding between the atoms and molecules. Ohm's law defines this as a familiar connection.

The fundamental attribute that characterises a material's capacity to resist current flow is its resistivity. Shows resistivity values for several materials. Resistivity is not a constant; rather, it fluctuates with temperature, as do many other qualities. It rises with temperature for metals.

It is often easier to think of a substance as transmitting electrical current rather than preventing its passage. A material's conductivity is just the reciprocal of its resistivity

Classes of Materials by Electrical Properties

Because of their metallic bonding, metals are the finest conductors of electricity. They have the least amount of resistance (Most ceramics and polymers are poor conductors because their electrons are strongly linked by ionic and covalent bonds. Because of their high resistivity's, several of these materials are utilised as insulators.

Because the word dielectric signifies nonconductor of direct current, an insulator is sometimes referred to as a dielectric. It is a substance that may be sandwiched between two electrodes without allowing electricity to flow between them. However, if the voltage is high enough, the current will travel through the material abruptly, such as in the form of an arc. The electrical potential needed to break down an insulator per unit width is the dielectric strength of the substance. Volts/m (volts/in) are the appropriate units. There are superconductors and semiconductors in addition to conductive layers (or dielectrics). A superconductor is a substance with no resistance. It is a low-temperature phenomena that has been seen in certain materials.

Getting close to absolute zero. Because of the enormous influence that temperature has on resistivity, one may assume the presence of this phenomena. The existence of these superconducting materials is of tremendous scientific significance. If materials with this ability at more typical temperatures could be created, it would have substantial practical consequences

in power transfer, electronic switching rates, and magnetosphere applications. Semiconductors have previously shown their utility: Their applications span from computers to home products and engine controls in automobiles. A semiconductor, as the name implies, is a substance whose resistance sits between insulators and conductors. Shows the usual range. Silicon is the most extensively used semiconductor material nowadays, owing to its abundance in nature, cheap cost, and simplicity of processing. What distinguishes semiconductors is their ability to drastically modify conductivities in surface chemistries in extremely limited locations in order to construct integrated circuits

Electrical qualities are crucial in many industrial processes.

Electrical energy is used in some of the unconventional procedures to remove material. Electric discharge machining removes material from metals by using the heat created by electrical energy in the form of sparks. The majority of essential welding procedures rely on electrical energy to dissolve the joint metal. Finally, the ability to modify the electrical characteristics of semiconductor materials serves as the foundation for microelectronics production.

Electrochemical Processes

Electrochemistry is the study of the link between electricity and chemical processes, as well as the conversion of electrical and chemical energy.

The molecules of an acid, base, or salt are split into positively and negatively charged ions in a water solution. These ions are the charge carriers in the solution, allowing electric current to flow in the same way as electrons do in metallic conduction. The ionized solution is referred to as an electrolyte, and electrolytic conduction needs current to enter and exit the solution via electrodes. The positive electrode is known as the anode, while the negative electrode is known as the cathode. The whole setup is known as an electrolytic cell. At each electrode, a chemical reaction occurs, such as material deposition or dissolution, or gas decomposition from the solution.

These chemical changes in the solution are referred to as electrolysis. Consider one example of electrolysis: water breakdown, to speed up the process, the electrolyte is dilute sulfuric acid (H_2SO_4), while the electrodes are platinum and carbon (both chemically inert). The electrolyte dissociates into H^+ and SO_4^{2-} . The highly reactive cathode attracts the hydrogen ions. When they get there, they pick up one electron and unite to form molecules of hydrogen gas: The result H_2SO_4 is separated into ions of H^+ and SO_4^{2-} , and the process is repeated.

Electrolysis is utilised in a variety of industrial operations in addition to the creation of hydrogen and oxygen gases, as indicated by the example. Electroplating, which applies a thin coating of one material (e.g., chromium) to the surface of a second metal (e.g., steel) for ornamental or other reasons; and electrochemical machining which removes material off the surface of a metal item. Both of these processes use electrolysis to add or remove material from the surface of a metal object. In electroplating, the workpiece serves as the cathode in an electrolytic circuit, attracting positive ions from the coated metal to the negatively charged portion. The work part is the anode in electrochemical machining, while the cathode is a tool with the required form. In this configuration, electrolysis removes metal from the component surface in locations dictated by the geometry of the tool as it progressively feeds into the work.

Michael Faraday, a British physicist, initially articulated the two physical rules that regulate the quantity of material deposited or withdrawn from a metallic surface:

1. The mass of a material released in an electrolytic cell is proportional to the amount of electricity that passes through the cell.
2. The masses of the substances freed are proportionate to their chemical counterparts when the same amount of power is transmitted through various electrolytic cells.

Faraday's laws are used in the following sections on electrodeposition and electrochemical machining.

Forging

Metal and alloys are distorted to the desired forms in forging by repeatedly striking them with a hammer. It is normally done hot, although cold forging is however done on occasion. The raw material is often a piece with a round or rectangle cross-section that is somewhat bigger in volume than the completed component. Depending on the final application of the component, it forged item may be utilised as is, or it may need to be machined to the necessary size and tolerances. As a result, the initial amount of material taken must account for loss due to scaling as well as the machining allowance.

Classification of Forging

Forging may be done by hand or using power hammers. Hydraulic presses are sometimes used for forging.

Hand Forging: Under the action of compressive pressures caused by hammer blows, the material expands laterally, that is, in a direction perpendicular to the direction of the hammer blows. Brittle materials, such as cast iron, cannot be forged because they will break under hammer blows. An ordinary blacksmith uses an open-hearth with coke (or sometimes steam coal) as fuel to heat the metal, and once it is red-hot, the blacksmith's assistant (called striker or hammer man) delivers blows on the metal piece while a blacksmith holds it on an anvil and manipulates it with a pair of tongs. This method of forging is known as "hand forging," and it is only appropriate for tiny forgings and low-volume manufacturing.

Drawing down: This is the opposite of the upsetting process. This procedure increases length while decreasing cross-sectional area. **Cutting:** This procedure involves eliminating excess metal from the task before completing it with hot chisels.

Bending: A blacksmith is often used to bend bars, flats, and other similar materials. To make a bend, first heat the section at the bend point then leap (upset) it on the outside surface. This adds material so that the cross-section at the bend does not shrink owing to elongation after bending.

Punching and drifting: Punching is an operation that involves forcing a punch through the work item to create a rough hole. The project is heated, held on the anvil, and a punch of appropriate size is hammered to roughly half the depth of the job. The work is then flipped upside down, and punch is pushed in from the opposite side, this time completely.

Punching is frequently followed by drifting, or driving a drift through and through the punched hole. This results in a superior hole in terms of size and quality. **Setting down and finishing:** Setting down is the process of removing the rounding from a corner to make it square. It is accomplished with the use of a set hammer. After the project has been roughly brought to the required form and size, finishing is the operation in which the uneven surface of the forging is smoothed out with the use of a flatter or set hammer and round stems are finished to size with the use of swages. **Forge welding:** It is sometimes essential to unite two pieces of metal. Steel forge

welding is extremely frequent and consists of heating the two ends to white heat (1050°C - 1150°C). The two ends of steel are then brought together after the surfaces under joining have been given a modest convex form. Scale is removed from the surfaces. Then they're hammered together using borax as a flux. The hammering begins in the Centre of the convex surface and continues to the ends. As a consequence, the slag is pressed out of the joint.

Hammering is carried out until a sound joint is created. There are many sorts of joints that may be formed, including butt joints, scarf joints, and splice joints.(b) Forging using Power Hammers: Hand forging is only used for minor forgings. When a massive forging is needed, relatively weak blows from a striker's hand hammer or sledge hammer will not create considerable plastic flow of the material. As a result, more powerful hammers are required. Forging has been done using several types of power hammers driven by electricity, steam, and compressed air (i.e., pneumatic). These hammers are now described in detail (Figure 4.1).




Figure 4.1 represents the parts of forging process

Electrochemistry is a branch of science that studies the link between electricity and chemical changes, as well as the conversion of electricity to chemical changes. An electric motor turns a pair of pulleys, one loose and one fast, in this configuration. The unsecured pulley spins aimlessly on its shaft. The fast pulley is secured to its shaft by a key, so that as the fast pulley turns, so does the shaft. Because the shaft has an eccentric sheave on it, when the electric motor turns the fast pulley, the eccentric sheave rotates with it, imparting vertical reciprocator motion to the connecting rod. The connecting rod's upper end is attached to one end of a laminated bearing spring. The other end of this spring is attached to a ram that may move up and down in a vertical guide built into the machine frame at the front of the machine. A tup (and, if necessary, a die) is attached to this ram. An anvil on a base is also lying vertically under the ram and tup. When the hammer operator depresses the treadle with his foot, the motor is linked to the fast pulley, and when the connecting rod goes up, the front end of the spring moves down, causing the spring buckle in the centre of the spring to be pivoted. The ram travels up when the

connecting rod slides down. Thus, the spinning of the motor causes the ram and tup to move up and down, which is utilised to hammer the work piece held on the anvil.

There is usually a mechanism for adjusting the pivot's location. The vertical movement of the ram and tup increases as the pivot is relocated towards the connecting rod, as does the intensity of the hammering action. When the foot is taken from the treadle, the motor is activated. To the loose pulley, and an automated brake engages, instantaneously halting the pounding operation. Spring hammers were manufactured in a variety of sizes, with tups weighing from 30 to 250 kg and capable of producing up to 300 blows per minute. The molecules of an acid, bases, or salt are split into positively and negatively charged ions in a water solution. These ions are the charge carriers in the solution, allowing electric current to flow in the same way as electrons do in metallic conduction. The ionised solution is referred to as an electrolyte, and electrolytic conduction needs current to enter and exit the solution via electrodes. The positive electrode is known as the anode, while the negative electrode is known as the cathode. The whole setup is known as an electrolytic cell. At each electrode, a chemical reaction occurs, such as material deposition or dissolution, or gas decomposition from the solution. These chemical changes in the solution are referred to as electrolysis.

Consider one example of electrolysis: water breakdown, as demonstrated in to speed up the process, the electrolyte is dilute sulfuric acid (H_2SO_4), while the electrodes are platinum and carbon (both chemically inert). The electrolyte dissociates into H and SO_4^{14} . The negative charge cathode attracts the hydrogen ions. An electric motor turns a crank, which in turn pushes a connecting rod (D) back and forth, converting the crank's rotating motion into a reciprocating motion. This reciprocating action is transmitted to a piston within cylinder 'C'. The cylinder and piston assembly are outfitted with appropriate air input ports, allowing the complete unit to function as a reciprocating air compressor, compressed air may be transferred to another piston piston assembly B. The hammerman or person operating this hammer operates this air valve A using the handle depicted in the picture H. When air valve A is entirely closed, the supply of air to cylinder B is cut off, and the piston of cylinder B rests at the bottom position. Its tup, which is connected to the piston through a piston rod (P), is resting on the anvil at this point. When the air valve 'A' is opened, the compressed air from cylinder C is sent to cylinder B, a double acting cylinder. The compressed air enters below the piston, raising it, and then enters above the piston, pushing it downward with enormous power. This upward and downward motion of the piston in cylinder B is transmitted to the tup, which travels in a vertical guide V supplied in the power hammer frame, and the tup impacts the work piece held on the anvil.

The intensity of the blows may be regulated by adjusting the opening of air valve a, ranging from very light to extremely heavy. The weight of moving elements, including the tup in cylinder B, determines the hammer's capacity. Pneumatic hammers come in capacities ranging from a quarter to five tonnes.

Steam hammers: These hammers vary from the pneumatic hammer in that they need a separate boiler to generate steam. Thus, cylinder 'C' of the pneumatic hammer is not necessary in a steam hammer. Cylinder B's piston is driven by steam taken from the boiler and is controlled by a simple slide valve system. Because the steam pressure is higher than the cabin pressure in pneumatic hammers, the striking force in steam hammering is greater than in pneumatic hammers of comparable size.

CHAPTER 5

Die Forging with Power Hammers

Karthik N

Assistant Professor, Mechanical Engineering

Faculty of Engineering and Technology, JAIN (Deemed-to-be University), Ramanagara District,
Karnataka - 562112, India

Email Id: - n.karthik@jainuniversity.ac.in

Power hammer tools are similar in form to hand forging tools, but they are bigger and more durable. To the greatest extent feasible, every effort is put in to complete the needed form in a single heat. Typically, the bottom surface of the tup and the top of the anvil are flat, as in hand forging, however dies are often used to enhance output and save costs. The top die is firmly connected to the tup, while the lower die is securely fitted to the anvil. One half of the completed job's imprint is sunk in the top die, while the other half is buried in the bottom die. The right amount of raw material is heated in the furnace and given a rough form initially. Following that, it is put on the bottom die and strokes are delivered with the tup and top die. The substance spreads to cover all the empty space in the die imprints. This kind of forging is known as die forging. There are three common die forging procedures. There are three types of forging: open die forging, impression die forging, and sealed die forging.

Open Die Forging

The metal is never entirely contained or restricted on all sides in this sort of forging. The majority of open die forgings are made on flat, V, or swaging dies. Swaging dies are often spherical, but they may also be of different forms, such as a double V, as shown in Figure 5.1.




Figure 5.1 open die forging process of material

The benefits of open die striking are as follows: (i) it is simple to learn and operate; (ii) it requires less machinery and equipment since no die-sinking is required; and (iii) it can handle a wide variety of work piece sizes. The biggest problem is the limited volume of manufacturing and the difficulties in controlling close size.

Impression Die Forging

Half of the final forging's imprint is sunk or created in the top die, while the other half is sunk or made in the bottom die. Die-sinking is the process of carving the impression in a die and is done using a particular equipment called a die sinking machine. The work item is crushed between the dies in impression die forging. The required shape is created between the closing dies as the

metals spreads to fill the voids sunk in the dies. "Flash" refers to material that is driven out of dies. As the tup impacts the anvil, the flash offers some padding for the dies.

The flash that surrounds the work piece is removed and disposed as junk. The imprint in the dies must be entirely filled by the material for a proper forging. This may need multiple hammer strokes; a single blow may not be enough. Hand forging may be used to give the work piece a rough form before die forging to help in the manufacture of excellent forgings.

Closed Die Forging

Closed die forging is similar to imprint die forging, but in real closed die forging, the initial quantity of material taken is precisely regulated such that no flash is created. Otherwise, the procedure is similar to impression die forging. It is a technology that lends itself to large manufacturing.

Drop Forging or Drop Stamping Hammers

A modified form of a power hammer is often used for closed die or impression die forging. It is known as a drop stamping or drop forging hammer, and it produces superior results. The tup is not an option in this scenario.

It is a distinct component of the piston and piston rod assembly. The tup, to which the top part of the die is attached, is raised using flexible ropes or a flexible canvas belting. It is then placed on the anvil, to which the bottom half of the die is connected.

Its downward movement is a gravity-controlled free fall regulated by vertical guides built into the hammer's frame. The flexible ropes guarantee that the tup may recover after hitting the anvil. Typically, one fall of the tup is enough to finish the forging. Before being drop stamped, the metal component is given a rough form.

Some Important Considerations Which Lead To Sound Beginnings

Hot forgings necessitate the heating of work parts to the previously stated forging temperature. If the material to be forged has a thick cross-section, we should give adequate "soaking" time for heat to flow from the surface to the core of the material. A general rule of thumb is to allow 30 minutes of soaking time for every 12-15 mm of cross-sectional thickness. It is critical that the whole cross-section be heated to a consistent temperature.

A good forging procedure requires for a 40% decrease in cross-section. It is not acceptable to choose a cross-section for work piece material that is near to the completed size and then forge it lightly or superficially to the desired form.

If this is done, the mechanical qualities of the forging will be severely compromised. It is important to note that forging is not only a procedure for changing the form of raw material to the appropriate shape, but it may also result in increased mechanical strength of the forged component.

Another important aspect of excellent forging practice is to employ as little "heats" as possible to complete the forging. It is also critical to complete forging/hammering operations when the work has reached a suitably low temperature; leaving forging at a high temperature causes grain development and reduces the mechanical strength of the forged product. Stop forging mild steel after the work piece has cooled to about 450-500°C. Hammering a cold work piece will result in wasted effort and may possibly cause fissures in the material.

Engineering Presses

High capacity hydraulic presses are sometimes used for forging, and the metal is formed by the press's squeezing action rather than the hammer's pounding action. Closed dies are utilised, with imprints buried in both dies; the top die is attached to the ram, while the lower die is attached to the press platen. Vertical presses are the most common kind. Forgings of exceptional structural quality are produced using presses.

Forging On a Machine

Special forging machines have been created for specialised applications such as mass production of bolts and nuts from bar stock. These devices operate in tandem with a furnace that heats one end of the bar for an extended period of time. The machine is then fed the warmed end of the bar. The hexagonal head of the bolt is forged by "upsetting" using dies and a heading tool. These devices are really horizontal mechanical presses controlled by a foot pedal. The die is made up of two parts as well as a heading tool.

Defects Are Created

Common forging errors may be traced back to raw material problems, inappropriate material heating, defective die design, and improper forging behaviour.

The following are the most prevalent forging defects:

1. Laps and Cracks at Borders or Surfaces a lap is created by a layer of material following over another surface. These flaws are the result of poor forging and defective die design.
2. Incomplete forging—either owing to insufficient or inappropriate material flow.
3. Mismatched forging as a result of misaligned die halves.

Scale pits are caused by the pressing of scales into the steel surface during the hammering motion.

5. Burned or overheated metal—due to insufficient heating.
6. Internal forging fractures generated by forceful hammer strokes and insufficiently heated and saturated material.
7. Fibre flow lines are disrupted as a result of metal's highly quick plastic flow.

Forgings Heat Treatment

In service, the forged components may be exposed to extreme strains. After finishing forging operations, forgings may indeed be given an appropriate heat treatment to increase service life, characteristics, reduce internal tensions, and occasionally machinability. Normalizing is the most often used heat treatment. Cold forging is limited to low and medium carbon steels and items that need little deformation to achieve final shape because to its limited formability at room temperature. Typically, the stock is in the form of a wire or thin rods, from which a head is created in a cold upsetting operation at one end. A manual press is often utilized. Nails, tiny diameter rivet pins, brass bolts, and other similar items are common.

Dimensions Surfaces, And Their Measurement

Aside from the mechanical and physical qualities of materials, the dimensions and surfaces of a produced object are also important elements in determining its performance. The dimensions of a

component are the vertical or angular sizes stated on the part design. Dimensions matter because they affect how well a product's components fit together during assembling. It is practically difficult and very expensive to fabricate a specific component to the precise dimensions specified on the design. Instead, a limited variance from the dimension is permitted, and this authorized variation is referred to as a tolerance.

A component's surfaces are also significant. They have an impact on the product's performance, assembly fit, and visual appeal to a prospective buyer. A surface is an item's outer border with its surroundings, which might be another object, a fluid, or space, or any combination of these. The surface encloses the bulk mechanical and physical qualities of the item.

Dimensions, tolerances, and surfaces are three properties defined by the product designer and determined more by manufacturing procedures used to manufacture the components and products. It also discusses how these characteristics are measured and gauged utilizing measuring and gauging equipment.

Dimensions and Tolerances

A dimension is defined by as a numerical number represented in proper units of measure and displayed on a drawing and in other documents together with lines, symbols, and comments to identify the size or geometric character, or both, of a part or part feature.

Component drawing dimensions indicate the nominal or fundamental sizes of the part and its characteristics. These are the values that perhaps the designer would prefer the component size to be if it could be manufactured to an exact size with no faults or changes throughout the fabrication process. There are, however, variances in the manufacturing process that emerge as variances in component size. Tolerances are used to determine the maximum allowable deviation. To per the ANSI standard a tolerance is "the entire amount by which a certain dimension is allowed to fluctuate. Tolerance is defined as the difference between the maximum and lowest limits.

Tolerances may be stated in a variety of methods, as shown in Figure 5.1. The bidirectional tolerance, in which deviation from the nominal dimension is accepted in both positive and negative directions, is perhaps the most prevalent. For example, the nominal size is 14 2.500 linear units (e.g., mm, in), with a permissible variation of 0.005 units in either direction. Parts that exceed these parameters are unacceptable. A bilateral tolerance, such as $2.500 +0.010, -0.005$ dimensional units, might be imbalanced. A unilateral tolerance allows deviation from the stated dimension in just one direction, either positive or negative.

Conventional Measuring Instruments and Gages

Measurement is the process of comparing an unknown amount to a known standard using an established and accurate system of units. The world has developed two systems of units: (1) the US customary system (U.S.C.S.) and (2) the International System of Units (or SI, for Systeme Européenne d'Unites), also known as the metric system. Throughout the book, both techniques are utilised in tandem. Except for the United States, which has steadfastly held to its U.S.C.S., the metric system is universally recognised across the industrialised world. The United States is gradually embracing SI.

Within specific bounds of accuracy and precision, measurement offers a numerical value of the quantity of interest. The amount to which the measured value corresponds with the real value of

the quantity of interest is referred to as accuracy. When a measuring technique is followed correctly, it is accurate.

Systematic errors, which are positive or negative variations from the correct value that are constant from one measurement to the next, are not present. The degree of repeatability in the measuring procedure is referred to as precision. Precision implies that random mistakes in the measuring technique are kept to a minimum. Random mistakes are often related with human involvement in the measuring procedure. Variations in setup, inaccurate scale readings, round-off approximations, and so on are all examples. Temperature fluctuations, progressive wear and/or misalignment of the device's operating parts, and other variables are all nonhuman factors to random error.

Gage is closely connected to measuring. Gaging (sometimes written gauging) simply assesses whether or not a component characteristic fulfills or fails to match the design criteria. It is frequently quicker than measuring, but it provides little data on the actual value of the feature of interest.

Precision Gage Blocks

Precision gauge blocks serve as the benchmarks by which other dimensional measuring equipment and gauges are measured. Gageblocks are typically square or rectangular in shape. The measuring surfaces are refined to a mirror sheen and are dimensionally exact and parallel to within few millionths of an inch. There are many precision gauge block grades available, with tighter tolerances for higher precision grades. The highest quality, known as the master laboratory standard, is manufactured with a tolerance of 0.00003 mm (0.000, 001 in). Gage blocks may be constructed of a variety of hard materials, depending on the degree of hardness sought and the price the customer is prepared to pay. These materials include tool steel, chrome-plated steel, chromium carbide, and silicon carbide.

Alternatively, tungsten carbide. Precision gauge blocks are available in a range of conventional sizes as well as in sets including an assortment of different-sized blocks. The sizes of a set are established deliberately such that they may be stacked to obtain practically any required dimension to within 0.0025 mm (0.0001 in).

Gage blocks should be used on a level reference surface, such as a surface plate, for the greatest results. A surface plate is a huge solid block with a flat plane on its top surface. Today, granite is used to make the majority of surface plates. Granite offers the benefits of being hard, nonrusting, nonmagnetic, long lasting, thermally stable, and simple to maintain.

Gage blocks and other high-precision measuring equipment must be used under standard temperature and other circumstances that may impact the measurement. The standard temperature has been set by international agreement at 20 degrees Celsius (68 degrees Fahrenheit). This is the standard at which metrology laboratories work. Corrections for heat expansion or contraction may be necessary if gauge blocks or other measuring equipment are employed in an industrial setting where the temperature varies from this norm. Furthermore, working gauge blocks used for inspection in the shop wear out and must be calibrated on a regular basis against more accurate laboratory gauge blocks.

Measuring Instruments for Linear Dimensions

Measuring devices are classified as graduated or no graduated. Graduated measuring instruments include a series of marks (called graduations) on a linear or angular scale with which the object's

feature of interest may be measured. No graduated measuring instruments lack such a scale and are used to compare dimensions or transfer dimensions for measurement by a graded device. The rule (made of steel and sometimes referred to as a steel rule) is the simplest basic graded measuring instrument, used to measure linear measurements. Rules come in a variety of lengths. Metric rule lengths range from 150 to 1000 mm, with graduations of 1 or 0.5 mm. The most common sizes in the United States are 6, 12, and 24 in, with graduations of 1/32, 1/64, or 1/100 in.

For numerous measuring uses, graded callipers are provided. The slide calliper is the most basic, consisting of a steel rule with two jaws, one fixed at the end of the rule and the other moveable. Depending on whether inner or outside jaw faces are employed, slide callipers may be used for either interior or exterior measurements. In usage, the jaws are pressed into contact with the to-be-measured component surfaces, and the position of the moveable jaw shows the dimension of relevance. Slide callipers provide for more precise and accurate measurements than basic rules. The vernier calliper, depicted in Figure 5.4, is a development of the slide calliper. The moveable jaw of this instrument comprises a vernier scale, named after P. Vernier (1580-1637), a French mathematician who designed it. The vernier has graduations at 0.01 mm in SI (and 0.001 inch in US customary scale), which is far more accurate than a slide calliper.

The micrometre is a popular and very precise measuring equipment, with the most typical configuration consisting of a spindle or a C-shaped anvil, and precise screw thread moves the spindle relative to the stationary anvil. Each turn of the spindle on a normal US micrometre produces 0.025 in of linear motion. A thimble with 25 markings around its circle, each equivalent to 0.001 in, is attached to the spindle. A vernier is normally attached to the micrometer sleeve. For numerous measuring uses, graded callipers are provided. The slide calliper is the most basic, consisting of a steel rule with two jaws, one fixed at the front of the rule and the other moveable. Depending on whether the inner or outside jaw faces are employed, slide callipers may be used for inside or exterior measurements. In usage, the jaws are pressed into contact with the to-be-measured component surfaces, and the position of the moveable jaw shows the measurement of interest. Slide callipers provide for more precise and accurate measurements than basic rules. The vernier calliper is an improvement on the slide calliper. The moveable jaw of this instrument comprises a vernier scale, named after P. Vernier (1580-1637), a French mathematician who designed it. The vernier has graduations of 0.01 mm in SI (and 0.001 inch in US customary scale), which is far more accurate than a slide calliper.

The micrometre is a frequently used and very precise measuring equipment that consists of a spindle and a C-shaped anvil. The spindle is manipulated relative to the fixed anvil through an exact screw thread. Each turn of the spindle on a normal US micrometre produces 0.025 in of linear motion. A thimble with 25 markings around its circle, each equivalent to 0.001 in, is attached to the spindle. A vernier is normally attached to the micrometre sleeve.

Comparative instruments are used to compare the dimensions of two items, such as a workpart and a comparison surface. They often cannot provide an absolute measurement of the quantity of interest; rather, they quantify the size and direction of the deviation between two items. Mechanical and electrical gauges are examples of instruments in this category.

Dial Indicators: Mechanical Gages Mechanical gauges are intended to mechanically exaggerate the deviation so that it may be seen. The dial indicator (Figure 5.6) is the most typical device in this category, converting and amplifying the linear movement of a contact pointer into spin of a

dial needle. The dial is calibrated to 0.01 mm increments (or 0.001 in). Dial indicators are used to assess straightness, flatness, parallelism, squareness, plumpness, and runout in a variety of applications.

Gages for Electronics Electronic gauges are a kind of measuring and gauging device that uses transducers to transform a linear movement into an electrical signal. The electrical signal is amplified and translated into an appropriate data format, such as a digital readout. Electronic gauge applications have expanded quickly in recent years, owing to advancements in microprocessor technology. Many traditional measuring and gauging equipment are increasingly being phased out. Electronic gauges have many advantages, including (1) high sensitivity, accuracy, precision, repeatability, and speed of response; (2) the capacity to detect extremely tiny dimensions—down to 0.025 mm (1 m-in.); (3) simplicity of operation; and (4) decreased cost.

Fixed Gages

There are two types of gauge: master gauge and limit gauge. A master gauge is made to be an exact reproduction of the nominal component dimension. It is often used to calibrate a measuring equipment or to set up a comparable measuring instrument, such as a dial indicator.

A limit gauge is a reverse duplicate of the component dimension that is used to verify the dimension for one or more tolerance limits. A limit gauge is often made consisting of two gauges in one piece, one for testing the lower limit of the tolerance on the component dimension and the other for measuring the higher limit. These gauges are often referred to as GO/NO-GO gauges because one gauge limit enables the component to be inserted while the other does not. The GO limit is used to assess the dimension at its maximum material condition; it is the lowest size for an interior feature like a hole and the maximum size for an exterior feature like an outer diameter. The NO-GO restriction is used to examine the dimension's minimum material condition.

Snap gauges and ring gauges are common limit gauges for checking outer component dimensions and plug gauges for checking inner dimensions. A snap gauge is made up of a C-shaped frame with gauging surfaces situated in the frame's jaws. It features two gauge buttons, one for the GO gauge and one for the NO-GO gauge. Outside measurements such as diameter, breadth, thickness, and comparable surfaces are checked using snap gauges.

Ring gauges are used to measure the diameter of cylindrical objects. A pair of gauges, one GO and the other NO-GO, are normally needed for a specific application. Each gauge is a ring with an aperture cut to one of the part's tolerance limits. The exterior of the ring is knurled for comfort. The existence of a groove around the exterior of the NO-GO ring distinguishes the two gauges.

The plug gauge is the most often used limit gauge for measuring hole diameter. A typical plug gauge consists of a lever to which two precisely ground cylindrical pieces (plugs) of hardened steel are connected. The cylindrical plugs function as the GO and NO-GO indicators. Taper gauges, which consist of a tapered plug for checking tapered holes, and thread gauges, which consist of a threaded plug for checking internal threads on components, are other gauges comparable to the plug gauge.

Fixed gauges are simple to use, and the time it takes to conduct an examination is nearly always shorter than that of a measuring instrument. Fixed gauges were a critical component in the evolution of interchangeable parts manufacturing

They made it possible to manufacture pieces with tight enough tolerances for assembly without filing nor fitting. Their downside is that they give little to no information about the actual component size; instead, they just show if the size is within tolerance. With the advent of high-speed electronic measuring equipment and the need for statistical process monitoring of component sizes, the usage of gauges is rapidly losing way to devices that offer real measures of the dimension of interest.

Angular Measurements

Angles may be measured using a protractor in one of many techniques. A basic protractor is made out of a pivoting blade relative to a semicircular head graded in angular units (e.g., degrees, radians). To use, rotate the blade to a point matching to the angle to be measured, and read the angle off the horizontal scale. A bevel protractor is made up of two straight blades that pivot relative to each other. The pivot assembly has a protractor scale for reading the angle created by the blades. The bevel protractor may be read to around 5 minutes when fitted with a vernier; without a vernier, the resolution is only about 1 degree.

A sine bar, as, may be used to make precise angular measurements. A flat steel straight edge (the side bar) and two precision rollers at a specified distance apart on the bar are one conceivable arrangement. To calculate height, the straight edge is aligned with the portion angle to be measured, and gauge blocks or other reliable linear measurements are taken. To produce the most exact results, the operation is performed on a surface plate. The angle A is calculated using the height H and length L of the sine bar among rolls.

Surfaces

When handling an item, such as a manufactured component, one touches the surface. The designer determines the component dimensions and connects the different surfaces. Lines in the engineering design define these nominal surfaces, which indicate the expected surface curvature of the component. The nominal surfaces look as perfectly straight lines, ideal circles, round holes, and other mathematically flawless edges and surfaces. The procedures employed to create a manufactured item define its actual surfaces. The multiplicity of manufacturing techniques available results in broad variances in surface properties, and engineers must understand surface technology.

Surfaces are significant economically and technologically for a variety of reasons, with various motivations for different applications: (1) Aesthetic reasons—smooth, free of scratches and imperfections surfaces are more likely to leave a good impression on the consumer. (2) Surfaces have an impact on safety. (3) Surface qualities influence friction and wear. (4) Surfaces have an impact on mechanical and physical qualities; for example, surface defects might constitute stress concentration locations. (5) The surfaces of components influence assembly; for example, the strength of adhesively bonded joints (Section 31.3) is improved when the surfaces are somewhat rough. (6) Smooth surfaces improve electrical contact.

Surface technology is concerned with (1) defining surface qualities, (2) surface texture, (3) surface health, and (4) the interaction between manufacturing processes and surface characteristics.

Characteristics of Surfaces

A microscopic examination of a part's surface shows inconsistencies and flaws. The characteristics of a typical layer are shown in a greatly enlarged cross section of a metal part's

surface. Despite the fact that this debate is centred on metallic surfaces. These remarks apply to ceramics and polymers, with adjustments due to structural variations between these materials. The majority of the part, known as the substrate, has a grain structure that is affected by previous metal processing; for example, the metal's substrate structure is affected by its chemical composition, the original casting process used on the metal, and any deformation operations and heat treatments performed on the casting. The outside of the component has a topography that is everything but straight and smooth. The surface shows roughness, waviness, and defects in this greatly magnified cross section. It also has a pattern and/or direction as a consequence of the mechanical process that created it, which is not visible here. Surface texture encompasses all of these geometric aspects.

Just under the surface lies a layer of metal with a different structure from the substrate. This is known as the changed layer, and it is a representation of the operations that have been performed on the surface both during and after its development. Manufacturing operations entail huge quantities of energy acting on the component against its surface. Work hardening (mechanical energy), heating (thermal energy), chemical, or even electrical energy may all result in a changed layer. The application of energy affects the metal in this layer, causing its microstructure to change. This changed layer comes within the purview of surface integrity, which is concerned with the definition, specification, and management of a material's surface layers during manufacture and subsequent performance in service. Surface integrity is often taken to encompass both surface texture and the changed layer underneath.

Furthermore, most metal surfaces are covered with an oxide coating following processing to allow the film to form. On its surface, aluminium forms a hard, dense, thin film of Al_2O_3 (which protects the substrate from corrosion), and iron forms oxides of various chemistries (rust, which provides virtually no protection at all). Moisture, filth, oil, adsorbed vapors, and other pollutants are also possible on the part's surface.

Surface Integrity

Surface texture does not fully characterise a surface. There may be metallurgical or other changes in the material close under the surface that affect its mechanical characteristics significantly. Surface integrity is the study and management of this subsurface layer and any changes that occur as a result of processing that may affect the performance of the completed component or product. When the structure of the subsurface layer changes from that of the substrate. Lists the probable abnormalities and damage to the subsurface layer that might occur during production. Surface modifications are induced by the use of many types of energy during processing, including mechanical, thermal, mechanical, and electrical energy.

Mechanical energy is the most frequent kind of energy utilised in manufacturing; it is exerted against the work material in activities such as metal forming (forging, extrusion), pressworking, and machining. Although mechanical energy's main role in these processes is to modify the geometry of the workpart, it may also generate residual strains, work hardening, and cracking.

Measurement of Surface Roughness

Surface roughness is measured using a variety of ways. They are classified into three types: subjective comparison with standard test surfaces, electrical devices with stylus, and optical approaches. Surfaces for Standard Testing Standard surface texture block sets with defined roughness levels are available. 1 To evaluate the roughness of a specific test specimen, the

surface is inspected and via the "fingernail test" compared to the standard. The user lightly scrapes the surfaces of the specimen and the standards in this test, determining which standard is closest to the specimen. Standard test surfaces are a quick and easy approach for a machine operator to determine surface roughness. They may also help design engineers decide how much surface roughness to provide on a component drawing. Instruments Stylus The fingernail test has the problem of being subjective. Several stylus-type tools for measuring surface roughness are commercially available similar to the fingernail test, but more scientific.

A cone-shaped diamond stylus with a point radius of around 0.005 mm (0.0002 in) and a tip angle of 90 is traversed over the test surface at a constant slow speed in these electrical devices. The stylus head rotates vertically as it moves horizontally to track surface irregularities. Vertical movement is translated into an electrical signal that depicts the surface topography. This may be shown as either a surface profile or an average roughness value. Profiling devices assess deviations against a distinct flat plane that serves as the nominal reference. The result is a surface contour map along the path crossed by the stylus. This device can detect roughness and waviness in the test surface. Roughness deviations are reduced to a single value R_a using averaging devices. To establish the nominal reference plane, they employ skids riding on the real surface. The skids operate as a mechanical filter to lessen the influence of surface waviness; in fact, these averaging devices execute the calculations electronically.

Evaluation of Surface Integrity

Surface roughness is easier to evaluate than surface integrity. Some approaches for inspecting for subsurface modifications are harmful to the material specimen. Surface integrity evaluation methodologies include the following: The texture of the surface. Surface roughness, lay designation, and other measurements give only superficial information about surface integrity. This sort of testing is reasonably easy to undertake and is always part of the surface integrity assessment.

Visual inspection. Surface imperfections like as cracks, crater, laps, and seams may be shown visually. Fluorescent and photographic methods are often used to supplement this sort of evaluation.

Microstructural analysis. This entails using typical metallographic methods to prepare cross sections and take photomicrographs of the microstructure of the surface layers in comparison to the substrate.

Microhardness distribution. Microhardness measuring methods such as Knoop and Vickers may detect hardness changes near the surface. To produce a hardness profile of the cross section, the component is sectioned and hardness is plotted versus distance below the surface. Profile of residual stress. To quantify residual stresses in a part's surface layers, X-ray diffraction methods may be used.

Effect of Manufacturing Processes

The manufacturing process determines the ability to attain a certain tolerance or surface. The general capabilities of different processes in terms of tolerance, surface roughness, and surface integrity are described in this section. Some manufacturing processes are more accurate by definition than others.

Most machining methods are very precise, with tolerances of 0.05 mm (0.002 in) or greater. Sand castings, on the other hand, are often imprecise, and tolerances 10 to 20 times those used

for machined components should be set. Includes several production techniques as well as the normal tolerances for each. Tolerances exist.

Conventional Manufacturing Process

According to traditional production methods, a paste made of lead and lead oxide powdered, additives, and the right proportions of acid and water to generate the desired density is applied to the carrying lead grid before being reduced to a porous lead mass. Metal is removed during the machining process. This procedure is subtractive since it removes a substance and reduces the material mass. The term "traditional machining process" can also refer to the ordinary machining procedure. It is the fundamental technique used in the metal removal process, which reduces the mass of the metal by removing a substance. The inhomogeneous structure and abrasive reinforcing are known to result in low-quality results when using conventional machining techniques. Laser machining thus offers several benefits over conventional machining techniques.

A conventional machining process entails performing the machining the old-fashioned manner, that is, without resorting to any advanced techniques. Thus, this machining technique is sometimes referred to as classical machining. In this kind of machining, sharp pointed cutting tools are used, for example the taper tool in the center lathe for tapering. Tool wear is exacerbated because the cutting tool's material is more durable than the workpieces and because it comes into direct touch with the workpiece. The cutting tool is used against a rotating or stationary workpiece to remove material. The inhomogeneous structure and abrasive reinforcing are known to result in low-quality results when using conventional machining techniques. Laser machining therefore provides a number of benefits over conventional machining techniques. Lathes, machine shops, vertical drilling machines, cutting machines, etc. are a few examples of typical machining equipment.

It is challenging to industries were established with contouring channels using conventional machining. To guarantee quick and smooth circulation, as well as the advantages of a quick cycle time and high plastic component quality, the channels are built employing milling and cutting in a design that is as near to the conform system as feasible. However, due to geometrical limitations, the channel count is reduced for the same mound volume since the drilled channels are straight and cannot curve the molding surface uniformly. As a result, some refrigeration effectiveness reduction is to be expected.

Applications of Conventional Manufacturing Process

Distinct conventional machining process types have varied operations, and thus have different uses. The most often employed include,

1. Operations on a lathe machine include knurling, face, screw cutting, and tapering.
2. surface abrasion during milling
3. use a drill machine to create perforations in a workpiece
4. On a shaper machine, there are exterior, internal, and surfacing keyways.

Metal Casting Process

Making items by pouring the molten into a blank, shaped space is known as metal casting. The metal then solidifies and cools into the shape that this shaped mound has provided for it. If an item needs to be machined out of a solid piece of metal, casting is sometimes a less expensive option. Modern metal casting has historical precedent. In the metal castings, metal is poured into

a mould cavity, cooled, and then shaped into the desired shape before being removed from the mound. The oldest and most important manufacturing plant in history is probably metal casting. Many of the metal items we use on a daily basis are made using it, including school bus pedals, railway wheels, automobile parts, and more. Additionally, metal recycling serves as a cost-effective supply of raw materials for metal casting foundries, thereby lowering the amount of discarded metal that may otherwise wind up in landfills.

History of Metal Casting

The earliest metal casting that has been discovered is a copper frog, which is thought to have been created in Mesopotamia about 3200 BCE when iron was a widely used material. Later, iron was found, perhaps about 2000 BCE. The first cast iron manufacturing, however, did not start until about 700 BCE in China. It's interesting to note that around 645 BCE, China also developed the sand molding technique for casting metals.

The technique of casting metals into useful items has evolved over thousands of years to become more precise and mechanized, yet at its foundation, the procedure has largely not changed. Automation advancements in foundry operations, such as the VIBRA-DRUM® Sand Casting Cleaner from General Kinematics, have simplified the processing of huge batches of castings while also enhancing the castings' quality. The equipment's large capacity mound and sand processing for foundry applications is groundbreaking.

Steps for Metal Casting

General Metal casting Process Steps and which is illustrated as below:

1. Make the core box and master pattern.
2. Make the core and the mould.
3. Burnish the alloy.
4. The molten metal should be poured into the mould.
5. Give the metal time to solidify.
6. Take the casting out of the mould.
7. Complete the casting.

Die casting process

Zinc and aluminum, two metals with low melting points, are injected into the die casting mould during the process of die casting, and then the mould is let to cool. Both simple and sophisticated sheet metal pieces may be produced using hot chamber casting, which happens under two distinct processes. The hot method uses a distinctive technique and is in charge of producing numerous metal components used in various applications depending upon that melting point, and cold chamber casting. It is used in manufacturing consumer and industrial goods. However, you should become quite knowledgeable about it before using the method or outsourcing to businesses that provide such services. Consequently, this essay will introduce die casting, including its history, its mechanics, and its benefits and drawbacks. Low-melting point metals are melted and injected into a die casting mould that has previously been created. This process is known as die casting. A mould or tools are made of steel that has been specifically manufactured for a given project utilizing manufacturing techniques like CNC machining. Die cast sheet metal parts offer great levels of accuracy, accuracy, and repeatability as a result.

Large capital expenses associated with the metal dies and casting equipment often restrict the method to high-volume manufacturing. Die casting requires only four primary procedures for the

production of components, which keeps the additional cost per item minimal. Die casting generates more castings than almost any other casting technique because it is especially well-suited for a lot of small- to intermediate castings. Die castings are distinguished by dimensional uniformity and a very excellent surface quality (by casting standards).

Rolling

Metals and alloys are plastically deformed into semifinished or finished products in this process by being pushed between two spinning wheels. The metal is first forced into the area between two rolls; after the roll takes a "bite" into the material's edge, the material is drawn in by the friction between the surfaces of the rolls and the material.

As the rollers squeeze (and pull) the material, it is exposed to considerable compressive force. This is a bulk material handling procedure that reduces the cross-section of the material while increasing its length. The imprint cut in the roll surface through which the substance travels and into which it is crushed determines the final cross-section.

Hot and cold rolling are both used. The starting point of a rolling mill linked to a steel factory is a cast ingot of steel, which is gradually broken down into blooms, billets, and slabs. The slabs are hot rolled into slab, sheet, rod, bar, rails, and other structural forms such as angles, channels, and so on. Steel is frequently converted into such economically essential parts in another rolling machine known as a merchant mill.

Rolling is a highly easy and cost-effective method of generating commercially significant sections. In the cases of steel, about three-fourths of all steel produced in the nation is marketed as a rolled product, with the remainder employed as forgings, extruded goods, and cast form. This demonstrates the significance of the rolling process.

Rolled Product Nomenclature

The following terminology is often used:

Blooms: The initial product produced by breaking down Ingots. A bloom's cross-section size ranges from 150 mm rectangular to 250 mm square, or possibly 250 300 mm rectangular.

Billet: The next product rolled from either a bloom is a billet. Billets range in size from 50 mm square to 125 mm square.

Slab: Slab has a rectangular cross-section and thicknesses ranging from 50 to 150 mm. It is available in lengths of up to 1 metre.

Plate: A plate is typically 5 mm thick or thicker, 1.0 or 1.25 metres wide, and 2.5 metres long.

Sheet: A sheet may be up to 4 mm thick and has the same width and length as a plate.

Flat: Flats come in a variety of thicknesses and widths and are lengthy strips of material with a certain cross-section.

Foil: An extremely thin sheet of metal.

Bar: Bars are typically circular in cross-section and many metres long. They are common raw material (stock) for capstan and turret lathes.

Wire: A wire is a length (typically in coil form) of a tiny circular segment, the diameter of which determines the wire's size.

Rolling mechanism

Each of the two rollers makes contact with the metal surface along the arc AB, which is referred to as the arc of contact. Angle of contact (α) is determined by dividing Arc AB by the radius of rolls. The rollers only move the material ahead because of the friction between the roll surface and also the metal. The response at the contact point A will be R acting along the radial line O1A, and the frictional force will be operating along the tangent at A at right angles to O1A. In the worst-case scenario, $R \sin \alpha = R \cos \alpha = \tan \alpha$ or $\alpha = \tan^{-1} \mu$. If μ is larger than $\tan^{-1} \mu$, the material will not enter the rollers without assistance, r is the radius of the rollers. The value of h_0 for a particular diameter of rollers and distance between them is restricted by the value of μ which relies on the material of the rolls and work being rolled, the roughness of their surfaces, and the rolling temperature and speed.

In the case of hot rolling, when maximal cross-section reduction per pass is desired, it may be required to artificially boost the value of μ by "ragging" the surface of rolls. Ragging is the process of roughening the surface of rolls by forming tiny grooves in the roll surface. However, ragging of rolls is not essential nor desired in cold rolling, which is a finishing process with minimal cross-section reduction. In reality, in such instance, some lubrication is used in addition to providing the rolls a perfect finish. Another rationale for settling for a lower coefficient of friction in cold rolling is because extremely high pressures are employed in this operation, and even with a low value of μ , significant frictional force is available. Biting angles used in industry are typically $2-10^\circ$... for cold rolling of sheets and strips; $15-20^\circ$... for hot rolling of sheets and strips; and $24-30^\circ$... for hot rolling of large billets and blooms.

Although the material is crushed between two rollers during the rolling process, the breadth (b_0) of the cloth does not grow or just marginally rises. Because the volume of material entering the rolls equals the volume of material leaving the rolls, and material thickness decreases from h_0 to h_1 , the velocity of material leaving the rolls must be greater than the velocity of material entering the rollers. The rolls move at a constant surface speed and at a constant r.p.m. The rolls are attempting to move the material into in the rolls only by friction; there is no positive hold between the rolls and the substance. As a result, on one side, i.e., point A, where contact between the rolls and workpiece begins, the rolls move at a faster surface speed than the work material. As the material is compressed and passed through the rollers, its speed steadily rises until, at a point CC (Fig. 3.2), known as the neutral or no slip section, the velocity of metal matches the velocity of rolls. As the material is pressed more, its speed surpasses the roll's speed. The angle subtended at the neutral region of the roll is known as the angle of no slip or crucial angle (angle BO1C).

The lagging zone is the deformation zone to the left of the neutral section, while the leading zone is the deformation zone to the right of the neutral section. If V_r is the velocity of the roll surface, V_0 is the velocity of the material at the entry to the deformation zone, and V_1 is the velocity of the material at the exit of the rolls, we get

$$V_1 (V_r - V_0) = \text{Forward slip}$$

A hundred percent

And Backward slip = $\frac{V_r - V_1}{V_0} \times 100\%$

V_r

Forward slip is typically 3-10% and rises with increasing roll dia and friction coefficient, as well as with decreasing material thickness being rolled.

Other concepts related to rolling are defined further below: Draught absolute $h = (h_0 - h_1)$ mm,

h/h_0 = relative draught

a hundred percent

Absolute elongation, $l = \text{Final length} - \text{Work material original length}$

Elongation coefficient = final length

The original duration

Absolute spread = final work material width minus original material width, Note: During cold working, absolute spread may be assumed to be zero.

ROLLING MILL TYPES

The following are short descriptions of several kinds of rolling mills:

Two large mills: It is made up of two thick rolls stacked on top of each other. Bearings support the rolls, which are housed in solid upright frames (called stands) that are grouted here to rolling mill floor. The vertical distance between the rollers may be adjusted. The rolls spin in opposing directions and are powered by large electric motors. Typically, the rotated direction of rolls cannot be changed, therefore

The work must only be fed into rolls from one direction. If rolling requires more than one 'pass' in the same set of rolling, the material must be returned to the same side once the first pass is completed.

Because conveying material (which is red hot) from one side to another is difficult and time consuming (material may cool in the meanwhile), a "two high reversing mill" has been developed in which the direction of roll rotation may be altered. By transferring the material via back and forth passes, this enables rolling.

Three large mills: a three-high rolling mill configuration. It is made up of three rolls stacked squarely on top of one another, as depicted. As in the case of a two-high mill, the first and two rollers rotate in opposing directions. The rotational directions of the second and third rolls are once again opposing. All three rollers always revolve in the same direction in their bearings. The benefit of this mill is that the work material may be supplied in just one direction between the first and second rolls, with a return pass given between the second and third rollers. This eliminates the need to carry material from one side of the rollers to the other after one pass.

Four tall mills: This mill is made up of four horizontal rollers, two of which are smaller in diameter and two of which are significantly bigger. Backup rolls are the bigger rolls. The smaller rolls are the working rolls, however without the backup rolls, the rolled material would be fatter in the centre and thinner at either end owing to roll deflection between stands. When the material is rolled, backup rolls keep the working rolls pressed and limit deflection. Heated and cooled rolled plates and sheets are the most common products of these mills.

Cluster mills: It is made up of two small-diameter working rolls and four or more backup rolls. Because backup rolls cannot surpass the diameter of working rolls by more than 2-3 times, a significant number of backup rolls are required. Working roll sizes are reduced to support

procedures requiring high rolling loads (e.g., cold rolling of high strength steel sheets). As the size of backup rolls increases, it is possible that backup rolls may give deflection. As a result, the backup rolls need assistance or backup from further rolls. As many as 20 backup rolls are employed in the cluster at the world-famous Sendzimir Mill. This machine is used to roll thin gauge stainless steel or other high strength steel sheets.

CHAPTER 6

Ring Rolling

Dr. Sujai S, Assistant Professor
Department of Mechanical Engineering
Faculty of Engineering and Technology, JAIN (Deemed-to-be University), Ramanagara District,
Karnataka - 562112, India.
Email Id: - s.sujai@jainuniversity.ac.in

Seamless (i.e., without a joint) rings are widely used in industry. Some examples are the inner and outer races of ball and roller bearings, as well as steel tyres for railway wheels. Ring rolling is a specific rolling procedure used to create these rings. The initial work piece is a thick-walled circular metal block with a hole in the centre created by drifting or piercing. The work item is heated until it gets red hot before being inserted between two opposingly rotating rollers A and B. The pressure roll B applies internal pressure to the material. The ring spins as it is caught between rolls A and B. At the same time, the interior and outer diameters of the ring gradually expand as the wall thickness decreases. Two guide rollers are appropriately positioned on the ring's outside surface to guarantee that it is round. The rolling is halted when the outer or inner dia of the ring reach the necessary size.

Cold Rolling

Hot rolled steel products have an unappealing greyish-black colour. Because to oxidation of the outer surface, nonferrous materials also obtain a tarnished appearance. The surface texture of hot rolled items is harsh, and the completed sizes are far from ideal. In the case of steel, decarburisation is caused by the oxidation of iron on the surface. Hot rolling, on the other hand, is particularly inexpensive because, because to greater flexibility, considerable cross-section reductions may be produced fast and with little energy usage. A large amount of hot rolled "black" bars and steel sheets/plates are utilised in the construction sector for structure fabrication.

Cold rolling produces thinner gauges, greater surface polish, tighter size control, and "bright" surfaces. Because of strain hardening, these goods gain strength and wear resistance. The impact of mechanical work (i.e., strain hardening) is automatically countered in the hot rolling process since recrystallisation inside the hot worked material continues at the same time.

Rolling Defects

To comprehend the reasons and solutions for rolling problems, we will separate them into two categories:

Surface flaws and structural flaws are the two types of flaws.

Surface flaws include rusting and scaling, interface scratches, surface fractures, and pits left on the surface after the detachment or removal of scales that may have been forced into the surface.

Structural flaws are more serious rolling flaws, some of which are impossible to correct. Among these flaws are the following: Wavy edges zipper cracks, and edge cracks, Split in the middle Alligatoring Folds

Laminations.

Zipper cracks and wavy edges: These flaws are created by roll bending under rolling pressure. A roll may be thought of as a beam supported by its supports. The rolls deflect when subjected to rolling pressure. As a result, the work material gets thinner at the two borders and thicker in the centre. In other words, the material develops longer towards the borders than in the centre. Tensile tension is generated in the centre, whereas compressive stress is generated at the margins. The former results in zipper fractures in the centre, while the latter results in wavy edges.

The solution to zipper cracks and wavy edges is to impart "camber" to the rolls. They are somewhat convex in the centre to compensate for distortion under rolling loads. Edgcracks and a split in the centre: These flaws are created by non-homogeneous plastic deformation of the metal over its breadth. Under the rolling pressure, the work piece's height lowers while its length grows as it travels through the rollers. Some lateral spread, or growth in breadth, occurs as well. However, lateral spread is greater towards the margins rather than in the centre because there is less barrier to lateral spread at the edges. Friction and the surrounding layer of material prevent lateral spread at the centre. As a consequence, a reduction in lateral spread in the middle area of the work material results in a bigger rise in length in this region than at the margins.

It is clear that under such non-homogeneous deformation of the work material, the edges suffer tension (as the centre section attempts to pull it owing to material continuity) while the central portion experiences compressive stress. Such a stress distribution may cause an edge fracture or, in extreme circumstances, a split along the core part.

Alligatoring: As previously stated, rolling results in a decrease in height and an increase in length. However, owing to friction at the interface between the rolls and the upper and lower surfaces of the work material, the dilation on the top and bottom surfaces is smaller than the material placed at the work piece's centre of thickness. If circumstances deteriorate, it may result in a defect known as "alligatoring," which is the rupture of material along its length into an upper and lower half that resembles the open mouth of the an alligator.

Layers are referred to as laminations. If the ingot is not sound and includes piping or blow holes, and they are not entirely welded during rolling (for example, if the piping has oxidised material or non-metallic inclusions, it will not be welded), it will result in a fault known as laminations. Nonmetallic inclusions are quite common in ingots; during rolling, they will be extended and including sound material. This may also result in laminations. These faults can only be corrected by eliminating the area of the ingot containing pipework and other problems and choosing only excellent metal for rolling.

Metal

Part II delves into the four different categories of engineering materials: (1) metals, (2) ceramics, (3) polymers, and (4) composites. Metals are the most significant engineering materials, and this chapter is about them. A metal is a class of materials distinguished by ductility, malleability, lustre, and high electrical and thermal conductivity. Metallic constituents and their alloys are included in this category. Metals offer qualities that allow them to meet a broad range of design needs. The industrial techniques that mould them into goods have been created and perfected through time; in fact, some of the processes trace back to prehistoric times (Historical Note 1.2).

Furthermore, heat treatment may improve the characteristics of metals. Metals' technical and economic relevance stems from the following broad qualities shared by almost all major metals:

High stiffness and strength. Metals may be alloyed to provide high rigidity, strength, and hardness, and are consequently employed to provide the structural framework for the majority of designed goods. The ability to be tough. Metals absorb energy more efficiently than other types of materials.

Excellent electrical conductivity. Metals are conductors due to their metallic bonding, which allows electrons to travel freely as charge carriers. Thermal conductivity is excellent. Metallic bonding also explains why metals transport heat more efficiently than ceramics or polymers.

Furthermore, several metals have unique qualities that make them appealing for particular uses. Many common metals are available at a cheap cost per unit weight and are often the material of choice due to their low cost.

A multitude of industrial methods are used to turn metals into components and products. Depending on the method, the metal's beginning form varies.

The major categories are (1) cast metal, which is purchased in the form of very small powders for conversion into parts using powder metallurgy techniques; (2) wrought metal, which has been worked or can be worked (e.g., rolled or otherwise formed) after casting; better mechanical properties are generally associated with wrought metals compared to cast metals; and (3) powdered metal, which is purchased in the form of very small powders for conversion into parts using powder metallurgy techniques. The majority of metals are accessible in all three forms. This chapter's discussion concentrates on categories (1) and (2), which are of the most commercial and engineering relevance. Chapter 16 looks at powder metallurgical methods. Metals are divided into two categories: ferrous (those based on iron) and nonferrous (all other metals).

Phase Diagrams

A phase diagram, as used in this literature, is a graphical representation of the phases of a metal alloy system on the basis of composition and temperature. This schematic discussion will be confined to alloy systems with two elements at atmospheric pressures. This is referred to as a binary phase diagram. Other types of phase diagrams are addressed in materials science textbooks, such as

The Alloy of Copper and Nickel the phase diagram is best introduced by example. Figure 6.2 depicts one of the most straightforward instances, the Cu-Ni alloy system. The horizontal axis represents composition, whereas the vertical axis represents temperature. As a result, every point on the diagram represents the overall composition as well as the phase or phases present at the particular temperature. Pure copper melts at 1083°C (1981°F), whereas pure nickel melts at 1455°C (2651°F). As temperature increases, alloy ratios between these extremes demonstrate progressive melting that begins at the solidus and ends at the liquidus.

Throughout its entire composition range, the copper-nickel system is a solid solution alloy. The alloy is a solid solution somewhere below the solidus line; there are no intermediate solid phase in this system. The zone delimited by the solidus and liquidus, on the other hand, has a combination of phases. The phase diagram now shows that these temperatures vary with composition. The metal is a solid-liquid mixture that exists between the solidus and the liquidus.

Determining Chemical Compositions of Phases

Although the overall composition of the alloy is determined by its location along the horizontal axis, the liquid compositions differ, and solid phases are not interchangeable. These compositions may be determined from the phase diagram by drawing a horizontal line just at temperature of interest. The locations of intersection between both the horizontal line and the solidus and liquidus represent the solid and liquid phase compositions, respectively. Simply make vertical projections from the junctures to the x-axis and read the compositions that result, as shown in Figure 6.1.




Figure 6.1: Represents the phases of material under chemical processes

Tube Drawing and Making

Extrusion is a procedure that subjects metal to plastic flow by confining the metal in a closed chamber with the single opening supplied by a die. The material is frequently prepared so that it can undergo deformations at a fast enough pace to be pushed out of the die hole. During the procedure, the metal fills the die hole and emerges as a long strip that has the same cross-section as the die opening. In addition, the metal strip manufactured will have a longitudinal grain flow. Extrusion is most typically used to produce solid and hollow sections of nonferrous metals and alloys such as aluminium, aluminum-magnesium alloys, magnesium and its alloys, copper, brass, and bronze, among others. Extrusion is also used to make certain steel goods. The material to be produced is in the form of cast ingots or billets. Extrusion may be done either hot or cold. Extruded goods have a broad range of cross-sections.

The following are some of the benefits of the extrusion process:

- (i) The complexity and variety of pieces that may be created by the extrusion technique are very broad. Dies are quite basic and straightforward to create.
- (ii) The extrusion operation is completed in a single pass. This is not the case with rolling; the amount of decrease in extrusion is substantial. The extrusion process is simple to automate.

- (iii) The extrusion technique can readily manufacture large diameter, hollow goods, thin walled tubes, and so forth.
- (iv) Extruded goods have a good surface polish and great dimensional and geometrical correctness. This cannot be achieved by rolling.

The pressure needed for extrusion is determined by the material's strength and the extrusion temperature. If the material is heated, it will shrink. It will also be determined by the needed cross-section reduction and the speed of insertion. The pace of extrusion is limited. Extrusion at high speeds may cause the metal to break. Extrusion ratio refers to the needed decrease in cross-sectional area. There is also a limit to this. This ratio should not exceed 40:1 for hot steel extrusion, but it may be as high as 400:1 for hot aluminum extrusion.

Extrusion Processes

The following extrusion processes may be classified:

Hot Extrusion (A)

1. Direct or forward extrusion.
2. Indirect or backward extrusion.

Cold Extrusion (B)

1. Extrusion of hooks.
2. Extrusion by impact.
3. Forging by cold extrusion.

Hot Extrusion Methods I Forward or direct extrusion method: The material to be extruded in this procedure is in the shape of a block. It is heated to the required temperature before being transported inside the chamber as die with an aperture shaped like the cross-section of the extruded product is inserted in the front part of the chamber. A ram and a foot pad are used to push the material block from behind. Because the chamber is completely sealed on all sides, the heated material is forced to squeeze through die-opening in the shape of a long strip with the requisite cross-section (Figure 6.2).




Figure 6.2 Represents extrusion process of material

The method seems straightforward, but the friction between the material and the chamber walls must be overcome with appropriate lubrication. The high temperature to which the steel must be heated makes it challenging to find a suitable lubricant for extruding steel items. As a lubricant, molten glass is used to remedy the issue. As a lubricant, a blend of oil and graphite is employed at lower temperatures. A little bit of metal is left in the chamber at the conclusion of the extrusion process that cannot be extruded. This item is known as butt end scrap and is discarded. To make a tubular rod, a ring with the same diameter as the tube bore is connected to the ram. When the material is extruded, this mandrel goes through the die in the centre. The hole in the die will determine the outer diameter of the tube produced, and the bore of the tube will be equal to the mandrel diameter. The extrusion process will be referred to as "tubular extrusion" from then on.

(ii) Reverse or indirect extrusion the heated metal block is put into the container/chamber as indicated. Except for the front, where a ram with a die pushes on the material, it is limited on all sides by the container walls. The material must flow forward through the aperture in the die while the ram pushes rearward. The ram is hollow so that the extruded metal bar may pass through freely.

Machines for Extrusion

For extrusion, both hydraulic and mechanical presses in horizontal and vertical configurations are employed. They should be able to apply strong pressures and have lengthy strokes on their rams. Lubricants are utilised to minimise friction between the metal and the extrusion chamber walls. Die and punches are constructed of high-quality alloy steels known as cold and hot die steels. Extrusion speed for light alloys is about 0.5 m/sec and 4.5 m/sec for copper alloys.

DEFECTS IN EXTRUSION

Surface fractures may form on the surface for extruded metal/products. This is due to the heat produced during the extrusion process. These fissures are particularly common in aluminium, magnesium, and zinc alloy extrusions.

Internal fissures might form in the extruded product as well. These are also known as a centre burst, a centre crack, and an arrowhead fracture. The likelihood for centre cracking rises as die angles and material impurities increase.

Drawing on Wire

Wire drawing is a straightforward procedure. Rods composed of steel or nonferrous metals and alloys are dragged through conical dies with a hole in the centre in this operation. The cone's included angle is maintained between 8 and 24°. As the material is drawn through the cone, it experiences plastic deformation and eventually shrinks in diameter. Simultaneously, the length is raised proportionally.

Because of the constant rubbing of metal being dragged through it, dies tend to wear out quickly. As a result, they are built of very hard materials such as alloy steel, tungsten carbide, or even diamond. The decrease in cross-sectional area accomplished in one pass is around 25-30%. As a result, in a wire drawing facility, the wire must pass through a series of dies of increasingly decreasing diameter to accomplish the needed diameter reduction. However, strain hardening occurs when the wire travels through dies and experiences plastic deformation. Its strength grows while its ability to withstand additional plastic deformation declines. As a result, during the whole course of the wire, it must be heated (and cooled) to eliminate the impact of work-

hardening. "In process annealing" refers to this procedure. The goal is to restore the material's softness and ductility so that the drawing process can go easily.

The metal rods that will be pulled into cables must be spotless. They are pickled in an acid bath if required to dissolve the oxide coating on the surface. Its front end is then tapered down to fit through the hole in the die, which is securely held in the wire drawing machine. The wire is dragged via a series of power-driven spools or revolving drums.

The friction between the wire rod and the die generates a lot of heat during wire drawing. Dry soap or a manmade lubricant is used to minimise friction. Despite the reduced friction, the dies and drummers may need water cooling.

Tungsten carbide is the main material for dies, however ruby or diamond dies are preferable for drawing thin wire.

The drawing machines may be linked together so that the wire drawn by the preceding die can be gathered (in coil shape) in sufficient amount before being fed into the next die for further diameter reduction. The linear speed of wire drawing increases as the diameter decreases. Reduction ratio, Die angle, and Friction are the primary variables in the wire drawing process. Inadequate management of these factors will result in flaws in the drawn material. Center cracking (as in extrusion and for the same reasons) and the production of longitudinal scratches or folds in the material are examples of defects.

Polyimides These polymers are available as thermoplastics and thermosets, although the TS variants are more often used in industry. They are available in a variety of forms, including tapes, films, coatings, and moulding resins, under brand names such as Kapton (Dupont) and Kaptrex (Professional Plastics). Chemical resistance, high tensile strength and stiffness, and temperature stability are all characteristics of TS polyimides (PI). Due to their strong heat resistance, they are known as hightemperature polymers. Insulating films, moulded components used in high-temperature operation, flexible cables in computers, medical tubing, and fibres for protective apparel are all examples of applications that make advantage of these qualities.

Polyurethanes this is a broad family of polymers that are all distinguished by the presence of the urethane group (NHCOO) in their structure. The chemistry of polyurethanes is complicated, and the family has several chemical variants. The interaction of a polyol with hydroxyl (OH) groups, such as butylene ether glycol (C₄H₁₀O₂), with an isocyanate, such as diphenylmethane diisocyanate, is the distinguishing property (C₁₅H₁₀O₂N₂). Polyurethanes may be thermoplastic, thermosetting, or elastomeric materials depending on chemistry, cross-linking, and processing. The latter two are the most relevant commercially. Polyurethane is most often used in foams. These may be elastomeric or stiff, with the latter having more cross-linked. Rigid foams are utilised in hollow building panels and refrigerator walls as a filler material. In these applications, the material offers great thermal insulation, increases structural stiffness, and does not absorb considerable quantities of water. Many paint, varnishes, and other coating products are urethane-based.

the repeating unit $-(\text{CH}_3)_m\text{-SiO}-$, where m determines proportionality. Polysiloxanes may be generated in three forms based on composition and processing: (1) fluids, (2) elastomers, and (3) thermosetting resins. Fluids (1) are low molecular weight polymers used in lubricants, polishes, waxes, and other liquids; they are not polymers in the meaning of this chapter, but they are major commercial items. Cross-linking occurs in silicone elastomers (2) (discussed in Section 8.4) and

thermosetting silicones (3) (discussed here). Polysiloxanes, when extensively crosslinked, create hard resin systems used in paints, varnishes, and other coatings, as well as laminates such as printed circuit boards.

They are also employed in the manufacture of electrical components. Curing is achieved by either heating or allowing the polymer-containing solvents to evaporate. Silicones are well known for their heat resistance and water repellence, yet their mechanical strength is not as high as that of other cross-linked polymers contains data for a typical silicon thermosetting polymer.

Elastomers

When exposed to relatively mild loads, elastomers exhibit considerable elastic deformation. Some elastomers can sustain 500% or more expansions and yet recover to their original form. Rubber is, of course, the more common name for elastomer. Rubbers are classified into two types: natural rubber, which is obtained from specific biological plants, and synthetic elastomers, which also are made by polymerization procedures similar to those used for thermoplastic and thermosetting polymers. Before delving into both natural and synthetic rubbers, explore the general properties of elastomers.

Characteristics of Elastomers

Elastomers are made up of cross-linked long-chain molecules. They have exceptional elastic qualities due to a combination of two characteristics: (1) the long molecules are tightly kinked when unstretched, and (2) the degree of cross-linking is much lower than that of thermosets. These characteristics are which depicts a strongly kinked merge molecule under no stress. When the material is stretched, the molecules are pushed to uncoil and straighten (b). The initial elastic modulus of both the aggregatematerial is provided by the molecules' inherent reluctance to uncoiling. As more tension is applied, the covalent bonds weaken.

Cross-linked monomers begin to play an increasing role in modulus and stiffness. \With increased cross-linking, the elastomer stiffens and its modulus of elasticity becomes more linear. The stress-strain curves for three grades of rubber are shown in the figure: natural crude rubber, which has very low cross-linking; cured (vulcanised) rubber, which has low-to-medium cross-linking; and hard rubber (ebonite), which has a high degree of cross-linking and thus becomes a thermosetting plastic.

To have elastomeric qualities, an apolymer must be amorphous in the unstretched state and have a temperature above T_g . The material is hard and brittle if it is below the glass transition temperature (T_g), and stretchy if it is above T_g . Because its linear molecules are constantly coiled to some degree, every amorphous thermoplastic polymer will display elastomeric characteristics above T_g for a short period, allowing for elastic extension. The lack of cross-linking in TP polymers precludes them from being fully elastic, instead exhibiting viscoelastic behaviour.

Most popular elastomers nowadays need curing to achieve cross-linking.

In the context of natural rubber (and some synthetic rubbers), curing is referred to as vulcanization, which entails the development of chemical cross-links between the polymer chains. Depending on the degree of stiffness wanted in the material, typical cross-linking in rubber is 1 to 10 links per 100 carbon atoms in the linear polymer chain. This is much less than

the degree of cross-linking seen in thermosets. Another way of curing includes use of starting chemicals that, when combined (often with the help of a catalyst or heat), react to generate elastomers with very uncommon cross-links between molecules. Reactive system elastomers are the name given to these synthetic rubbers. Certain polymers that cure this way, such as urethanes and silicones, may be classed as thermosets or elastomers based on the degree of cross-linking accomplished during the reaction.

Thermoplastic elastomers are a relatively new family of elastomers with elastomeric qualities resulting from the combination of two thermoplastic phases.

At room temperature, one is above its T_g , while the other is below it. As a result, we have a polymer with soft rubbery areas intermixed with hard particles that serve as crosslinks. The mechanical behaviour of the nanocomposites is elastic, albeit not as extensible as most other elastomers. Because all phases are thermoplastic, the bulk material may be heated beyond its T_m for shaping, allowing for more cost-effective techniques than those utilised for rubber.

Natural Rubber

Natural rubber (NR) is mostly composed of polyisoprene, an isoprene polymer with a high molecular weight (C_5H_8). It is made from latex, which is a milky material generated by many plants, the most significant of which being the rubber tree (*Hevea brasiliensis*), which thrives in tropical area. Latex is an aqueous emulsion containing polyisoprene (approximately one-third by weight) and additional chemicals. Rubber is recovered from latex using a variety of processes that remove the water (for example, coagulation, drying, and spraying).

Natural unvulcanized rubber is sticky in hot weather yet stiff and brittle in cold weather. Natural rubber must be vulcanised in order to be converted into an elastomer with usable qualities. Vulcanization has traditionally been performed by combining tiny quantities of sulphur and other chemicals with raw rubber and heating it. Cross-linking is the chemical consequence of vulcanization; the mechanical outcome is improved strength and stiffness while maintaining flexibility. The stress-strain curves in Figure 8.13 show the substantial change in characteristics produced by vulcanization. Cross-linking may be caused by sulphur alone, but the process is sluggish and takes hours to complete.

Different compounds are added to sulphur during vulcanization to speed up the process and fulfil other purposes. Rubber may also be vulcanised using substances other than sulphur. Curing periods have been greatly shortened in comparison to the traditional sulphur curing of years ago.

Vulcanized rubber is an engineering material known for its high tensile strength, tear strength, resilience (ability to restore shape after deformation), and resistance to wear and strain. Its disadvantage is that it degrades when exposed to heat, sunshine, oxygen, ozone, and oil. Some of these constraints may be alleviated by the application of additives. shows typical characteristics and other characteristics for vulcanised natural rubber. Market share is calculated as a percentage of total yearly rubber volume (natural + synthetic). Rubber accounts for about 15% of the overall polymer market. Automotive tyres are the biggest single market for natural rubber. Carbon black is a significant addition in tyres; it strengthens the rubber, increasing tensile strength and resistance to tearing and abrasion. Rubber is also used in shoe bottoms, bushings, seals, and shock-absorbing components. The rubber is compounded in each instance to acquire the precise qualities needed in the application. Other additives used in rubber and certain synthetic

elastomers, in addition to carbon black, include clay, kaolin, silica, talc, and calcite, as well as compounds that accelerate and encourage vulcanization.

Synthetic Rubbers

Synthetic rubber tonnage is now more than three times that of natural rubber. The development of these synthetic materials was primarily spurred by the World Wars, when NR was scarce. Styrene-butadiene rubber (SBR), a copolymer of butadiene (C₄H₆) and styrene, is the most significant of the synthetics (C₈H₈). Petroleum, like most other polymers, is the primary raw source for synthetic rubbers. Only the most commercially important synthetic rubbers are mentioned here. Contains technical information. Data for market share are for total volume of natural and synthetic

Butadiene Rubber is a kind of rubber. Polybutadiene (BR) is most essential when combined with other rubbers. In the manufacture of vehicle tyres, it is combined with natural rubber and styrene (styrene-butadiene rubber is addressed later). Polybutadiene's tear resistance, tensile strength, and simplicity of processing are less than acceptable without compounding.

Howeveryl Rubber Butyl rubber is a polyisobutylene (98%-99%) and polyisoprene (1%-2%) copolymer. It may be vulcanised to produce a rubber with extremely low air permeability, leading to uses in inflatable items such as inner tubes, tubeless tyre liners, and sports goods.

Rubber made with chloroprene one of the earliest synthetic rubbers to be produced was polychloroprene (early 1930s). It is a significant specialpurpose rubber that is now commonly known as Neoprene. When stretched, it crystallises to offer excellent mechanical characteristics. Chloroprene rubber (CR) is more resistant to oils, weather, and ozone, heat, even flame than natural rubber (NR), although it is somewhat more costly. Fuel hoses (and other automotive components), conveyor belts, and gaskets are among its uses, however tyres are not among them.

Rubber made of ethylene and propylene the terpolymer ethylene-propylene-diene (EPDM) is formed by polymerizing ethylene and propylene with tiny amounts (3%-8%) of a diene monomer. Other than tyres, applications include for components in the automobile sector. Other applications include wire and cable insulation.

Isoprene Rubber is a kind of rubber. Polymerization of isoprene results in the chemical equivalent of natural rubber. Unvulcanized synthetic polyisoprene is softer and more malleable than raw natural rubber. The synthetic material's applications are comparable from those of its natural counterpart, with vehicle tyres being the biggest single market. It is also utilised in footwear, conveyor belts, and caulk. The cost per unit weight is about 35% greater than for NR.

Nitrile Rubber is a kind of rubber. This is a vulcanizable copolymer of butadiene (50%-75% by weight) and acrylonitrile (25%-50% by weight). Butadiene-acrylonitrile rubber is the more technical term for it. It's tough and resistant to abrasion, oil, gasoline, and water. Because of these qualities, it is perfect for applications such as fuel hoses and seals, as well as footwear.

Polyurethanes Elastomers, most often generated as flexible foams, are thermosetting polyurethanes with little cross-linking. They are extensively utilised as cushion materials for furniture and automotive seats in this form. Unfoamed polyurethane may be moulded into a wide range of goods, from shoe bottoms to vehicle bumpers, with the cross-linking altered to provide the necessary qualities for the application. The material is a thermoplastic elastomer which can be injection moulded since there is no cross-linking. Reaction injection moulding and other shaping procedures are employed with elastomers and thermosets.

Silicones Silicones, like polyurethanes, may be either elastomeric or thermosetting depending on the degree of cross-linking. Silicone elastomers are well-known for their broad temperature range of use. Their oil resistance is low. The silicones have a variety of chemistries, the most prevalent of which being polydimethylsiloxane. Silicone elastomers must be reinforced, often with fine silica particles, to provide acceptable mechanical characteristics. Because of their high cost, they are classified as special-purpose rubbers for uses such as gaskets, seals, wire and cable insulation, prosthetic devices, and caulking material bases. Butadiene-Styrene Rubber SBR is a random copolymer of styrene (about 25%) and butadiene (75%). Prior to World War II, it was created in Germany as Buna-S rubber. It is now the greatest tonnage elastomer, accounting for almost 40% of all rubbers manufactured (natural rubber is second in tonnage). Its appealing characteristics include cheap cost, abrasion resistance, and greater homogeneity than NR. Its properties and uses are extremely similar to those of natural rubber when supplemented with carbon black and vulcanised. The price is also comparable. A detailed examination of its qualities indicates that, with the exception of wear resistance, most of its mechanical properties are inferior to NR, but its resistance to heat ageing, ozone, weather, and lubricants is greater. Automotive tyres, footwear, and wire and cable insulation are all examples of applications. Styrene-butadiene-styrene block copolymer is a thermoplastic elastomer that is chemically linked to SBR.

Elastomers that are thermoplastic a thermoplastic elastomer (TPE), as previously defined, is a thermoplastic that behaves like an elastomer. It belongs to a polymer family that is a rapidly increasing part of the elastomer industry. TPEs get their elastomeric qualities not from chemical cross-links, but through physical linkages between the material's soft and hard phases. Styrene-butadiene-styrene (SBS) is a block copolymer, as opposed to styrene-butadiene rubber (SBR), which is a random copolymer.

Other copolymers and polymer mixes include thermoplastic polyester copolymers. SBS data may be found in. icated, comprising two incompatible components that form discrete phases with varying room temperature characteristics. TPEs cannot compete with typical cross-linked elastomers in terms of increased temperature strength and creep resistance due to their thermoplasticity. Footwear, rubber bands, extruded tubing, cable coating, and moulded components for automotive and other purposes requiring elastomeric qualities are examples of typical applications. TPEs are not suited for tyre applications.

Polymer Recycling and Biodegradability

It is estimated that 1 billion tonnes of plastic have been wasted as rubbish since the 1950s. 2 Because the main linkages that make plastics so durable also make them resistant to disintegration by natural environmental and biological processes, this plastic waste may stay there for generations. In this part, we look at two polymer themes related to environmental concerns: (1) polymer recycling and (2) biodegradable plastics.

Polymer Recycling

Every year, around 200 million tonnes of plastic items are manufactured worldwide, with the United States producing more than one-eighth of this total. Only around 6% of the tonnage in the United States gets recycled as plastic trash; the rest stays in goods or ends up in rubbish dumps. Recycling entails recovering wasted plastic goods and reprocessing them into new products, which may be substantially different from the original discarded ones. Plastic recycling is often more challenging than recycling glass and metal items. There are various causes for this,

including: (1) Many recycled metal items are much larger and heavier than plastic parts (e.g., structural steel from buildings and bridges, steel car body frames), so the economics of recycling are more favourable for recycling metals; most plastic items are lightweight; (2) glass products are all based on silicon dioxide, whereas plastics come in a variety of chemical compositions that do not mix well; and (3) many plastic products contain fillers, dyes, and additives. The change in the cost of recycled materials is, of course, a constant issue in all recycling initiatives.

The Plastic Identification Code (PIC) was established by the Society to address the issue of mixing various kinds of plastics and to facilitate plastic recycling of the Plastics Industry. The code is represented as a triangle formed by three bent arrows surrounding a number. On the plastic object, it is printed or moulded. The number is used to identify the plastic for recycling reasons. The seven plastics (all thermoplastics) used in the PIC recycling programme are: (1) polyethylene terephthalate, which is used in 2-liter beverage containers; (2) high-density polyethylene, which is used in milk jugs and shopping bags; (3) polyvinyl chloride, which is used in juice bottles and PVC pipes; (4) low-density polyethylene, which is used in squeezable bottles and flexible carton lids; (5) polypropylene, which is The PIC aids in the separation of objects created from various kinds of plastics for recycling. Nonetheless, sifting the plastics is a time-consuming task.

The thermoplastic materials may be easily recycled into new products after being separated. This is not true for thermosets and rubbers as cross-linking occurs in these polymers. As a result, these materials must always be recycled and treated in various ways. Recycled thermosets are often pulverised into fine particles and utilised as fillers in moulded plastic products. The majority of recycled rubber originates from old tyres. While some of these tyres are retreaded, others are pulverised into granules such as chunks and nuggets that may be used for landscaping mulch, playgrounds, and other similar applications.

The code is represented as a triangle consisting of three bent arrows surrounding a number. On the plastic object, it is printed or moulded. The number is used to identify the plastic for recycling reasons. The seven plastics (all thermoplastics) used in the PIC recycling programme are: (1) polyethylene terephthalate, which is used in 2-liter beverage containers; (2) high-density polyethylene, which is used in milk jugs and shopping bags; (3) polyvinyl chloride, which is used in juice bottles and PVC pipes; (4) low-density polyethylene, which is used in squeezable bottles and flexible container lids; (5) polypropylene, which is The PIC aids in the separation of objects created from various kinds of plastics for recycling. Nonetheless, sifting the plastics is a time-consuming task.

The thermoplastic materials may be easily recycled into new products after being separated. This is not true for thermosets and rubbers due to cross-linking in these polymers. As a result, these materials must be recycled and treated in various ways. Recycled thermosets are often pulverised into fine particles and utilised as fillers in moulded plastic products. The majority of recycled rubber originates from old tyres. While some of these tyres are retreaded, others are pulverised into granules such as chunks and nuggets that may be used for landscaping mulch, playgrounds, and other similar applications.

Biodegradable Polymers

Another strategy to addressing plastics' environmental issues is the creation of biodegradable plastics, which are characterised as polymers that disintegrate via the activity of microorganisms found in nature, such as bacteria and fungus. Conventional plastic goods are typically composed

of a petroleum-based polymer plus a filler, resulting in a polymer-matrix composite. The filler's goal is to increase mechanical qualities and/or minimise material costs. Both the polymer and the filler are not always biodegradable. Non-biodegradable plastics are distinguished by two types of biodegradable polymers: (1) partly degradable and (2) entirely degradable.

A standard polymer plus a natural filler make up partially biodegradable polymers. Although the polymer matrix is petroleum-based and hence non-biodegradable, the natural filler may be devoured by microorganisms (for example, in a landfill), transforming the polymer into a sponge-like structure and perhaps contributing to its disintegration over time.

The most environmentally friendly plastics are entirely biodegradable plastics (aka bioplastics), which are made up of a polymer and a filler produced from natural and renewable sources. Biodegradable plastics are made from a variety of agricultural products. Starch, a key component of maize, wheat, rice, and potatoes, is a frequent polymeric starting material. It is made up of the polymers amylose and amylopectin. Starch may be used to create a variety of thermoplastic polymers that can be processed using traditional plastic shaping processes such as extrusion and injection moulding. Another method for producing biodegradable plastics is to ferment maize starch or sugar cane to make lactic acid, which can then be polymerized to form polylactide, another thermoplastic material. Cellulose is a frequent filler in bioplastics, generally in the form of reinforcing fibres in the polymer-matrix composite. Cellulose is cultivated in the same way as flax or hemp are. It is cheap and has high mechanical strength.

The fact that biodegradable plastics are more costly than petroleum-based polymers limits their use. This might change in the future as a result of technical advancements and leverage. Biopolymers are particularly appealing in instances when degradability trumps economic savings.

Packaging materials that are promptly abandoned as garbage in landfills are at the top of the list. It is estimated that 40% of all plastics are used in packaging, the majority of which is for food goods. As a result, biodegradable polymers are increasingly being employed as alternatives for conventional plastics in packaging applications. Other uses include disposable food service products, paper and cardboard coatings, garbage bags, and agricultural crop mulches. Sutures, catheter bags, and sanitary laundry bags are examples of medical uses.

Press Work and Die-Punch Assembly

The use of mechanical and hydraulic presses for forging and extrusion was previously described. Mechanical presses with knuckles are often used for sheet metal work. These presses are typically vertical in design. These presses have a large flywheel that is powered by an electric motor. When a ram is attached to the flywheel by a connecting rod and just a crank mechanism, it travels up and down the guide ways supplied in the press frame. A foot-operated treadle operates the clutch, which transfers momentum from the flywheel to the ram. The configuration resembles the mechanics of a reciprocating engine. These presses are very handy for producing short, forceful strokes.

These presses are offered in two designs: (i) open frame and (ii) closed frame.

Open frame presses are less sturdy than closed frame presses, but they allow for more material loading since they are open on all sides. Because of their appearance, they are also known as C-frame or gap presses. For heavier work, closed frame presses are employed. The force (or tonnage) that the press is capable of exerting indicates its capability.

Tools working with presses necessitates the use of a collection of dies. A die set is made up of three parts: a punch (male tool), a die (female tool), and a stripping plate. The punch is connected to the ram and the die is bolted to the machine bed in such a way that the two are perfectly aligned. When the punch, together with the press ram, goes lower, the punch passes through the die centrally.

The punch slices the metal sheet as it falls. The punch hole has the same profile as the punch. If the remaining section of the sheet metal is usable, the punched out portion is discarded as scrap. The procedure is known as "punching" in this scenario. If the punched out section is the usable part, the procedure is known as "blanking," and the punching out piece is known as blank. The size of the blank is governed by the size of the die hole (Figure 6.3).




Figure 6.3 Represents Die Forging Process

The stripper plate's duty is to keep the sheet held down throughout the succeeding upward movement of the punch; otherwise, this sheet may get entangled with the punch during the ram's and punch's upward movement. Some room is given between the punch and the die for effective operation and clean cut surfaces. It is a measure of sheet thickness under shear and ranges from 3-5% of thickness. Actually, after the punch's bottom surface makes contact with the sheet, it travels or permeates through the sheet up to roughly 40% of the sheet thickness, causing increasing and higher compressive stress in the sheet metal. Finally, the shear force at the blank's perimeter surpasses the material's maximum shear strength, and the blank is sheared off over the remaining 60% of the sheet thickness. If the blank's perimeter is visually inspected, the depth of penetration-zone and plate boundary are delineated and plainly visible.

The area beneath this curve (shown darkened) represents the amount of energy needed for shearing.

The die and hammer are composed of fine-grained alloy steel of excellent grade. After that, they are heat treated to achieve high hardness, wear resistance, and impact resistance.

When there is no press capable of delivering complete shear force, the bottom surface of the punch is tapered. Shear is the term for this. The use of shear minimises the maximum force needed since the whole perimeter of the punch does not bear on the steel sheet at the same time.

CHAPTER 7

Procedures of Bending

Dr. Ranganathaswamy M K, Assistant Professor
Department of Mechanical Engineering, Faculty of Engineering and Technology, JAIN (Deemed-to-be University), Ramanagara District, Karnataka - 562112, India
Email Id: - mk.ranganatha@jainuniversity.ac.in

Bending is the process of deforming a single layer along a straight line to create the appropriate angle. Bending produces various sections like as angles, channels, and so on, which may subsequently be utilised to construct steel structures. Bending is accomplished with a V-shaped punch, a die, and a press specifically built for the task. The stroke of such presses may be adjusted by the operator, and they are known as press brakes.

A V-shaped punch drives a metal sheet or flat strip into a wedge-shaped die in V-bending. The bend angle is determined by the distance the punch depresses. Bends of 90° or obtuse as well as sharp angles are possible. Only 90° bends are utilised for wiper bending. The sheet is securely held down on the die here, while the punch bends the extended area of the sheet.

Spring back: Due to elasticity, the bend angle tends to expand up after the conclusion of the bending operation once the punch applying the bending force is recovered. This is known as "spring back". The impact of spring back may be countered in the first place by modest overbending. Other approaches to bottoming and ironing help to prevent spring back. Spring back is $1-2^\circ$ for low carbon steels and $3-4^\circ$ for medium carbon steels.

THICK DRAWING

Deep drawing begins with a flat metal plate or sheet that is converted into a cup form by pressing the sheet in the centre with just a circular punch that fits into a cup shaped die. Many containers in the home kitchen, such as deep saucepan, are manufactured via the deep drawing procedure. Deep drawing is used when the depth of the cup is more than half its diameter, while shallow drawing is used when the depth to diameter ratio is less than half. Drawing produces parts of diverse geometries and shapes.

The area of the blank between the die wall and the punch surface is only subjected to tension, but the portion further down at the bottom is subjected to both tension and bending. The part of metal blank that forms this flange at the top of the cup is subjected to circumferential stress concentration and buckling, causing it to thicken. As a result, the flange must be kept down by a hydraulic piston, or its surface would buckle and become uneven, much like an orange peel.

Deep drawing is a challenging procedure, and the material used must be extremely malleable and ductile to avoid cracking under the produced forces. A deep drawn component's wall thickness does not stay constant. Tensile strains cause the vertical walls to thin. However, the thinnest part is all around the bottom corner of the cup. Necking refers to the thinning of the sheet at certain points.

Following deep drawing, the element may be subjected to finishing procedures such as "ironing," the goal of which is to achieve more uniform wall thickness (Figure 7.1).




Figure 7.1 Represent Thick Drawing to the Manufacturing Material

Embossing and Coining

Both coining and embossing procedures are performed 'cold,' and mechanical presses with die and punch are employed. Impressions are formed on sheet metal in such a way that the thickness of the sheet stays constant all throughout even after embossing. It implies that if one face of the sheet is lifted to make a pattern, the other side of the sheet is depressed. Essentially, it is a pressing process that requires little effort. The sheet is spread over the bottom die, and the punch stroke is regulated such that as it goes down to its lowest position, it leaves a consistent clearance equal to the height of the sheet being embossed between the imprints cut in the punch and the die. The pattern is transferred to the sheet by bending it up and down without changing its thickness in any way. Many religious decorative elements are manufactured in this manner.

Coining

A blank of metal softened by the annealing process is put between two dies carrying an imprint in the coining process. The blank is confined throughout its perimeter in such a way that when the two dies close around it, the material cannot flow laterally, or sideways. The content is limited to free to flow both vertically (filling the depressions in the higher die) and downwards (when it fills up depressions in the bottom die). The coining procedure results in the design engraved on the top and bottom dies being stamped in relief (i.e., elevated material) on the corresponding faces of the blank without affecting the size of the blank-circumference. This is how coins used as money in everyday life are made. The pressures necessary here are substantially larger, causing plastic flow of material.

Shear of Guillotine

Readers may have noted that the raw material for all press operations is in the shape of sheets or plates. Sheets and plates are commercially available in two sizes: 2500 1000 mm and 2500 1250 mm. Before subsequent operations such as bending, punching, and so on, they must be chopped into smaller rectangular or square pieces to the desired sizes. Guillotine shears (also known as mechanical presses) are used to cut sheets into smaller pieces with straight cuts. Guillotine shears come with two straight blades of sufficient length manufactured of die steel. The blades are hardened and ground to provide smooth and sharp edges. One blade is attached to the ram (which is significantly longer in the case of guillotine shears), while the other is attached to the machine bed's edge (Figure 7.2).




Figure 7.2 represent sheet positioning

The sheet is positioned on the machine bed with one end protruding. It is kept in place by a clamp. The blades shred the sheet along blade length as the ram goes down. On 250 tonne presses, steel plates up to 10 mm thick may be sheared in this manner. A guillotine shear is essential in every sheet-metal business.

Composite Materials

A fourth material group may be differentiated in addition to metals, ceramics, and polymers: composites. A composite material is a material system made up of two or more physically separate phases that when combined create aggregate qualities that vary from the components. Composites are the most intriguing of the engineering materials in some ways since their structure is more complicated than the other three varieties.

The technical and economic interest in composite materials stems from the fact that their qualities are not only distinct from those of their constituents, but are sometimes substantially better. Among the options are: Composites may be constructed to be very strong and stiff while being extremely light in weight, resulting in strength-to-weight and stiffness-to-weight ratios many times higher than steel or aluminium. These characteristics are extremely desired in a wide range of applications, from commercial aeroplanes to sports equipment.

Fatigue characteristics are often superior to those of popular engineering metals. Toughness is often increased as well. Composites that do not corrode like steel may be created; this is essential in automotive and other applications.

It is feasible to produce combinations of qualities using composite materials that are not conceivable with metals, ceramics, or resins alone. Certain composite materials may improve the look and control of surface smoothness.

Along with the benefits, there are drawbacks and limits to composite materials. These are some examples: (1) Many important composites' properties are anisotropic, which means they differ depending on the direction in which they are measured; (2) many polymer-based composites are susceptible to attack by chemicals or solvents, just as polymers themselves are susceptible to attack; (3) composite materials are generally expensive, though prices may fall as volume increases; and (4) certain manufacturing methods for shaping composite materials are sloppy.

In our review of the other three material classes, we have already come across various composite materials. Cemented carbides (tungsten carbide with a cobalt binder), plastic moulding compounds with fillers (e.g., cellulose fibres, wood flour), and rubber combined with carbon

black are some examples. Although we did not always label these materials as composites, they properly match the above description. A two-phase metal alloy (e.g., Fe-Fe₃C) may even be claimed to be a composite material, albeit it is not categorised as such. Wood is perhaps the most significant composite material. We begin our discussion of composite materials by looking at its technology and categorization. There are several materials and structures that may be used to produce composites; we examine the main categories, giving the greatest focus to fiber-reinforced plastics, which are the most significant economically.

Technology and classification of composite Materials

The word phase refers to a homogenous substance, such as a metal or ceramic having the same crystal structure throughout, or a polymer with no fillers. By merging the phases via yet-to-be-described procedures, a new material is generated with aggregate performance that exceeds the sum of its parts. The result is additive.

Composite materials are categorised in a variety of ways. One such categorization is (1) conventional composites and (2) synthetic composites. Traditional composites are those found in nature or created by civilizations throughout time. Wood is a naturally occurring fiberglass reinforced, while classic composites used in building include concrete (Portland cement with sand or gravel) and asphalt combined with gravel.

Synthetic composites are contemporary material systems that are often connected with the manufacturing sectors, in which the elements are initially manufactured separately and then mixed in a controlled manner to provide the required structure, characteristics, and part shape. These synthetic materials are the composites that are often associated with designed items. In this chapter, we will concentrate on these elements.

Components in A Composite Material

A composite material, in its most basic form, consists of two phases: a primary phase and a secondary phase. The matrix in which the secondary phase is embedded is formed by the main phase. Because it normally works to reinforce the composite, the embedded phase is frequently referred to as a reinforcing agent (or equivalent word).

As we will see, the reinforcing phase may take the shape of fibres, particles, or a variety of different geometries. The phases are normally insoluble in one other, but there must be significant adhesion at their contacts.

The matrix phase may be made of any of three different kinds of materials: polymers, metals, or ceramics. The secondary phase might be one of the three basic materials or an element like carbon or boron.

1. Metal Matrix Composites (MMCs) are composites made of ceramics and metals, such as cemented carbides and other cermets, as well as aluminium or magnesium reinforced by strong, high-strength fibres.

The second most prevalent group is Ceramic Matrix Composites (CMCs). Aluminum oxide and silicon carbide are two materials that may be embedded with fibres to enhance their characteristics, particularly in high-temperature applications. Composites using Polymer Matrix (PMCs). Thermosetting resins are the most common polymers utilised in PMCs. Epoxy and polyester are often blended with fibre reinforcement, whereas phenolic is used with powders. Thermoplastic moulding compositions are often reinforced, most commonly using powders

The categorization may be used to both conventional and synthetic composites.

Asphalt and wood are polymer matrix composites, but concrete is a ceramic matrix composite.

In the composite, the matrix material fulfills many purposes. First, it offers the bulk form of the composite material component or product. Second, it keeps the embedded phase in situ by enclosing and often obscuring it. Third, when a load is applied, the matrix shares the burden with the secondary phase, deforming in certain situations such that the stress is borne mostly by the reinforcing agent.

The Reinforcing Phase

It is critical to remember that the secondary phase's job is to support the main phase. The embedding phase is most usually represented by one of the morphologies shown in Figure 9.1: fibres, particles, or flakes. Furthermore, the secondary phase might exist as an infiltrated phase in a skeletal or porous matrix. Depending on the material, diameters vary from less than 0.0025 mm (0.0001 in) to roughly 0.13 mm (0.005 in).

Fiber reinforcing has the most potential for increasing the strength of composite constructions. Because it carries the majority of the load in fiber-reinforced composites, the fibre is often regarded as the primary ingredient. Because the filament form of most materials is substantially stronger than the bulk form, fibres are appealing as reinforcing agents. As the diameter of the material shrinks, it gets orientated in the direction of the fibre axis, and the likelihood of structural flaws falls considerably. Tensile strength rises considerably as a consequence.

Composite fibres may be either continuous or discontinuous. Continuous fibres are very long; in principle, they provide a continuous channel for a load to be borne by the composite portion. In actuality, because to variances in the fibre material and processing, this is impossible to accomplish. Discontinuous fibres (chopped pieces of continuous fibres) have a small length to diameter ratio (L/D 100). Whiskers hair-like single crystals with diameters as small as 0.001 mm (0.00004 in) and very high strength are an important form of discontinuous fibre. The dimension in which the composite material has isotropic characteristics.

Metals, ceramics, polymers, carbon, and boron are all employed as fibres in fiber-reinforced composites. The most common commercial use for fibres is in polymer composites. The usage of fiber-reinforced metals and ceramics, on the other hand, is increasing. The following is a list of the major varieties of fibre materials. Glass, the most often used fibre in polymers, the name fibreglass refers to glass fiber-reinforced plastic (GFRP). E-glass and S-glass are the two most prevalent glass fibres. E-glass is strong and inexpensive, although its modulus is lower than that of other fibres. S-glass is stiffer and has one of the greatest tensile strengths of any fibre material; nonetheless, it is more costly than E-glass. Carbon may be converted into high-modulus fibres. Other appealing features besides stiffness are low density and minimal thermal expansion.

C-fibers are typically made of graphite and amorphous carbon. Boron has a very high elastic modulus, but its expensive cost restricts its use in aerospace components where this (and other) properties are crucial.

Kevlar 49

This is the most significant polymer fibre; it is a crystallinity aramid polyamide family member. Because of its low specific gravity, it has one of the greatest strength-to-weight ratios of any fibre.

Ceramics

Among ceramics, the most common fibre materials are silicon carbide (SiC) and aluminium oxide (Al₂O₃). Both have large elastic moduli and may be utilised to reinforce metals with low densities and moduli, such as aluminium and magnesium.

Metal

Steel filaments, both continuous and discontinuous, are utilised in polymers as reinforcing fibres. Other metals are less often used as reinforcing fibres at the moment.

Particles and Flakes

It is critical to remember that the secondary phase's job is to support the main phase. The embedding phase is most usually represented by one of the morphologies \: fibres, particles, or flakes. Furthermore, the secondary phase might exist as an infiltrated phase in a skeletal or porous matrix. Depending on the material, diameters vary from less than 0.0025 mm (0.0001 in) to roughly 0.13 mm (0.005 in).

Fiber reinforcing has the most potential for increasing the strength of composite constructions. Because it carries the majority of the load in fiber-reinforced composites, the fibre is often regarded as the primary ingredient.

Because the filament form of most materials is substantially stronger than the bulk form, fibres are appealing as reinforcing agents. As the diameter of the material shrinks, it gets orientated in the direction of the fibre axis, and the likelihood of structural flaws falls considerably. Tensile strength rises considerably as a consequence.

Composite fibres may be either continuous or discontinuous. Continuous fibres are very long; in principle, they provide a continuous channel for a load to be borne by the composite portion. In actuality, because to variances in the fibre material and processing, this is impossible to accomplish.

Discontinuous fibres (chopped pieces of continuous fibres) have a small length to diameter ratio (L/D 100). Whiskers hair-like single crystals with diameters as small as 0.001 mm (0.00004 in) and very high strength are an important form of discontinuous fibre. The dimension in which the composite material has isotropic characteristics.

Metals, ceramics, polymers, carbon, and boron are all employed as fibres in fiber-reinforced composites. The most common commercial use for fibres is in polymer composites. The usage of fiber-reinforced metals and ceramics, on the other hand, is increasing. The following is a list of the major varieties of fibre materials, with their attributes

Glass

The most often used fibre in polymers, the name fibreglass refers to glass fiber-reinforced plastic (GFRP). E-glass and S-glass are the two most prevalent glass fibres. E-glass is strong and inexpensive, although its modulus is lower than that of other fibres. S-glass is stiffer and has one of the greatest tensile strengths of any fibre material; nonetheless, it is more costly than E-glass.

Carbon may be converted into high-modulus fibres. Other appealing features besides stiffness are low density and minimal thermal expansion.

C-fibers are typically made of graphite and amorphous carbon.

Boron

Boron has a very high elastic modulus, but its expensive cost restricts its use in aerospace components where this (and other) properties are crucial.

Kevlar 49

This is the most significant polymer fibre; it is a highly crystalline aramid polyamide family member. Because of its low specific gravity, it has one of the greatest strength-to-weight ratios of any fibre.

Ceramics

Among ceramics, the most common fibre materials are silicon carbide (SiC) and aluminium oxide (Al_2O_3). Both have large elastic moduli and may be utilised to reinforce metals with low densities and moduli, such as aluminium and magnesium.

Metal

Steel filaments, both continual and discontinuous, are utilised in polymers as reinforcing fibres. Other metals are less often used as reinforcing fibres at the moment.

Properties of Composite Material

In the case of a composite material, the best mix of qualities is generally sought rather than a single attribute. For example, an aircraft's fuselage and wings must be lightweight while yet being robust, rigid, and durable. It is challenging to find a monolithic material that meets these characteristics. This combination of characteristics is seen in a number of fiber-reinforced polymers. Rubber is another example. Natural rubber is a brittle substance. It was found in the early 1900s that adding substantial quantities of carbon black (nearly pure carbon) to natural rubber boosted its strength considerably. The two elements combine to form a composite substance that is substantially stronger than each ingredient alone. To reach maximum strength, rubber must, of course, be vulcanised.

Rubber may be used as an addition in polystyrene. Brittleness is one of polystyrene's distinguishing and unfavourable qualities. While most other polymers have significant ductility, polystyrene has almost none. Rubber (natural or synthetic) may be used in small quantities (5% - 15%) to create high-impact polystyrene, which has much higher toughness and impact strength. Three elements influence the properties of a composite material: (1) the materials employed as component phases in the composite, (2) the geometric forms of the components and the resultant structure of the composite system, and (3) the method in which the phases interact with one another.

The Mixture Rule a composite material's qualities are determined by the initial ingredients. Certain attributes of a composite material may be calculated using a mixtures rule, which entails taking a weighted average of the component material properties.

Carbides Cemented Carbides are made up of one or more carbide compounds that are bound together in a metallic matrix. Even though it is theoretically valid, the name cermet is not used for all of these materials. Wrought iron carbide (WC), titanium carbide (TiC), and chromium carbide are the most prevalent cemented carbides (Cr_3C_2). Tantalum carbide (TaC) and other materials are also used, although less often. Cobalt and nickel are the primary metallic

binders. We already mentioned carbide ceramics (Section 7.3.2); they are the main constituent in cemented carbides, often accounting for 80% to 95% of total weight.

Particulate processing procedures are used to create cemented carbide component). Cobalt is a typical binder for WC, while nickel is a binder for TiC and Cr₃C₂. Even though the binder accounts for just 5% to 15% of the total weight of the composite material, its impact on mechanical characteristics is substantial. In the case of WC-Co, as the proportion of Co increases, hardness decreases but transverse rupture strength (TRS) increases. TRS correlates with WC-Co composite toughness. Cutting tools are the most typical use for tungsten carbide-based cemented carbides. Other uses for WC-Co cemented carbides include wire drawing dies, rock-drilling bits and other mining equipment, powder metallurgy dies, hardness tester indenters, and other applications where hardness and wear resistance are required.

Titanium carbide ceramics are primarily employed in high-temperature applications.

Nickel is the favoured binder because it is more resistant to oxidation at high temperatures than cobalt. Gas turbine nozzle vanes, valve seats, thermocouple protection tubes, torch tips, and hot-working spinning tools are examples of applications TiC-Ni is also employed in machining processes as a cutting tool material. Nickel-bonded chromium carbides are more brittle than WC-Co cemented carbides, but they have superior chemical stability and chemical resistance. This combination, along with its high wear resistance, makes it appropriate for gauge blocks, valve liners, spray nozzles, and bearing seal rings.

Cermets based on oxidation the majority of these composites employ Al₂O₃ as the particulate component; MgO is another oxide which is occasionally utilised. Chromium is a typical metal matrix, however other metals may also be employed as binders. The relative quantities of the two phases vary greatly, with the metal binder being the most important component. Cutting tools, mechanical seals, and thermocouple shields are examples of applications.

Fiber-Reinforced Metal Matrix Composites

These MMCs are interesting because they combine a fiber's high tensile strength and modulus of elasticity with metals of low density, resulting in a composite material with excellent strength-to-weight and modulus-to-weight ratios. Aluminum, magnesium, and titanium are common low-density matrix metals. Al₂O₃, boron, carbon, and SiC are some of the major fibre components employed in the composite. Fiber-reinforced MMCs have anisotropic properties, as predicted. Continuous fibres tightly attached to the matrix metal achieve maximum tensile strength in the chosen direction. The elastic modulus and tensile strength of the composite material rise as fibre volume increases. MMCs with fibre reinforcement provide excellent high-temperature strength and electrical and thermal conductivity. The majority of applications have been components in aircraft and turbine gear, where these features may be utilised.

Ceramic Matrix Composites

Ceramics offer many appealing qualities, including high stiffness, hardness, hot hardness, and compressive strength, as well as a low density. Ceramics also have various flaws, including poor toughness and aggregate tensile strength, as well as thermal cracking susceptibility. Ceramic matrix composites (CMCs) are an effort to keep ceramics' beneficial qualities. While compensating for their limitations. CMCs are made up of a ceramic primary phase embedded in a secondary phase. Too far, the majority of research has been on the utilisation of fibres as the secondary phase. Success has eluded me. The thermal and chemical compatibility of the

ingredients in CMCs during processing is one of the technical challenges. Furthermore, like any other ceramic material, component geometry constraints must be addressed.

Alumina (Al_2O_3), boron carbide (B_4C), boron nitride (BN), silicon carbide (SiC), silicon nitride (Si_3N_4), titanium carbide (TiC), and other kinds of glass have all been utilised as matrices. As CMC matrices, several of these materials are currently in the development stage. Carbon, SiC, and Al_2O_3 are some of the fibre materials used in CMCs.

In modern CMC technology, the reinforcing phase comprises of either small fibres, such as whiskers, or long fibres. Short fibre products have been effectively manufactured employing particle processing techniques with the fibres being treated as a powder in these materials. Although employing long fibres as reinforcement in nanocomposites offers performance benefits, developing cost-effective processing procedures for these materials has proved problematic. As demonstrated in the figure, one prospective commercial use of CMCs is in metal-cutting tools as a rival to cemented carbides. The composite tool material has whiskers of SiC in an Al_2O_3 matrix. Various possible uses include high temperatures and chemically corrosive conditions for other materials.

Polymer Matrix Composites

A polymer matrix composite (PMC) is made up of a polymer primary phase with an embedded secondary phase in the form of fibres, particles, or flakes. PMCs are the most significant commercially of the three types of synthetic composites. Most plastic moulding compounds, rubber reinforced with carbon black, and fiber-reinforced polymers are among them (FRPs). FRPs are most closely associated with the word composite. When a design engineer hears the phrase "composite material," FRP is generally the first thing that springs to mind. Our composite materials and production video clip gives an overview into fiber-reinforced polymer composites.

Polymers with Fiber Reinforcement

A fiber-reinforced polymer is a composite material made up of a polymer matrix and high-strength fibres. The polymer matrix is often a thermosetting material like unsaturated polyester or epoxy, although thermoplastic polymers including nylons (polyamides), polycarbonate, polystyrene, and polyvinylchloride are also utilised. Furthermore, fibres are used to strengthen elastomers in rubber goods such as tyres and conveyor belts. PMC fibres may be discontinuous (chopped), continuous, or woven into a fabric. Glass, carbon, and Kevlar 49 are the most common fibre materials used in FRPs. Boron, SiC, Al_2O_3 , and steel are less frequent fibres. Glass (especially E-glass) is the most frequent fibre material in today's FRPs; it has been used to strengthen plastics since approximately 1920.

The phrase "advanced composites" refers to FRPs produced since the late 1960s that include boron, carbon, or Kevlar as reinforcing fibres. The most prevalent matrix polymer is epoxy. These composites typically have a high fibre content (>50% by volume) and a high modulus of elasticity. A hybrid composite is formed when two or more fibre components are mixed in a FRP composite.

Hybrids' advantages over traditional or advanced FRPs include balanced strength and stiffness, enhanced toughness and impact resistance, and decreased weight. Aerospace applications make use of advanced and hybrid composites. The most common kind of FRP is a laminar structure, which is created by stacking and connecting small layers of fibre and polymer until the appropriate thickness is achieved. A certain amount of anisotropy in characteristics may be

obtained in the laminate by altering the fibre orientation among the layers. This technology is used to create thin-section elements like as aircraft wing and fuselage sections, car and truck body panels, and boat hulls.

Properties A variety of appealing characteristics differentiate fiber-reinforced plastics as engineering materials. The most noticeable features are (1) a high strength-to-weight ratio. Composite material categorization system is based on the matrix phase. The classes are listed here.

1. Metal Matrix Composites (MMCs) are composites made of ceramics and metals, such as cemented carbides and other cermets, as well as aluminium or magnesium reinforced by strong, high-strength fibres.

The second most prevalent group is Ceramic Matrix Composites (CMCs). Aluminum oxide and silicon carbide are two materials that may be embedded with fibres to enhance their characteristics, particularly in high-temperature applications.

Composites using Polymer Matrix (PMCs). Thermosetting resins are the most common polymers utilised in PMCs. Epoxy and polyester are often blended with fibre reinforcement, whereas phenolic is used with powders. Thermoplastic moulding compositions are often reinforced, most commonly using powders.

The categorization may be used to both conventional and synthetic composites. Asphalt and wood are polymer matrix composites, but concrete is a ceramic matrix composite. In the composite, the matrix material fulfils many purposes. First, it offers the bulk form of the composite material component or product. Second, it keeps the embedded phase in situ by enclosing and often obscuring it. Third, when a load is applied, the matrix shares the burden with the secondary phase, deforming in certain situations such that the stress is borne mostly by the reinforcing agent.

Casting Process

Casting is the method of making a machine component by heating a metal or alloy over its melting point and pouring the liquid metal/alloy into a cavity that is about the same shape and size as the machine part. When the liquid metal cools and solidifies, it takes on the form and size of the cavity and mimics the desired end product. The foundry is the workshop section where castings are created.

A casting is made by: (a) preparing a pattern, (b) preparing a mould with the help of the pattern, (c) melting metal or alloy in a furnace, (d) pouring molten metal into mould cavity, (e) breaking the mould to retrieve the casting, (f) cleaning the casting and cutting off risers, runners, etc., (g) inspecting the casting.

Castings are produced in a wide range of ferrous and non-ferrous metals and alloys. Grey cast iron components are widely utilised; steel castings are stronger and used for components subjected to greater loads. Bronze and brass castings are utilised aboard ships and in maritime environments where ferrous goods may corrode rapidly. Automobiles employ aluminium and aluminum-magnesium castings. Cutlery pieces are made from stainless steel castings. Casting is a cost-effective method of creating components of a certain form in small or large quantities. Castings, on the other hand, are less sturdy than wrought components created by procedures such as forging and so on. However, castings allow for somewhat better properties in certain areas of

the casting using procedures like as the application of chill, for example. Very little metal is wasted during the casting process.

Patterns

Patterns are exact duplicates of the casting needed

It is about the same shape and size as the finished product. Typically, the mould is created in wet sand with a binder added to keep the sand particles together. The pattern is then removed from the sand mould in such a way that the impression/cavity formed in the mould is not damaged or destroyed. Finally, molten material into the hollow, where it solidifies and cools to room temperature.

CHAPTER 8

Allowances for Patterns

Mr. Dipendra Kumar, Associate Professor, Department of Mechanical Engineering,
School of Engineering & Technology, Jaipur National University, Jaipur, India.

Email Id-dipendra1987@jnujaipur.ac.in

Because most metals decrease in volume after solidifying from a liquid condition and again when cooling, the design should be somewhat bigger than the completed casting size. This discrepancy in pattern size is known as shrinking allowance. This allowance is 1% for cast iron and about 1.6% for aluminium.

Castings manufactured in the foundry shop are often machined afterwards. The goal of machining is to get precise dimensions and a higher surface quality on the component. If this is the case, a 1.5-2.5 mm thick coating of material must be given all around the casting. This is accomplished by making the design slightly larger than the casting. The term "machining allowance" refers to this increase in pattern size.

Draft allowance is another essential provision granted on patterns. It makes it easier to remove the pattern from of the mould. It is available on vertical surfaces. The objective is to provide vertical surfaces a 2-3 degree inclination so that when lifting the pattern, the top surface is broader and removing the pattern with the draught given does not harm the sand mould. Draft is given on inner building facades in such a manner that the top surface is smaller and the bottom half of the pattern is broader.

Aside from the tolerances mentioned above, certain extra allowances are frequently granted to compensate for intrinsic casting distortion or bending. When creating a pattern, sharp edges and bends are also radiused. Patterns are often constructed of high-quality wood. Wood is simple to work with, has a smooth surface, and keeps its size when properly seasoned. It is also quite inexpensive and plentiful. Metal patterns, on the other hand, may be employed if a large number of castings are needed. They are often constructed of aluminum-magnesium alloys.

Pattern Styles

Solid or single piece pattern: These patterns are manufactured in a single piece and are only appropriate for extremely basic castings. There is no provision for runners or risers, for example. Moulding may be done on the foundry floor (referred to as pit moulding) or in a moulding box. The design is easy to remove from the mould since the widest part of the pattern is at the top. For instance, if a cylindrical pin with a round head to be cast, the one-piece design

Piece no. 0 in one moulding box will make one-half of the imprint in the mould, and piece no. two in a second moulding box will make the other half of the impression. After removing the pattern halves from their respective moulding boxes, the two boxes will be joined and secured together so that the whole imprint is ready for metal pouring. The two pattern halves are equipped with locating dowels, allowing one half to sit on the other in the precise location necessary with

no mismatch. Each portion also has two tapped holes on the flat mating surface. These tapped holes serve as a grip for lifting the pattern halves from the sand without harming the mould imprint.

The line that divides the pattern into half is known as the "parting line," and it generally follows the casting's largest cross-section. Choosing where to draw the separating line requires great expertise and experience.

Some of the more intricate castings may need splitting the design into three or more sections.

Loose piece pattern: The casting may include minor projections or overhanging parts in certain circumstances. These protrusion make removing the design from the mould difficult. As a result, these projections are constructed in bits. They are loosely linked to the main body of the design, and the mould is constructed as normal.

When the main pattern is removed from the mould, some loose parts fall out and stay in the mould. The loose parts are removed once the top part of the design has been removed.

Match plate design: A match plate is a metal plate that is often composed of aluminium. The split pattern's two parts are placed on this match plate, one on each side. Care is taken to ensure that there is no mismatch while attaching them to the match plate. These patterns are used in combination with moulding equipment that are mechanically driven. The bottom portion of the mould imprint in one moulding box is made using the bottom side of the match plate template (known as the drag). In another moulding box, the top side of the match plate design is utilised to make the mould imprint. Finally, the two moulding boxes are stacked on top of each other, with the bottom box known as the drag and the top box known as the cope.

Gated patterns: When a pattern for a casting is created, additional component is often included so that when the impression is formed in the moulding box, the cavity has a shallow channel in addition to the primary cavity for the item to be cast. This duct, known as the "gate," will be utilised to feed molten metal into the main cavity. Gated patterns are patterns that have been designed with gating in mind. It eliminates the need to create a gate individually.

Other patterns include skeleton patterns, sweep patterns, and segmental patterns, among others. The whole pattern is not created in these designs, and the mould is finished using an improvised pattern. This is done to lower the cost of pattern creation. If just one or two moulds are to be manufactured, this process is used.

Sand for Moulding and Its Properties

Sand is used in foundries to make moulds. Although high grade silica sand is mined, natural sand found on the bed and banks of rivers provides an ample supply. Sand is chemically SiO₂ - silicon dioxide in the form of granules. Aside from silica grains, ordinary river sand includes clay, moisture, non-metallic contaminants, and traces of magnesium and calcium salts. This sand is used to make moulds once it has been properly treated. A good moulding sand should contain the following characteristics:

Refractoriness, or the ability to withstand high temperatures.

Permeability, or the ability to flow gases, water vapour, and air through it.

Green sand strength, i.e., when a mould is produced using wet sand, it must be strong enough to prevent the mould from breaking.

Good flowability, which means that when it is packed around a pattern in a moulding box, it should be able to cover all nooks and corners, or else the imprint of the pattern in the mould will be blurry.

Good collapsibility, i.e., it should collapse readily after cooling and extraction after breaking the mould. It is especially critical when creating cores.

Sand grain cohesiveness, or the capacity of sand grains to adhere together. The moulds will be weak if they lack cohesion.

Adhesiveness, or the capacity of sand to adhere to other bodies. If the moulding sand does not adhere to the walls of the moulding box, the whole mould will slide through.

Permeability, cohesiveness, and green strength are all affected by the size and form of the sand grains, as well as the binding substance and moisture content of the sand. Clay is a natural adhesive. If the clay content of natural sand is insufficient, chemical binders such as bentonite are occasionally used.

Foundrymen developed standard methods to assess sand characteristics. Fresh moulding sand created in the foundry typically has the following composition:

1. 75% Silica (approx.)
2. Clay 10–15%
3. 2-5% Bentonite (as required)
4. 5-10% coal dust
5. Moisture 6–8%

The major binding ingredient in core sand is oil. A core is encircled by molten metal, causing the oil to vaporise. This promotes sand collapsibility and helps removing sand from casting holes easier.

Technique for Making Moulds

Mould manufacturing is a highly skilled craft. We will walk you through the process of manufacturing a split pattern mould, step by step:

Step 1: Place the bottom half of the divided pattern on a flat moulding board, parting surface down. Parting sand should be applied to the design and the moulding board. Parting sand is silica sand that does not include any clay or binding substance. Then, to encompass the design, put a moulding box.

Step 2: Spread facing sand over the whole design to a depth of 20-25 mm. Facing sand is moulding sand that has been newly prepared. Backing sand should be used to fill the leftover space in the moulding box. Backing sand is made by reconditioning previously used foundry sand, which is constantly on hand on the foundry floor. The use of backing sand eliminates the need for expensive face sand.

Step 3: A specific instrument is then used to drive the sand in the moulding box. Ramming is the process of gently pounding the sand down. Sand should be placed snugly but not too tightly in the moulding box. If the level of sand in the box falls as a consequence of ramming, additional sand should be placed in and slammed. Then, using a trowel, level the sand on top of the mould

box. Next, using a venting tool (a long, thick needle), cut venting holes in the sand, being careful not to go so deep as to contact the design. This moulding box, known as "drag," will produce the bottom box.

Step 4: After levelling the foundry floor, carefully flip the moulding box over and place it on some loose sand. Place the top half of the split pattern in the right relative location on the bottom half of the pattern's flat surface. Drag another empty moulding box on top of the previous moulding box and temporarily attach them together. Parting sand should be sprinkled across the exposed surface of the upper half of the design and the surrounding sand. Cover the design with facing sand that is 20-25 mm deep. Place two taper pins in the appropriate locations for the runner and riser. Fill the box with backing sand, compress it in with a ramming tool, level the sand, and drill vent holes. Remove the taper pins and create space on the foundry floor, close to the drag box, for the "cope," as the top box is known. Unclamp the moulding boxes, then raise the 'cope' and set it on its back. Now you can see the smooth separating surface of both portions of the split pattern, one in each box.

Step 5: To raise the patterns from the cope and drag, find the tepped holes on the flat surface and screw in a lifting rod. This offers a handle for effortlessly lifting the patterns vertically. However, before raising the handles, the patterns are loosen somewhat by gently knocking them. This reduces the risk of sand mould damage.

Step 6: After removing the wooden pattern halves, the mould cavities may be repaired if any corners or other details are broken. This is a sensitive procedure. In addition, any sand that has fallen into the mould cavity is carefully raised or blown away by an air stream.

Step 7: If any cores were used to form holes in the casting, now is the time to insert the cores into the mould cavity. Of course, the cores are appropriately supported by core prints or other devices such as chaplets, etc. When the liquid metal is pumped in, cores that are not adequately supported may be displaced from their right location.

Step 8: Graphite powder is spread on the mould surface in both boxes before to sealing. A gate is cut below the runner's placement in the drag box (in the cope box). The molten metal will flow through the gate into the mould cavity after being put into the runner.

If the moulds have been dried, a mould wash comprising a suspension of graphite in water is softly applied over the mould surface instead of graphite powder.

After all of these processes are completed, the cope box is repositioned on the drag and tightly secured. The mould is now ready for the pouring of molten metal. Molten metal is poured till it reaches the riser. It guarantees that the mould cavities are full with metal and that the metal does not flow out. Sand moulds are classified into three types:

- (a) Green sand mould: This kind of mould is used for pouring molten metal while the sand is still damp.
- (b) Skin dry moulds: These moulds are superficially dried by passing a flame over the cavity of the mould, allowing the mould to dry only to a few millimetres depth.
- (c) Dry moulds: After creating such moulds, they are dried by storing the mould in an oven with a temperature of 130-150°C for 24-36 hours. Dry sand moulds are stronger and cannot cause moisture-related casting problems. Mould wash increases casting surface smoothness.

Cores

When a hole, recess, undercut, or internal cavity is needed in a casting, a core formed of a refractory substance such as sand is introduced at the desired position in the mould cavity before ultimately sealing the mould. A core should be able to endure high temperatures since it is surrounded on all sides by molten metal. It should also be suitably supported, otherwise it will be moved owing to the buoyancy of molten metal.

The core should give way when the molten metal surrounding the core solidifies and shrinks; otherwise, the casting may split (hot tear). As previously stated, cores should be produced of oil sand and dried in ovens before usage. Core boxes are used to create cores. Core boxes are constructed of wood and have a hollow carved into them to accommodate the core's form and size. The sand has been blended and placed in the core boxes. Then it is jammed. A core box is divided into two parts, with each side containing a half imprint of the core. A core may need reinforcements at times to keep it together. The reinforcements are in the form of wire or nails, which may be retrieved from the casting hole with the core sand.

Core Prints

A core must be supported in the cavity of the mould. This is accomplished whenever feasible by giving core printouts. Core prints comprises extensions of the core that rest in analogous extensions of the mould cavity, allowing the core to stay sustained in the mould cavity without dropping to the cavity's bottom.

Risers, Runners, and Gates

The gating system is the path in the mould via which molten metal flows into the mould cavity. It is created by scooping sand into the drag box and cutting the appropriate channels. The top of the cope's runner hole has been expanded to create a pouring basin. The molten metal then runs down the runner into a well, where it enters the gating system and the mould cavity. The riser hole is linked at a suitable place inside the mould cavity.

Without the barrier, the metal would have fallen directly into the mould cavity, causing damage. Furthermore, the gated system is intended to prevent contaminants from entering the mould cavity. The riser has two functions.

For starters, it serves as a visual signal that the mould chamber is filled. Second, and more crucially, the molten metal in the riser acts as a reservoir to feed the shrinkage that occurs when the casting solidifies and cools. The metal with in riser should be kept molten for as long as feasible. This is accomplished by offering a "hot-top".

Cupola

Metal must be heated well beyond its melting point in order to be cast. A furnace is used to heat the house. Furnaces may be categorised as electric, oil-fired, or coal-fired, depending on the fuel utilised. Electric kilns are used to produce metal that is free of impurities. The flame interacts with the hot metal in oil and coal powered furnaces, and the molten metal takes up impurities by coming into touch with flames. Electric furnaces are expensive to purchase and run.

Oil-fired crucible furnaces are often used for nonferrous metals and alloys. The metal is put in enormous graphite cauldrons and heated on the outer surface of the crucibles so that no flames come into direct contact with the metal.

Construction

A cupola furnace is used to melt cast iron. It is one of the most cost-effective and easy methods of obtaining molten cast iron. Cockpit canopy is powered by coke. Coke is made by heating conventional steam coal inside of an inert environment. It produces more heat than coal. The cupola is made out of a hollow tubular steel shell with a refractory fire-brick inside. It is built vertically and rests on small pillars around 0.85 metres above ground. The cupola's bottom is equipped with steel doors that are coated with fire-resistant material and topped with a layer of high-quality sand.

A suitable height opening is built towards the top of this steel shell for charging fuel and commodities into the furnace. Mostly one metre above the bottom closing doors, a wind box with a motorised blower is attached. This wind box produces little air tubes.

To aid in the combustion of fuel, air is introduced into the cupola shell. These air tubes are known as tuyeres. A tapping spout is provided at the bottom, above the door, to tap molten metal, and a slag hole is provided at the back of the cupola, roughly 350 mm above the tapping hole, through which fluid slag may be forced out under air pressure. The cylindrical space between the tap hole and the slag hole where molten metal gathers between two taps is known as the molten metal well.

Cupola Operation

The first operation in the cupola is to repair the lining of the entrance and the area surrounding it before shutting the hinged doors. Doors are wedged shut, making it impossible for them to open while the cupola is in use. The fire is then lit at the bottom using some wood and kerosene oil rags. When the fire is hot, coke is fed from the top charging door until the height of the coke bed reaches approximately half a metre above the tuyeres. Following that, the tuyeres are partly opened, the air blower is turned on, and alternating layers of metal, flux (in the form of limestone fragments), and coke are charged from the top. These alternating layers settle into a coke bed. When the cupola is filled to the charging door level, the tuyeres are completely opened and the heating of charge starts.

The coke close to the tuyeres begins to burn, and the coke bed gets very hot. The metal in the lower layers near the coke bed begins to melt. Limestone is composed of CaO and CO_2 . Calcium oxide interacts with impurities such as silica and other oxides to generate slag (CaSiO_3). Slag is lighter than water and floats on top of the molten metal layer. When enough metal has melted, the slag is blasted out via the slag hole. The metal is then tapped by inserting a long steel rod with one end fashioned like a cone into the tap hole. The molten metal will begin to flow down the metal chute, where it will be gathered into ladles (refractory coated steel buckets with long handles) and hauled away for pouring into moulds. The tap hole is then sealed up with a piece of fire clay.

Cast iron's characteristics increase when modest quantities of ferro manganese and ferro silicon are added. Because the majority of the manganese and silicon already present in scrap cast iron, pig iron, and a small amount of thin steel scrap that forms the metallic charge fell into the cupola is oxidised and lost, ferro manganese and ferro silicon must be added to the molten metal in the ladles prior to pouring.

Extra coke is charged into the cupola with the final charge once the day's work is completed. After all of the metal has melted, the air blower is turned off and the cupola's bottom door is

opened. Whatever remains unburned coke, etc., is permitted to fall to the earth under the cupola door. This is required because otherwise the leftover coke, slag, metal, and so on would clump together and become exceedingly difficult to remove. The inside diameter of a cupola indicates its size.

Defects in Casting

The following are some of the most prevalent casting defects:

1. **Blow-holes:** These are little holes that emerge in the casting. They might be open to the surface or below the surface of the casting. They are caused by imprisoned gas bubbles. They could
Excessively hard ramming, incorrect venting, excessive moisture, or a lack of permeability in the sand may all cause this.
2. **Shrinkage cavity:** A shrinkage cavity may be formed at the junction of two very thick and thin sections of a casting due to faulty design. The shrinkage cavity is entirely internal.
It is induced by molten metal shrinkage. The solution is to employ either a chill or relocation of
3. **Misrun:** Incomplete filling of the mould cavity. It might be caused by bleeding of the molten metal at the splitting of cope and drag, insufficient metal supply or incorrect design of gating.
4. **Cold shut:** A cold shut is generated inside a casting when molten metal from two distinct streams comes into contact but does not completely fuse. The fundamental source of this problem might be a low pouring temperature.
5. **Mismatch:** This problem occurs when the mould impressions in the cope and drag are slightly moved from one another. This is caused by a mismatch in the split pattern (a dowel pin may have fallen loose) or by faulty clamping of the cope and drag boxes.
6. **Drop:** This occurs when a piece of mould sand falls into the molten metal. This flaw might be caused by loose sand that was not properly pushed or a lack of binder.
7. **Scab:** This flaw develops when a part of the face of a casting lifts or breaks down, allowing molten metal to fill the recess.
8. **Hot tear:** These fractures form in thin long portions of the casting when the part of the casting cannot shrink freely on cooling owing to too densely packed intervening sand, and provides resistance to such shrinking. The rip or fracture generally takes place while the component is red hot and has not achieved full strength, so the fault is termed "hot tear". The cause might be extremely tight sand ramming.
9. Other flaws include scars, blisters, sponginess (owing to a cluster of pin holes in one spot), and slag inclusions, among others.

Casting Dies

A sand mould can only be used to make one casting. It cannot be used more than once. A die is simply a metal mould that can be reused. A die is often formed in two halves. One part is fixed, while the other is mobile. They encompass the mould cavity in all of its complexities. Molten metal is fed into the dies after clamping or sealing the two parts of the dies together. The

procedure is known as gravity die casting if the molten metal is fed into the dies by gravity. If, on the other hand,

The procedure is known as "pressure die casting" because the metal is pushed into the dies under pressure (for example, a piston in a cylinder forces the material through a cylinder nozzle). The material used to make the dies should have a substantially higher melting point than the casting material. Many die castings are constructed of zinc, tin, and lead alloys, as well as aluminium, magnesium, and copper alloys. As a result, dies are built of medium carbon low alloy steels. The dies are typically cooled by water or air blast. Because most materials shrink as they cool, removing castings from dies is critical; otherwise, they will get entangled in the die as they cool. As a result, some provision for casting extraction is included in the design of dies.

Die Casting Steps

1. After covering the mould cavity surfaces with a mould wash, close and lock the two sides of a die:
2. Inject the molten metal into the die under pressure.
3. Continue to apply pressure until the metal solidifies.
4. Separate the die halves.
5. Eject the casting, as well as the runner, riser, and so on.
6. The preceding cycle is repeated.

There are two pressure die casting processes used:

1. Hot chamber process: For zinc, tin, lead, and their alloys, pressures of up to 35 MPa are employed. The chamber in which molten metal is held before being pressure injected into the die is maintained warm throughout this procedure.
2. Cold chamber procedure: High pressures of up to 150 MPa are employed in this process. The storage compartment is unheated. This procedure is mostly utilised for metals and alloys with comparatively higher melting points, such as aluminium, magnesium, and their alloys.

Die casting benefits and disadvantages:

1. It is employed in the mass manufacturing of small and medium-sized castings. For example, pistons from motorcycle and scooter engines, valve bodies, carburettor housings, and so on.
2. The initial cost of producing a die is quite expensive. It is a drawback.
3. This method yields high-quality, defect-free castings.
4. This procedure produces castings with high surface polish and dimensional control that may not need considerable machining. Every casting that is made is the same.
5. This method is incapable of producing large-scale castings. It is a drawback.
6. Die casting is difficult to manufacture castings with particularly complicated forms or multiple cores.
7. Castings may be made inexpensively in the event of mass manufacturing.
8. The procedure does not need the use of sand and takes up considerably less room than a traditional foundry utilising sand mound

Fundamentals of Metal Casting

Casting is a technique in which molten metal flows into a mould by gravity or other force and hardens in the form of the mould cavity. The component produced by this procedure is

sometimes referred to as casting. It dates back 6000 years and is one of the earliest shaping processes. The casting concept seems simple: melt the metal, pour it into a mould, and let it to cool and solidify; yet, several aspects and variables must be addressed in order to complete a successful casting process.

Casting encompasses both ingot casting and form casting. The word ingot is often connected with the primary metallurgy industries; it refers to a big casting with a basic form that is designed for further reshaping by operations such as rolling or forging. In Chapter 6, we spoke about ingot casting. Form casting entails creating more complicated geometries that are considerably closer to the ultimate intended shape of the component or product. This and the next chapters are focused with the casting of forms rather than ingots. There are several form casting techniques available, making it one of the most adaptable production processes. The following are some of its capabilities and advantages:

Casting may produce complicated component geometries with both exterior and interior forms.

Some casting methods may produce pieces that have net form. There are no additional manufacturing activities needed to attain the appropriate geometry and dimensions for the components. Other casting procedures are near net form, which need some further shape processing (typically machining) to get correct dimensions and features.

Casting may be used to make very big pieces. More than 100 tonnes of castings have been produced. Any metal that can be heated to a liquid condition may be used in the casting process. Some casting technologies lend themselves well to mass manufacturing.

There are additional drawbacks to casting, with various drawbacks for different casting processes. These include mechanical property restrictions, porosity, poor dimensional accuracy and surface polish for various casting techniques, human safety dangers when working with hot molten metals, and environmental issues. Casting parts varies in size from little components weighing a few ounces to extremely big items weighing tonnes. Dental crowns, jewellery, statuary, wood-burning stoves, engine blocks and heads for motor vehicles, machine frames, railway wheels, frying pans, pipes, and pump housings are among the items available. Metals of all types, ferrous and nonferrous, may be cast.

Casting may also be employed on other materials such as polymers and ceramics; however, the specifics are sufficiently different that we will explore these materials' casting procedures in subsequent chapters. This and the next chapters are entirely dedicated to metal casting. In this section, we will go over the principles that apply to almost all casting processes.

Processes of Casting

The mould is the appropriate starting point for any discussion of casting. The form of the cast component is determined by the geometry of the cavity in the mould. The actual size and form of the cavity must be somewhat bigger to account for metal shrinkage during solidification and cooling. Because various metals shrink at different rates, the mould cavity must be built for the specific metal to just be cast if dimensional accuracy is required. Molds are created from many materials such as sand, plaster, ceramic, and metal. The numerous casting techniques are often grouped based on the different kinds of moulds.

To begin a casting procedure, the metal is heated to a high enough temperature to totally turn it into a liquid condition. It is then poured or otherwise guided into the mold's cavity. The liquid metal is simply poured into an open mould, until it fills the open cavity shows a closed mould

with a tunnel called the gating system that allows molten metal to flow from outside the mould into the cavity. In production casting processes, the closed mould is by far the most significant type.

The molten metal starts to cool as soon as it enters the mould. Solidification starts when the temperature decreases enough (for example, to the freezing point of a pure metal). The metal's phase changes during solidification. It takes time to accomplish the phase shift, and a lot of heat is lost in the process. During this stage of the process, the metal adopts the solid form of the mould cavity and many of the casting's qualities and characteristics are defined. When the casting has sufficiently cooled, it is taken from the mould. Additional processing may be necessary depending on the casting technique and metal utilised. Trimming surplus metal from the actual cast item, polishing the surface, checking the result, and heat treating to improve qualities are all possible. Furthermore, machining may be necessary to attain tighter tolerances on certain component features and to remove the cast surface.

Casting procedures are classified into two types based on the kind of mould used: expendable-mold casting and permanent-mold casting. To remove the casting from an expendable mould, the mould in which the molten metal solidifies must be destroyed. These moulds are composed of sand, plaster, or similar materials, and their shape is kept by applying different binders. The most visible example of an expendable-mold method is sand casting. Sand casting involves pouring liquid metal into a sand mould. To retrieve the casting when the metal solidifies, the mould must be sacrificed.

A permanent mould is one that may be used again to make multiple castings. It is constructed of metal (or, less typically, a ceramic refractory material) that can resist the high temperatures of the casting process. The mould in permanent-mold casting is made up of two (or more) portions that may be opened to allow the final object to be removed. Die casting is the most well-known method in this category.

Casting geometries with more complicated casting geometries are typically attainable using expendable-mold methods. The necessity to open the mould limits part forms in permanent-mold techniques. On the other hand, certain permanent mould methods provide some cost benefits in high-volume operations.

Solidification of Metals

Metals that are pure a pure metal solidifies at a temperature constant equal to its freezing point, which is also its melting point. The melting points of pure metals, known as a cooling curve, are widely known and recorded. It takes time for the metal's latent heat of fusion to be released into the surrounding mould, which is referred to as the local solidification time in casting.

The total crystalline lattice time is the amount of time that elapses between pouring and final solidification.

Metals that are pure a pure metal solidifies at a temperature constant equal to its freezing point, which is also its melting point. The melting points of pure metals, known as a cooling curve, are widely known and recorded. It takes time for the metal's latent heat of fusion to be released into the surrounding mould, which is referred to as the local solidification time in casting.

The time elapsed between pouring and full solidification is referred to as the total solidification time. The cooling curve's slope is downward. A thin layer of solid metal is first formed due to the cooling action of the mould wall. Developed at the contact shortly after pouring. As

solidification moves inward toward the core of the skin, its thickness rises to create a shell around the molten metal. The pace of freezing is determined by heat transmission into the mould as well as the metal's thermal characteristics.

The production and development of metallic grains during the solidification process is of interest. The metal used to make the first skin has been quickly cooled due to heat extraction via the mould wall. Because of the chilling effect, the granules in the skin become fine and randomly aligned. As cooling proceeds, more grain formation and development occurs in the opposite direction of heat transmission. Because heat is transferred through the skin and mould wall, the grains develop inward as solid metal needles or spines. Lateral branches arise as these spines expand, and as these branches grow, further branches emerge at right angles to the initial branches. Dendritic development is a sort of grain growth that happens not only in the freezing of pure metals but also in alloys.

During freezing, new metal is constantly deposited onto the dendrites, progressively filling in the treelike formations until full solidification occurs. The grains formed as a consequence of this dendritic development have a favoured direction, with coarse, columnar grains oriented toward the centre of the casting. Figure 10.6 depicts the phase diagram for a specific alloy system and the cooling curve for a certain composition, which may be used to explain alloy solidification. As the temperature decreases, freezing starts at the liquidus temperature and continues until the solidus temperature is achieved.

The freezing process is comparable to that of pure metal. Because of the significant temperature difference at this area, a thin skin forms on the mould wall. The freezing process then continues as previously, with the production of dendrites that expand away from the walls. However, due to the temperature difference between the liquidus and solidus, the nature of the dendritic development results in the formation of an advance zone in which both liquid and solid metal coexist. The dendritic structures that have grown enough to capture tiny islands of liquid metal in the matrix are the solid sections. The mushy zone derives its name from the squishy quality of this solid-liquid area. Depending on the freezing conditions, the murky zone might be relatively limited or present for the majority of the casting. Factors such as delayed heat transport out of the heated metal and a large temperature differential between liquidus and solidus encourage the latter situation. As the temperature of the casting decreases to the solidus for the particular alloy composition, the liquid islands in the dendritic matrix harden gradually.

Another aspect that complicates alloy solidification is that the composition of dendrites as they develop favours the metal with the higher melting point. As the freezing process proceeds and the dendrites grow, an imbalance in composition arises between the frozen metal and the remaining liquid metal. This composition imbalance is eventually represented in the finished casting as element segregation. There are two forms of segregation: microscopic and macroscopic. The chemical makeup of each individual grain differs at the microscopic level. This is because the initial spine of each dendrite has a larger amount of one of the alloy's constituents.

As the dendrite develops in its immediate surroundings, it must use the remaining liquid metal, which has been somewhat drained of the initial component. Finally, the last metal to freeze in each grain is that caught by the dendrite's branches, and its composition is much more out of balance. As a result, the chemical makeup of the casting varies within single grains. The chemical composition fluctuates at the macroscopic level during the casting. Because the parts of the

casting that freeze first (at the exterior near the mould walls) are richer in one component than the other, the remaining molten alloy is deprived of that component by the time the interior freezes.

Solidification Time

Solidification takes time regardless of whether the casting is pure metal or an alloy. The total solidification time is the time it takes for the casting to harden after it has been poured. This time is determined by an empirical relationship known as Chvorinov's rule, which states: $TTS = \frac{V}{A} \sqrt[2]{\frac{C_m}{n}}$ total solidification time, min; V volume of the casting, cm³ (in³); A surface area of the casting, cm² (in²); n is an exponent usually taken to have a value of 4; and C_m is the mould constant. Given that $n = 4$, the units of C_m are min/cm² (min/in²), and its value depends on the casting operation's specific conditions, such as mould material (e.g., specific heat, thermal conductivity), thermal properties of the cast metal (e.g., heat of fusion, specific heat, thermal conductivity), and pouring temperature relative to the metal's melting point. Even though the geometry of the item is substantially different, the value of C_m for a specific casting operation may be based on experimental data from past operations carried out using the same mould material, metal, and pouring temperature.

According to Chvorinov's rule, a casting with a larger volume-to-surface area ratio cools and solidifies more slowly than one with a lower ratio. This approach is used in the design of the riser in a mould. The metal in the riser must stay in the liquid phase longer than the casting in order to accomplish its duty of supplying molten metal to the main cavity. To put it another way, the TTS for the riser must be greater than the TTS for the main casting. Because the mould conditions are the identical for both the riser and the casting, their mould constants will be the same. Using

216 By constructing the riser to have a greater volume-to-area ratio, we can be pretty certain that the main casting solidifies first and that the consequences of shrinkage are minimal. Before we get into how the riser may be constructed utilising Chvorinov's formula, let's talk about shrinkage, which is why risers are required.

Shrinkage

The significance of shrinkage during cooling and freezing has been overlooked in our consideration of solidification. Shrinkage happens in three stages: (1) liquid contraction before to solidification; (2) contraction during the phase shift from liquid to solid, known as solidification shrinkage; and (3) thermal contraction of the solidified casting during room temperature cooling. The three procedures may be shown using a cylindrical casting prepared in an open mould. Part (0) of the series depicts the molten metal shortly after pouring.

The height of the liquid is lowered from its beginning level due to contraction of the liquid metal while cooling from pouring temperature to freezing temperature, as shown in (1) of the figure. This liquid shrinkage is typically approximately 0.5%. Part (2) shows that solidification shrinkage has two impacts.

First, contraction reduces the height of the casting even more. Second, the quantity of liquid metal available to feed the casting's top centre piece is reduced. This is generally the last section to freeze, and the lack of metal causes a void in the casting. Foundrymen refer to this shrinkage cavity as a pipe.

When a casting is formed, it contracts in height and diameter as it cools, as seen in (3). This shrinkage is defined by the coefficient of thermal expansion of the solid metal, which in this instance is used in reverse to determine contraction.

Because the solid phase has a larger density than the liquid phase, practically all metals experience solidification shrinkage. The phase shift that occurs with solidification reduces the volume per unit weight of metal. The exception is high-carbon cast iron, whose solidification during the last stages of freezing is exacerbated by a period of graphitization, which results in expansion that tends to offset the volumetric drop associated with the phase transition. Depending on the casting technique, compensation for solidification shrinkage is accomplished in a variety of methods.

Risers are used in sand casting to provide liquid metal to the cavity under pressure, molten metal is applied in die casting. Patternmakers adjust for temperature shrinkage by enlarging mould cavities. The pattern shrinkage allowance is the amount by which the mould must be made bigger in relation to the final casting size. Although shrinkage is volumetric, casting dimensions are presented linearly, therefore allowances must be adjusted correspondingly. Special "shrink rules" with slightly enlarged scales are employed to create the patterns and moulds somewhat bigger than the required casting. Table typical linear shrinkage values for several cast alloys; these values may be used to calculate shrink rule scales.

Directional Solidification

To reduce the negative impacts of shrinkage, it is preferable for the sections of the casting most away from the liquid metal supply to freeze first, followed by solidification progressing from these remote parts toward the riser (s). As a result, molten metal will be accessible from the risers at all times, preventing shrinkage voids during freezing. This element of the freezing process and the technologies employed to manage it are referred to as directed solidification. The necessary directional solidification is accomplished by following Chvorinov's rule in the design of the casting itself, its orientation inside the mould, and the riser system that feeds it. For example, by situating areas of the casting with lower V/A ratios away from the riser, freezing will occur first in these regions, leaving the supply of liquid metal for the remainder of the casting open until these bulkier sections freeze.

Chills—internal or exterior heat sinks that generate fast freezing in certain sections of the casting—are another approach to enhance directed solidification. Internal chills are tiny metal bits that are inserted within the cavity before to pouring so that the molten metal solidifies around these objects first. The internal chill should have a chemical makeup comparable to the metal being poured, which is most easily accomplished by casting the chill from the same metal as the casting itself.

External chills are metal inserts in the mould cavity walls that may evacuate heat from the molten metal faster than the surrounding sand, promoting solidification. They are often utilised efficiently in casting areas that are difficult to feed with liquid metal, promoting quick freezing in these parts while the link to liquid metal remains open a hypothetical application of external chills as well as the anticipated outcome of the casting if the chill was not applied.

As vital as it is to commence freezing in the proper parts of the cavity, it is equally critical to prevent premature solidification in mould portions closest to the riser. The tunnel between the riser and the main cavity is of special relevance. This connection must be built such that it does

not freeze before the casting, isolating it from the molten metal in the riser. Although it is normally preferable to lower the volume of the connection (to prevent wasted metal), the cross-sectional area must be large enough to postpone the beginning of freezing. Making the route short in length helps to achieve this aim by absorbing heat from the liquid steel in the riser and the casting.

Lathe Machine

To reduce the detrimental consequences of shrinkage, it is preferable for the sections of the casting most away from the liquid metal supply to freeze first and for solidification to advance from these remote regions toward the riser (s). Molten metal will be continuously accessible from the risers in this manner, preventing shrinkage voids during freezing. The term directed solidification is used to describe this feature of the freezing process and the strategies employed to manage it. The necessary directional solidification is accomplished by following Chvorinov's rule in the design of the casting itself, its orientation inside the mould, and the design of the riser system that feeds it. For example, by situating areas of the casting with lower V/A ratios away from the riser, freezing will occur first in these regions and the supply of liquid metal for the remainder of the casting will stay open until these bulkier sections freeze.

Chills—internal or exterior heat sinks that generate fast freezing in certain sections of the casting are another method for encouraging directed solidification. Internal chills are tiny metal objects inserted within the cavity prior to pouring such that the molten metal solidifies first around these bits. The internal chill should have a chemical composition comparable to the metal being poured, which is most easily done by producing the chill out of the same metal as the casting itself.

External chills are metal inserts in the mould cavity walls that may transfer heat from the molten metal faster than the surrounding sand in order to facilitate solidification. They are often utilised efficiently in casting parts that are difficult to feed with liquid metal, facilitating quick freezing in these sections while the connection to liquid metal is still open a hypothetical use of external chills and the anticipated outcome in the casting if the chill was not employed. As vital as it is to commence freezing in the right portions of the cavity, it is equally critical to prevent early solidification in sections of the mould closest to the riser. The route between the riser and the main hollow is very dangerous. This connection must be built such that it does not freeze before the casting, which would isolate the casting from the molten metal in the riser. Although it is normally preferable to lower the volume of the connection (to prevent wasted metal), the cross-sectional area must be adequate to postpone the beginning of freezing. This purpose is frequently facilitated by having the route short in length so that it absorbs heat from the molten metal in the riser and the casting.

Headstock: It is attached to the extreme left side of the bed and includes lubricated shafts and gears. An electric motor powers the driving shaft within. The driven shaft, which is in the shape of a hollow spindle and may be driven at different speeds by changing gears, protrudes from the headstock. This spindle is screwed with a chuck (three or four jaw). The work piece may be held in the chuck's jaws. When the spindle spins, the chuck and the work item it is holding likewise revolve around the spindle's longitudinal axis.

Tailstock: At the right end of the bed, there is a tailstock. It may be moved closer to the headstock by sliding along the guide ways supplied on the bed. In such position, it may be clamped or secured to the bed.

The top component of the tailstock has a spindle whose axis aligns with the axis of the headstock spindle, both of which are at the same height above the bed. By spinning a hand wheel, this spindle may be moved forward or backward. The front of the tailstock spindle has a 'dead' or 'live' centre. When a long work piece is held in the chuck at the headstock end, the tailstock spindle is moved forward to support it at the tailstock end. Naturally, there must be a little conical hole in the centre of the work piece into which the tailstock centre may be put for support. A live centre is one that rotates with the work piece while being carried in its own bearings. However, if the tailstock centre stays stationary while the work piece spins alone, the centre is referred to as a 'dead centre,' and the conical tip of the centre must be greased with grease to decrease friction between the tailstock centre and the work piece.

The carriage is equipped with a cross slide that may travel independently in a transverse manner at right angles to the bed. The cross slide may also be operated manually or automatically by using a smaller hand wheel. A tiny slide called the compound rest (or tool post slide) is mounted on the cross slide and may be turned in a horizontal plane. At 0° rotation, its usual posture is parallel to the bed. The angle of rotation may be calculated with a protractor. This combination rest is used to place the tool for angular cuts during taper turning. The compound rest can only be moved manually. The cutting tool is held in place by the tool post, which is attached to the compound rest.

The gears, clutches, and other equipment necessary to move the carriage and cross slide, among other things, are concealed from view by an apron (thin steel plate) affixed to the carriage's front face. Half concealed in the front are two long shafts going from the headstock to the tailstock end (the screwed one is called the lead screw shaft/rod and the plain one is called the feed shaft/rod). These two shafts may be engaged one at a time to offer the carriage longitudinal movement. Only during the screw cutting process is a lead screw employed. Other processes, like as turning, make use of the feed shaft.

The distance between the headstock chuck and the tailstock centre determines the size of a lathe. This is the longest work that can be accommodated or manufactured on the lathe. Furthermore, the swing of the lathe is given (i.e., the vertical distance between the chuck centre and the lathe bed), since this is the radius of the greatest work item that may be turned on the machine.

Tools for Cutting On The Lathe

A chuck holds and secures the work piece in a centre lathe. If a component is made of round bar, the bar is fed through the hollow spindle of the headstock, and the needed length is drawn out and clamped in the jaws of the chuck, with the free end of the bar protruding towards the tailstock end. The tool is mostly moved from right to left. This is referred to as right hand functioning. It is sometimes required to work while moving tools from left to right, i.e., left hand working. The tools used for right hand lathe operations vary significantly from those used for left hand labour. They are, in reality, mirror reflections of one other.

Lathes are used for a variety of activities, including

1. Turning
2. Facing
3. Taper turning
4. Form turning or profile turning
5. Parting

6. Boring threading
7. Knurling.

Centering and Holding the Work Piece in the Chuck

Before any of the above-mentioned processes can be conducted on a lathe, all tasks must be properly fastened in the chuck and centred. A 3-jaws chuck is a self-centering device used for gripping round bars, among other things. A four-jaw chuck is used to clamp unevenly shaped tasks. In a four-jaw chuck, each jaw moves independently of the others. The centre line of the work material should roughly correspond with the centre line of the machine spindle. It is not enough to hold the job in the chuck centrally; the section of the work piece protruding from the chuck should also be centrally located. Other work piece holding devices include collet chucks, face plates, and so on.

Turning: The work piece is turned at an appropriate r.p.m. in this operation so that metal cutting may take place at the necessary cutting speed. If 'd' is the diameter of the work piece and N is the revolutions per minute, the cutting speed may be computed as $d.N$. A cutting tool is secured in the tool post with the tip at the same height as the centre of the work. The job rotates during the turning operation, and the cutting tool is introduced into the surface of the work piece by moving the cross slide, beginning at the right end of the work piece. The tool is steadily moved from right to left by moving the carriage on the machine bed, with a depth of cut of 1-1.5 mm.

The tool is fed. Feed is measured in mm/rev of work piece. Because the r.p.m. of the work piece is N, the feed per minute will equal N feed/revolution (mm).

Obviously, it may not be able to accomplish the necessary diameter reduction in one pass of the tool; the tool will have to be brought back to the right side, advanced by 1-1.5 mm by moving the cross slide, and then traversed from right to left. This technique will have to be performed multiple times until the required diameter is obtained.

The combined movement of the work piece and the tool produces a cylindrical form during the turning process.

In this procedure, the work piece is rotated as previously, but the tool is moved across by a cross slide. The carriage stays fixed in one location. As a consequence, a flat circular segment is produced at one end of the cylinder. During further machining processes, all lengths may be measured using this surface as a reference.

Taper Turning

Taper turning is the process of producing a conical surface by gradually decreasing the diameter as we go down the length of the cylinder. If the cutting tool travels along a path that is inclined to the longitudinal direction of the work piece rather than parallel to it, a conical surface will be generated. Swivelling compound rest for taper turning. The compound rest is swivelled, or turned in a horizontal plane by half cone angle, in this approach. The work piece is turned as normal, but instead of utilising the carriage to drive the tool ahead, the compound rest slide handwheel is used. Because the compound rest has been swivelled to an inclined position with regard to the lathe's longitudinal axis, the tool travels at an angle to the lathe's longitudinal axis, correctly producing a conical surface. Set above the tailstock centre:

The tailstock centre is relocated in this approach in a direction perpendicular to the machine's longitudinal axis. The tailstock base guide ways have some clearance and may be adjusted laterally on the machine bed to a limited extent.

Swivelling compound rest for taper turning

The compound rest is swivelled, or turned in a horizontal plane by half cone angle (θ), in this approach. The work piece is turned as normal, but instead of utilising the carriage to drive the tool ahead, the compound rest slide handwheel is used. Because the compound rest has been swivelled to an inclined position with regard to the lathe's longitudinal axis, the tool travels at an angle to the lathe's longitudinal axis, correctly producing a conical surface.

Set above the tailstock centre:

The tailstock centre is relocated in this approach in a direction perpendicular to the machine's longitudinal axis. The tailstock base guide ways have some clearance and may be adjusted laterally on the machine bed to a limited extent.

Form Turning or Profile Turning

The underlying idea of this lathe operation may be seen in the example of taper turning with a form tool. Other shapes, such as a given radius, semicircular shape, and so on, may be created in a similar fashion by using a properly shaped form tool and making a plunge cut (i.e., only cross slide will be used while carriage will remain locked in position). Form tools should have a low profile, otherwise the work piece and tool may shake and clatter.

Parting off: This process is carried out with the use of a parting tool. This also need a plunge cut? As the tool is fed in, the diameter of the work piece at the tool contact surface gradually decreases and becomes smaller and smaller. As the tip of the tool approaches the centre line of the work, the job will be divided into two parts, with the left hand portion remaining clamped in the chuck and the right hand piece of the required length separating off.

Boring: Boring is the process of expanding an existing hole. To begin drilling a hole on the lathe machine, remove the tailstock centre and put a drill into the tailstock spindle. The tailstock is moved closer to the work piece, which is rotated in the chuck. The drill is now progressed by turning the tailstock handwheel.

The advancing drill makes contact with the work piece's end face and drills a hole through it. The drill is removed when the hole has been dug to the necessary depth. A boring tool may then be used to extend the diameter of this hole.

CHAPTER 9

Making of Molds

Mr. Sanjeet Kumar,
Assistant Professor, Department of Mechanical Engineering,
School of Engineering & Technology, Jaipur National University, Jaipur, India,
Email Id- sanjeet.kumar@jnujaipur.ac.in

Foundry sands are composed of silica (SiO_2) or silica combined with other minerals. The sand should have strong refractory qualities, or the ability to withstand high temperatures without melting or otherwise deteriorating. Other critical characteristics of sand include particle size, grain size distribution in the combination, and grain shape. Smaller crystallite size gives the cast item a superior surface polish, whereas big grain size is more porous (to allow escape of gases during pouring). Molds created from irregularly shaped grains are stronger than moulds formed from round grains due to interlocking, although interlocking restricts permeability.

The sand grains are kept together in the mould by a combination of water and bonding clay. A common combination is 90% sand, 3% water, and 7% clay (by volume). Other bonding agents, such as organic resins (e.g., phenolic resins) and inorganic binders, may be employed in lieu of clay (e.g., sodium silicate and phosphate). Aside from sand and glue, additives are occasionally added to the mixture to improve qualities such as mould strength and/or permeability. The typical technique for forming the mould chamber is to compress the moulding sand around the pattern for both cope and drag in a container known as a flask. Various techniques are used in the packing process. The most basic method is hand ramming, which is done manually by a foundry worker. Furthermore, several equipment have been designed to automate the packaging process. These machines work through one of three mechanisms: (1) pneumatic pressure squeezing the sand around the pattern; (2) a jolting action in which the sand contained in the flask with the pattern is dropped repeatedly to pack it into place; and (3) a slinging action in which the sand grains are impacted against the pattern at high speed.

Flaskless moulding, which refers to the use of one master flask in a robotic mould manufacturing system, is an alternative to typical flasks for each sand mould. The same master flask is used to make each sand mould. This more automated process claims mould production rates of up to 600 per hour.

Several factors are used to assess sand mould quality: (1) strength the ability of the mould to maintain its shape and resist erosion caused by the flow of molten metal; it is affected by grain shape, adhesive qualities of the binder, and other factors; (2) permeability the ability of the mould to allow hot air and gases from the casting operation to pass through the voids in the sand; (3) thermal stability the ability of the sand at the surface of the mould cavity to resist cracking and buckling when in contact with the molten. These criteria are often conflicting; for example, a stronger mould is less collapsible. Green-sand, dry-sand, and skin-dried moulds are the most common types of sand moulds. Greensand moulds are comprised of sand, clay, and water, with the term "green" alluding to the fact that the mould holds moisture throughout the pouring process. Green-sand moulds are the least costly of the moulds and have appropriate strength for most applications, excellent collapsibility, permeability, and reusability. They are the most

common mould type, however they are not without flaws. Depending on the metal and shape of the item, moisture in the sand might create problems in certain castings. Dry-sand moulds are constructed with organic binders rather than clay and cooked in a big oven at temperatures ranging from 200C to 320C (392F to 608F). Oven baking hardens the cavity surface and strengthens the mould. When opposed to green-sand moulding, a drysand mould gives superior dimensional control in the cast product. Dry-sand moulding, on the other hand, is more costly, and the manufacturing rate is lowered due to drying time. In general, applications are confined to medium and large castings at low to medium production rates. The benefits of a dry-sand mould are partly realised in a skin-dried mould by drying the surface of a green-sand mould to a depth of 10 to 25 mm (0.4-1 in) at the mould cavity surface using torches, heating lamps, or other methods. To reinforce the cavity surface, special bonding agents must be added to the sand mixture.

The mould classes that follow apply to the usage of traditional binders that are either clay-and-water or need heating to cure. In addition to these categories, chemically bonded moulds that are not based on either of these typical binder materials have been produced. Furan resins (composed of furfural alcohol, urea, and formaldehyde), phenolics, and alkyd oils are some of the binder components employed in these "no-bake" systems. Because of its excellent dimensional control in high-volume applications, no-bake moulds are becoming more popular.

The Essential Permanent-Molding Process

Permanent-mold casting employs a metal mould with two pieces engineered for simple, accurate opening and closure. Steel or cast iron is typically used to make these moulds.

The cavity, complete with gating mechanism, is machined into the two halves to ensure exact dimensions and an excellent surface polish. Aluminum, magnesium, copper-base alloys, and cast iron are among metals that are regularly cast in permanent moulds. However, cast iron demands a high pouring temperature, 1250C to 1500C (2282F-2732F), which reduces mould life significantly. Steel's very high pouring temperatures make permanent moulds impractical, unless the mould is built of refractory material.

In permanent moulds, cores may be employed to generate internal surfaces in the cast product. Metal cores may be used, but their form must allow for removal from the casting or they must be mechanically collapsible to allow for removal. If removing a metal core would be difficult or impossible, sand cores may be utilised, and the casting method is known as semipermanent-mold casting.

Before casting, the mould is warmed and one or more coatings are sprayed over the cavity. Preheating allows metal to flow more easily through the gating system and into the cavity. The coatings help in heat dissipation and lubricate the mould surfaces, allowing for quicker cast product separation. After pouring, the mould is opened and the casting is removed as soon as the metal hardens. Permanent moulds, unlike disposable moulds, do not collapse, hence the mould must be opened before significant cooling shrinkage occurs to avoid fractures from forming in the casting.

As previously stated, the benefits of permanent-mold casting include superior surface polish and precise dimensional control. Furthermore, the metal mold's faster solidification leads in a finer grain structure, resulting in stronger castings. In general, the procedure is confined to metals with lower melting points. Other restrictions include simple component shapes relative to sand casting

(due to the requirement to open the mould) and mould cost. Because moulds are expensive, the method is best suited to high-volume manufacturing and may be automated as such. Automotive pistons, pump bodies, and various castings for aeroplanes and missiles are examples of typical components.

Casting Dies

Die casting is a permanent-mold casting method in which molten metal is shot under high pressure into the mould cavity. Pressures range from 7 to 350 MPa (1015-50,763 lb/in²). After solidification, the mould is opened and the portion is removed, with the pressure maintained. Die casting refers to the use of moulds in this casting process. The most noteworthy aspect that separates this method from others in the permanent-mold category is the employment of high pressure to drive the metal into the die cavity. Die casting operations are performed in specific die casting machines, which are intended to hold and precisely seal the two parts of the mould, and to maintain them closed while the liquid metal is driven into the cavity. Die casting machines are classified into two types: (1) hot-chamber and (2) cold-chamber, based on how the molten metal is poured into the cavity.

Metal is melted in a container connected to the machine in hot-chamber machines, and a piston is used to inject the liquid metal under high pressure into the die. Injection pressures range from 7 to 35 MPa (1015-5076 lb/in²). Figure 10.1 depicts the casting cycle. It is not unusual to see production speeds of up to 500 components per hour. Because most of the injection system is immersed in molten metal during hot-chamber die casting, it faces additional challenges. As a result, the method is confined to low-melting-point metals that do not chemically harm the plunger and other mechanical components. Zinc, tin, lead, and magnesium are among the metals.

Molten metal is poured into an unheated chamber from an external melting container in cold-chamber die casting equipment, and a piston is used to inject the metal under high pressure into the die cavity. In these machines, injection pressures range from 14 to 140 MPa (2031-20,305 lb/in²). Cycle rates are often slower in cold-chamber machines due to the necessity to ladle liquid metal into the chamber from an external source. Regardless, this casting process is a high-volume activity. Cold-chamber machines are often used for casting aluminium alloys, brass alloys, and magnesium alloys. Low-melting-point alloys (zinc, tin, lead) may also be cast using cold-chamber machines, although the benefits of the hot-chamber method typically outweigh the disadvantages.

Die casting moulds are often constructed of tool steel, mould steel, or maraging steel. Tungsten and molybdenum, which have high refractory properties, are frequently utilised, particularly in efforts to die cast steel and cast iron. Dies may have a single or several cavities. When the die opens, ejector pins are necessary to extract the component from the die. These pins lift the item away from the mould surface, allowing it to be removed. To avoid sticking, lubricants must be sprayed into the cavities.

Because the die materials have no inherent porosity and the molten metal flows quickly into the die during injection, venting holes and passages at the parting line must be constructed into the dies to remove the air and gases in the cavity. Despite their modest size, the vents fill with metal during injection. This metal must be removed from the component subsequently. Flash is also prevalent in die casting, where the liquid metal squeezes into the narrow space between the die halves at the parting line or into the clearances surrounding the cores and ejector pins under high pressure. This flash, as well as the sprue and gating system, must be removed from the casting.

Semisolid Metal Casting and Squeeze Casting

These are two procedures that are often linked to die casting. Squeeze casting is a mixture of casting and forging in which molten metal is injected into a warmed lower die, and the higher die is closed after solidification to produce the mould chamber. This contrasts from the traditional permanent-mold casting technique, in which the die halves are closed before pouring. Because of its hybrid character, the method is also known as liquid-metal forging. In squeeze casting, the pressure generated by the top die allows the metal to fully fill the cavity, resulting in an excellent surface quality and little shrinkage. The needed pressures are substantially lower than in forging a solid metal billet, and the die may provide much finer surface detail than in forging. Squeeze casting may be used for both ferrous and non-ferrous alloys, however because to their lower melting temperatures, aluminium and magnesium alloys are the most frequent. A typical use is automotive parts.

Semi-solid metal casting refers to a group of net-shape and near-net-shape methods used on metal alloys at temperatures between the liquidus and solidus (Section 10.3.1). Thus, during casting, the alloy is a slurry of solid and molten metals; it is in the mushy stage. To flow effectively, the combination must be composed of solid metal globules in a liquid rather than the more common dendritic solid structures that develop after the freezing of a molten metal. This is accomplished by vigorously swirling the slurry in order to inhibit dendrite development and instead favour spherical forms, which decreases the viscosity of the work metal. The following are some of the benefits of semisolid metal casting: (1) complicated component geometries, (2) thin walled parts, (3) tight tolerances, and (4) zero or low porosity, resulting in high casting strength.

Semisolid metal casting comes in a variety of shapes. The phrases thixocasting and rheocasting are used in the context of aluminium. The term thixocasting comes from the word thixotropy, which refers to the reduction in viscosity of several fluid-like materials when they are stirred. The prefix rheocasting is derived from rheology, the discipline that studies material deformation and flow. The beginning work material in thixocasting is a precast billet with a nondendritic microstructure, which is heated to semisolid temperature and injected into a mould cavity using die casting equipment. Rheocasting is similar to traditional die casting in that a semisolid slurry is pumped into the mould cavity by a die casting machine. The starting metal in rheocasting is at a temperature between the solidus and the liquidus rather than above the liquidus. In order to avoid dendrite development, the mushy mixture is stirred.

Thixomolding is a name used to describe the process of moulding magnesium using equipment comparable to an injection moulding machine. As magnesium alloy granules are heated into the semisolid temperature range, they are fed into a barrel and driven forward by a spinning screw. The revolving screw's mixing action achieves the requisite globular shape of the solid phase. The slurry is then injected into the mould cavity by moving the screw forward in a straight line.

Furnaces

Cupolas, direct fuel-fired furnaces, crucible furnaces, electric-arc furnaces, and induction furnaces are the most popular kinds of furnaces used in foundries. The most suitable furnace type is determined by parameters such as the casting alloy, melting and pouring temperatures, furnace capacity requirements, investment, operating, and maintenance expenses, and environmental pollution concerns.

Cupolas a cupola is a vertical cylindrical furnace with a tap spout towards the bottom. Cupolas are solely used for melting cast irons, and although other furnaces are sometimes utilised, cupolas melt the most cast iron. The cupola of steel plate coated with refractory has a general construction and operational properties. The "charge," which consists of iron, coke, flux, and sometimes alloying ingredients, is loaded via a charging door positioned about midway up the cupola's height. The iron is often a combination of pig iron and scrap (such as risers, runners, and sprues from prior castings). The fuel needed to heat the furnace is coke. For combustion of the coke, forced air is delivered via apertures towards the bottom of the shell. Slag is formed when a basic material, such as limestone, combines with coke ash and other impurities to generate flux. The slag protects the melt from reacting with the atmosphere within the cupola and reduces heat loss. The furnace is frequently tapped to produce liquid metal for the pour as the mixture is heated and the iron melts.

Furnaces that run on direct fuel a direct fuel-fired furnace has a tiny open-hearth in which the metal charge is heated by fuel burners on the furnace's side. The ceiling of the furnace helps to heat the charge by bouncing the flame down upon it. Natural gas is the most used fuel, and the combustion products escape the furnace via a stack. A tap hole at the bottom of the hearth allows the molten metal to escape. In casting, direct fuel-fired furnaces are often used to melt nonferrous metals such as copperbase alloys and aluminium.

Furnaces for crucibles these furnaces melt metal without exposing it to a burning fuel combination. As a result, they are sometimes referred to as indirect fuel-fired furnaces. In foundries, three kinds of crucible furnaces are used: (a) lift-out, (b) stationary, and (c) tilting. To store the charge, they all need a container (the crucible) constructed of a suitable refractory material (e.g., a clay-graphite combination) or high-temperature steel alloy. The crucible is put in a furnace and heated enough to melt the metal charge in the lift-out crucible furnace. These furnaces often use oil, gas, or powdered coal as fuel. When the metal has melted, the crucible is removed from the furnace and used as a ladle. The other two varieties, known as pot furnaces, combine the heating furnace and container into a single device. The furnace is stationary in the stationary pot furnace, and the molten metal is ladled out of the container. The whole assembly in the tilting of furnace may be tilted for pouring. Crucible furnaces are used to melt nonferrous metals such as bronze, brass, and zinc and aluminium alloys. Generally, furnace capacity are restricted to several hundred pounds.

Arc-Fuel Electric Furnaces The charge is melted in this furnace type by heat produced by an electric arc. There are many designs available, using two or three electrodes. Although power consumption is significant, electric-arc furnaces may be configured for high melting capacity (23,000-45,000 kg/hr or 25-50 tons/hr) and are generally used for steel casting. Furnaces for Induction An induction furnace creates a magnetic field in the metal by feeding alternating current via a coil, and the resultant induced current produces fast heating and melting. A mixing is caused by the electromagnetic force field

Heat Treatment, Cleaning, and Pouring

Crucibles are occasionally used to transport molten metal from the melting furnace to the mould. Ladles of different types are often used for the transfer. These ladles receive the metal from the furnace and enable easy pouring into the moulds. Two standard ladles, one for handling huge quantities of molten metal using an overhead crane and the other for manually manipulating and pouring smaller amounts.

One of the issues with pouring is that oxidised molten metal might enter the mould. Metal oxides degrade product quality, potentially leaving the casting faulty, hence precautions are required to prevent these oxides from entering the mould during pouring. Filters are sometimes used to collect oxides and other impurities as the metal is poured from the spout, and fluxes are used to coat the molten metal to slow oxidation. Furthermore, ladles have been developed to pour the liquid metal from the bottom, since the oxides collect on the top surface.

A number of extra procedures are normally necessary once the casting has set and been taken from the mould. These activities are as follows: (1) trimming, (2) core removal, (3) surface cleaning, (4) inspection, (5) repair (if necessary), and (6) heat treatment. In foundry work, steps 1 through 5 are referred to as "cleaning." The amount to which these extra activities are necessary varies depending on the casting technique and metal. When they are essential, they are frequently time consuming and expensive.

Trimming the cast component entails removing sprues, runners, risers, parting-line flash, fins, chaplets, and any other extra metal. These appendages on the casting may be broken off in the event of brittle casting alloys and when the cross sections are very tiny. Other types of cutting include pounding, shearing, hack-sawing, band-sawing, abrasive wheel cutting, and different torch cutting processes.

Cores must be removed if they were utilised to cast the component. The majority of cores are chemically or oil-bonded sand, and they often slip out of the casting when the binder deteriorates. They are sometimes eliminated by shaking the casting, either manually or automatically. Cores are sometimes removed by chemically dissolving the bonding agent employed in the sand core. Hammering or pressing out solid cores is required.

Casting Quality

In a casting procedure, there are several potential for things to go wrong, resulting in quality faults in the cast product. In this part, we provide a list of the most frequent casting flaws and describe the inspection processes for detecting them.

Defects in the Casting some flaws are common to all casting methods. These flaws are and are briefly discussed below:

(a) Misruns are castings that harden before filling the mould chamber fully.

Typical reasons include (1) inadequate molten metal fluidity, (2) pouring temperature being too low, (3) pouring being done too slowly, and/or (4) the cross-section of the mould cavity being too narrow.

(b) Cold Shuts, which occur as two parts of the metal flow together but fail to fuse owing to premature freezing. Its causes are comparable to those of a misrun.

Cold shots are caused by splattering during pouring and result in the creation of solid globules of metal that get caught in the casting. Pouring processes and gating system designs that minimise splattering may help to avoid this flaw.

d) A shrinkage cavity is a dip on the casting's surface or an interior void generated by solidification shrinkage, which limits the quantity of molten metal accessible in the final area to freeze. It is most often seen towards the top of a casting, where it is referred to as a "pipe." Figure 10.8 depicts this (3). Proper riser design may often remedy the issue.

(e) Microporosity is a network of tiny spaces scattered throughout the casting induced by the dendritic structure's localised solidification shrinkage of the final liquid metal. Because of the prolonged nature of freezing in these metals, the fault is generally connected with alloys.

(f) Hot tearing, also known as hot cracking, occurs when a rigid mould prevents the casting from contracting during the latter stages of solidification or the early stages of cooling following solidification. Because of the metal's inability to shrink normally, the defect manifests as a separation of the metal (thus the words ripping and cracking) at a site of high tensile stress. It is avoided in sand casting and other expendable-mold procedures by making the mould foldable. Hot tearing is decreased in permanent-mold procedures by removing the item from the mould soon after solidification.

Some flaws are caused by the usage of sand moulds and so occur exclusively in sand castings. Other expendable-mold methods are also subject to same issues, although to a lesser extent. and describes defects encountered predominantly in sand castings:

(a) Sand blow is a fault characterised by a balloon-shaped gas chamber induced by mould gas leakage during pouring. It happens towards the top of the casting, at or below the casting surface. The typical culprits include low permeability, insufficient venting, and a high moisture content of the sand mould.

(b) Pinholes are created at or slightly below the surface of the mold and are generated by the discharge of gases during pouring.

(c) Sand wash, an irregularity on the surface of the casting caused by sand mould erosion during pouring, and the contour of the erosion is produced in the surface of the final cast part.

Scabs are rough regions on the surface of a casting caused by sand and metal encrustations. It is caused by flaking off sections of the mould surface during solidification and getting embedded in the casting surface.

(e) Penetration is a surface fault that arises when the liquid metal's fluidity is high and it enters the sand mould or sand core. The casting surface becomes a combination of sand grains with metal after freezing. This issue is alleviated by harder packing of the sand mould.

(f) Mold shift is a flaw induced by a sideways movement of the mould cope relative to the drag, resulting in a step in the cast product near the parting line.

(g) Core shift is similar to mould shift, except that the core is moved instead of the mould, and the displacement is generally vertical. The buoyancy of the molten metal causes core movement and mould shift.

(h) Mold crack occurs when mould strength is inadequate, resulting in the formation of a fracture through which liquid metal may leak and create a "fin" on the final casting.

Methods of Inspection Foundry inspection procedures include (1) visual inspection to detect obvious defects like misruns, cold shuts, and severe surface flaws; (2) dimensional measurements to ensure tolerances are met; and (3) metallurgical, chemical, physical, and other

tests concerned with the inherent quality of the cast metal. Pressure testing (a) is used to locate leaks in the casting; radiographic methods, magnetic particle tests, the use of fluorescent penetrants, and supersonic testing (b) is used to detect either surface or internal defects in the casting; and mechanical testing (c) is used to determine properties such as tensile strength and hardness. If minor flaws are identified, it is generally feasible to preserve the casting by welding, grinding, or other salvage processes agreed upon by the buyer.

CHAPTER 10

Metals for Casting

Mr. Dipendra Kumar,
Associate Professor, Department of Mechanical Engineering,
School of Engineering & Technology, Jaipur National University, Jaipur, India,
Email Id-dipendra1987@jnujaipur.ac.in

Alloys, rather than pure metals, are used in the majority of commercial castings. Alloys are often simpler to cast, and the finished product has superior qualities. Casting alloys are either ferrous or nonferrous. Cast iron and cast steel are subcategories of the ferrous category. Alloys for Ferrous Casting: Iron Casting The most significant of all casting alloys is cast iron. Cast iron castings have a tonnage many times that of all other metals combined. Cast iron is classified into five types: (1) grey cast iron, (2) nodular iron, (3) white cast iron, (4) malleable iron, and (5) alloy cast irons (Section 6.2.4). Depending on the composition, typical pouring temperatures for cast iron are approximately 1400C (2552F).

Steel is a ferrous casting alloy. Steel's mechanical qualities make it an appealing engineering material, and its ability to construct complicated shapes makes casting a desirable method. The foundry specialised in steel, on the other hand, has significant challenges. For starters, steel has a far greater melting point than most other widely cast metals. The solidification temperature range for low carbon steels starts slightly below 1540C (2804F). This implies that the pouring temperature for steel is quite high around 1650C (3002F). Steel is chemically extremely reactive at this high temperatures. Because it oxidises easily, specific processes must be utilised to separate the molten metal from air during melting and pouring. Furthermore, molten steel has a low fluidity, which restricts the design of thin sections in steel components.

Several properties of steel castings make it worthwhile to make the effort to tackle these challenges. Tensile strength is greater than that of most other casting metals, reaching about 410 MPa (59,465 lb/in²). Steel castings are more durable than most other casting alloys.

Steel castings have isotropic characteristics, which means that their strength is about the same in all directions. Mechanically made pieces, on the other hand (e.g., rolling, forging), demonstrate directionality in their attributes. Isotropic behaviour of the material may be advantageous depending on the needs of the product. Another benefit of steel castings is their ease of welding. They can be easily welded without substantial loss of strength, allowing them to be repaired or used to construct buildings with other steel components.

Alloys for Nonferrous Casting Alloys of aluminium, magnesium, copper, tin, zinc, nickel, and titanium are examples of nonferrous casting metals. Aluminum alloys are often regarded as being particularly castable. Because pure aluminium has a melting point of 660C (1112F), pouring temperatures for aluminium casting alloys are lower than for cast iron and steel. Light weight, a broad variety of strength qualities accessible by heat treatment, and simplicity of machining make them appealing for castings. Magnesium alloys are the lightest metals for casting. Corrosion resistance, as well as high strength-to-weight and stiffness-to-weight ratios, are among the other qualities.

Bronze, brass, and aluminium bronze are examples of copper alloys. They are appealing because of their corrosion resistance, beautiful look, and outstanding bearing properties. The high cost of copper restricts the utilisation of its alloys. Pipe fittings, maritime propeller blades, motor components, and beautiful jewellery are all examples of applications. Tin is the casting metal with the lowest melting point. Tin-based alloys are often simple to cast. They are corrosion resistant but have little mechanical strength, limiting their applicability to pewter cups and related objects that do not need significant strength.

Die casting often employs zinc alloys. Zinc has a low melting point and excellent fluidity, making it ideal for casting. Because of its poor creep strength, its castings cannot withstand sustained high strains. Because of their great hot strength and corrosion resistance, nickel alloys are well suited for high-temperature applications such as jet engine and rocket components, heat shields, and related components. Nickel alloys are also difficult to cast because of their high melting point. Titanium alloys for casting are resistant to corrosion and have good strength-to-weight ratios. Titanium, on the other hand, has a high melting point, limited fluidity, and a propensity to oxidise at high temperatures. Because of these characteristics, it and its alloys are difficult to cast.

Product Design Considerations

If the product designer chooses casting as the principal manufacturing technique for a certain component, certain rules should be followed to ease production and eliminate many of the problems. Some of the most significant casting principles and considerations are covered here.

Geometric elegance. Although casting may be utilised to create complicated component geometries, reducing the part design improves castability.

Avoiding superfluous complications simplifies mould construction, decreases the need for cores, and enhances casting strength.

The corners. Sharp edges and angles should really be avoided since they are stress concentration points that may produce hot ripping and fractures in the casting. Inside corners should have generous fillets, and sharp edges should be softened.

The thickness of a section. To eliminate shrinkage voids, section thicknesses should be consistent. Because higher volume necessitates longer time for solidification and cooling, thicker portions induce hot spots in the casting.

These are most likely shrinkage cavities. **Draft.** Part parts that protrude into the mould should be drafted or tapered, as the goal of this draught in expendable-mold casting is to make it easier to remove the pattern from the mould. Its function in permanent-mold casting is to facilitate in the removal of the component from the mould. If solid cores are utilised in the casting process, similar tapers should be permitted. The needed draught for sand casting is only approximately 1 and 2 to 3 for permanent-mold techniques.

Utilization of cores. Minor adjustments in component design, may lessen the necessity for coring. **Dimensional tolerances.** The dimensional accuracies that may be attained in castings vary significantly depending on the procedure utilised. **Compiles typical component tolerances for several casting methods and metals.** **The finish on the surface.** Surface roughness in casting process is typically approximately 6 mm (250 m-in). Shell moulding also yields poor results, as does plaster moulding.

Centrifugal Casting Process

High material soundness components are produced via centrifugal casting. As a result, it is the technique of choice for high-reliability applications such as jet engine compressor casings, hydro wear rings, and many military goods. In comparison to forgings and fabrications, it has been shown to be a more affordable way to provide complicated forms with lower production costs and less machining needs.

The first stage in the centrifugal casting is the pouring of molten metal into a heated, rotating die. Depending on how the intended component is set up, the die may be orientated either on a horizontal or a vertical axis. Centrifugal force is used to evenly distribute molten metal inside a rotating mould as the metal is pumped into it at pressures that are close to 100 times greater than the force of gravity. Superior-quality components are produced by combining this applied pressure with the mechanics of controlled crystallization and subsequent refining.

Types of Centrifugal Casting

There are vertical and horizontal centrifugal casting procedures. A further option provided by certain manufacturers is near-net shaping, which combines the advantages of centrifugal castings with O.D. shaping and, perhaps, with the completed detail of the investment casting.

Vertical Centrifugal Casting

Castings with a greater length to diameter are typically used for cylindrical designs when the use of the length or elevation of the casting. Steel mill rollers are an exception to this, since they utilize a roller guiding system to allow the fabrication of solid castings. It may also be used to cast complicated objects like control valves and propellers. A parabolic effect occurs in the bore due to gravity attraction while pouring the material; this may be changed by varying the casting speed. The denser portions of the molten iron were pushed towards the outer diameter as the mould and die rotate. The mould functions as a cooling surface, consolidating the iron from the outside diameter as it advances towards the bore in a process called as directed solidification.

Horizontal Centrifugal Casting

Horizontal Centrifugal Molding is ideally suited to castings with a length larger than the diameter and a cylindrical bore. This is why tubes ranging in length from 300mm to 6000mm are so prevalent. A shaped mold or sand inlays can be used to generate shaped castings horizontally.

Vacuum Centrifugal Casting

Some alloys, especially nickel-cobalt hyper alloys, are reactive to oxygen, centrifugal casting in a vacuum is utilized when component detail and control of the environmental impact are crucial. In addition to the benefits of vacuum casting, the inherent increased metal integrity provided by injection molding is achieved, including directed solidification, lack of porosity, and total. Vacuum centrifugal casting produces extremely reliable products, which are frequently utilised in aerospace and weapons system.

Working Principle of Centrifugal casting

The centrifugal casting process begins with molten phase being filled with a rotating high-temperature die. Depending on the design criteria, the die might be mounted on a vertically or flat pivot. During the action, centrifugal force operates to disperse the liquid metal in the form at pressures approaching multiples of gravity's strength. This applied pressure prevents fractures

and other micro and macro defects. This is quite similar to the traditional die casting technique in which applied pressure lowers overall faults in the result. The thicker molten material is drawn to the bulk of the spinning die as the die fills.

Furthermore, sound metal directional cementing progresses from the external diameter it toward the drag, whereas less thick material with imperfections floats to the external diameter. When the solidification process is finished, the entire component is withdrawn first from die and the residual debasements in the part's borders are removed by the machining process.

1. The process begins similarly to any other casting process, with the metal being heated above its melting point.
2. The mould is then rotated to prepare that for filling in the second stage. In general, the rotational speed ranges from 300 to engine Speed. The precise figure, however, is determined by the project's specifications.
3. The next step is to start pouring. This is a straightforward procedure that requires no extra preparation. But, must exercise caution since the process will occur while the mould is rotating.
4. When the pouring is finished, the following phase begins automatically. The rotation speeds up the cooling process while also creating enough pressure within in the mould to eliminate the possibility of casting errors.
5. After cooling, is comparable to any other casting process. Simply take the mould off the roller and retrieve its material from the castings.
6. Finally, fine-tune the finished result. The centrifugal spin forces imperfections in the metal to the edges, where they may be machined off to achieve the desired quality.

Three Types of Centrifugal Casting

Aside from machine differentiation, the process also includes several casting procedures that have direct impact on the total outcome. Here are the three primary types of casting procedures used in the business.

True Centrifugal Casting

True casting is precisely what the preceding section explained. The procedure might be either horizontal or vertical. However, horizontal axis spinning creates high-intensity applications such as cylinder liners. In general, the rotation speed influences the physical attributes of the product, such as density and strength.

However, the location of the mound and other elements combine to produce the finest overall outcomes with this centrifugal casting process.

Semi-Centrifugal Casting

The semi-centrifugal casting technique is quite close to the actual process. However, there are several significant disparities between the two procedures and their overall outcomes. To begin with, instead of using a tubular cast, this procedure produces a solid result. Similarly, because the outside regions of the things created with this procedure have a larger density, this casting method produces products with varied densities.

The spinning speed, overall diameter, temperature, and other elements all have an impact on the overall integrity of the castings you manufacture. This indicates that there is a higher chance of anything going wrong, which might inevitably impair the quality.

Centrifugal Casting

Centrifuging, also known as centrifuge casting, is a common technique for producing complicated objects with various surface details. This approach is most commonly used for jewellery, little shrubs, sleeves, and other such items. Centrifuging involves placing a mould cavity of a specific form at a separation from rotating axis and continuing the procedure as usual. Rotational forces press the molten into the cavity, forming it into the desired shape.

Element of Mold

Mold development is a complicated process with many moving parts that necessitates a high level of technical skill. To ensure exact dimensions and design characteristics, the process of molding a finished product necessitates specialized technical expertise. The first stage in the precise process is to understand the fundamental components of molding. They perform vital functions in the injection mould manufacturing process. The following are the major mould components necessary to make high-quality parts. Mold components are the systems that allow the mould to function and create a high-quality final result. Mold base, pins, hydraulic actuators, lifters, bushings, guides, and alignment devices are all important components. Mold components are classified into three types: frame plates, frame elements, and cavity tooling

Cavity and Core Components

Molding components are made up of such a cores and a cavity. The interior surface of the product is formed by the core, while the exterior surface is formed by the hollow. Concave die refers to the moulding components that make up a product's external shape which is also called female mould . Core or terrace dies are those that make up a product's interior form (such as a hole, groove, etc) which is also called male mold . When creating molding components, the general structure of the cavity should be determined first based on the qualities of the plastic, the geometric shape of the product, dimensional tolerance, and operational requirements

Mold Lock Unit

This is a clamp mechanism that uses numerous plate motions to secure the mould. The device's capabilities include

1. In cold chamber machines, a fixed fixing plates holds the fixed (casting) mould half or the shot component
2. The moveable (ejector) mould half is held in place by a movable fixing plate.
3. The moveable fixing plate is guided by guide columns, which contain the die locking force generated by the locking device.

Side-Action Mechanism

Undercuts or side holes are seen on several plastic goods. They require side separating before demolded to extract the exterior core first. There are two types of side-action systems:

1. Perfect fit action (backup) that covers all actions that aim to maintain the core position by ensuring that components fit perfectly.

2. Compression fit operation (zero movement), which encompasses all operations that compress the core into place before, throughout, and after injection by delivering and keeping a high set force.

In the chemical processing business, injection moulding machines must run constantly for lengthy periods of time to ensure consistency. Venting: During the melting process, every moulding step eject gas. Vents provide as escape routes. They are moulded gas vents with grooves. The finished products will exhibit porosity, plate markings, and short shots if there is no venting.

Gating

Gating is utilised for a number of reasons, including managing material flow velocity and preventing backflow during injecting. Gate sections are often rectangular or circular in design. However, the form, height, and placement of the gate are determined by plastic qualities, structures, design to achieve, and sizes.

Ejector Pins

They are employed to remove mould pieces. Straight and shoulder ejector pins are the two types. The structural location of a product determines the specific pin needs. The "bouncers" of the plastic injection world are ejector pins. They use force to remove a part from mould and may leave markings in some circumstances.

Cooling System

Mold temperature management is critical for uniform molding. Cooling channels that enable conduction are used to cool molded hot plastic. Water is commonly utilised as the working fluid, while petroleum can be employed in elevated applications. The heat generated by the molding process is swiftly and uniformly dissipated through injection mould cooling. Fast cooling is essential for cost-effective production, and consistent cooling is needed for product quality. Because cooling generally accounts for 2 different of the injection molding cycle time, the configuration of the cooling cycle requires considerable consideration.

Hot Runner Systems

Mold temp management is essential for uniform moulding. To cool formed hot plastic, conduction-enabled cooling tubes are employed. Water is generally utilized as the coolants, however petroleum can be used in high-altitude applications. Through injection mould cooling, heat created during the moulding process is quickly and uniformly removed. Consistent cooling is required for product quality and fast cooling is required for cost-effective production. Because cooling typically accounts for two-thirds of the injected moulding cycle duration, the cooling cycle layout must be carefully considered.

Guide Bushings:

The injection mold's guide device's duty is to direct the upper and lower moulds into the right position. Guide bushings are maybe the most misunderstood router accessory. Their applications

include jig-cutting dovetails, writing, inlay work, and even replicating furniture pieces. The injection molded parts cycle refers to the sequence of events that occur during the injection molding of a plastic item. When the mould shuts, the cycle begins, and the polymer is injected into the mould.

Casting

Casting is a production method that involves pouring a liquid material into a mould that has a hollow hole of the desired shape and then allowing it to harden. To finish the process, the solidified portion, also referred as a casting, is expelled or broke out of the mould.

Types of Casting and the Casting Process

Although casting is among the oldest known production procedures, developments in casting technologies have resulted in a diverse range of specialized casting methods. Die-casting, casting, plaster trying to cast, and sand casting are all hot forming methods with distinct industrial advantages. Comparing the benefits and drawbacks of the various casting methods might aid in picking the method particularly fits for a certain production run.

Sand Casting

Sand casting is often done with silica-based materials such as manufactured or naturally bonded sand. Casting sand is often made up of finely chopped, spherical grains that may be closely packed together to provide a smooth molding surface. By permitting a reasonable amount of elasticity and shrinkage throughout the cooling portion of the process, the casting is meant to limit the possibility of ripping, cracking, or other faults. Sand may also be reinforced by adding clay, which makes the particles connect more tightly. Sand casting is used to make automotive parts such as engine block

Patternmaking, moulding, melting and pour, etc cleansing are all phases in the sand casting process. The patter is the shape which the material is packed, which is generally divided into two pieces, the coped and the drag. The cope is withdrawn anis d the pattern retrieved once the sand has been compressed sufficiently to reproduce the design. The cope is then replaced, together with any extra inserts known as core boxes. That after metal has indeed been poured and hardened, the casting is withdrawn, the risers and valves used during the pouring operation are trimmed, and the casting is cleaned of any attached sand and scale.

Investment Casting

Investment casting, also known as lost-wax casting, employs a disposable wax template for each cast item. The wax is incorporated intravenously into a mould, removed, and then covered with passivation layer and just a binding agent in stages to form a thick shell. Several patterns are combined onto a single sprue. The designs are inverted and baked in furnaces to remove the wax once the seashells have solidified. The leftover shells are then filled with molten metal, which solidifies into the form of the thermoplastic materials

Parts for the automobile, power generating, and aerospace sectors, like as turbine blades, are frequently manufactured using investment casting. Among the primary benefits and drawbacks of investment casting are:

1. A high level of precision and precision in dimensional findings.
2. Capability to manufacture thin-walled items with complicated shapes.

3. The ability to cast ferrous and nonferrous materials.
4. Surface polish and precision in final pieces are of rather good grade.

Plaster Casting

Plaster casting is identical to sand casting, except instead of sand, a combination of gypsum, reinforcing compound, and water is used. The plaster design is usually covered with an anti-adhesive substance to keep it from sticking to the mould, and the plaster can fill in any gaps surrounding the mould. When the plaster material used to cast the item fractures or develops faults, it must be replaced with new material.

Plaster casting has the following advantages:

1. The surface is really smooth.
2. The capacity to cast intricate forms with thin walls.
3. The ability to manufacture huge pieces at a lower cost than other methods, like as investment casting.
4. Dimensional precision is greater than in sand casting.

Permanent Mold Casting

Permanent mould casting is similar to die cast and centrifugal casting in that it uses reusable moulds. These can be composed of steel, graphite, or other materials and are commonly used to cast lead, zinc, aluminum, and magnesium alloys, some bronze medals, and cast iron. Pouring is often done by hand utilising many moulds on a turntable in a low-pressure technique. The moulds are sequentially covered, sealed, filled, cleaned, and emptied as they rotate through the different phases. Slush casting is one such process, in which the mould is filled but then drained before the metal solidifies completely.

Advantages of casting process:

1. In the molten cavity, molten steel flows into a tiny ant segment. As a result, any complicated form may be simply made.
2. Casting may be done with almost any material.
3. The best way is to produce modest amounts.
4. The qualities of the casting are the same from all directions due to the low melting point from all directions.
5. Up to 200 tonnes of casting may be made in any size.
6. Casting is frequently the cheapest and also most direct method of manufacturing a form with certain mechanical qualities.
7. Certain metals and alloys, such as extremely creep resistance steel alloys for gas turbines, can only be cast and cannot be manipulated mechanically.
8. Heavy equipment, such as machine leads and ship propellers, may be simply thrown in the desired size rather than fabricated by combining multiple small parts.
9. Casting is ideal for composite components that require varied characteristics in different directions. These are created by adding desired inserts into a casting. Aluminum conductors in slots in iron framework for electric engines, for example, or wear resistant coverings on shock resistant components.

Limitations of casting process

The dimensional accuracy and surface quality of a standard sand casting method are lower.

1. Defects cannot be avoided.
2. Sand casting is a time-consuming process.
3. the original source

Casting Solidification

Casting is a popular metal solidification technique that involves melting and re-solidifying a metal or combination within a mould to obtain the desired final result. Casting is frequently used to make intricate forms that would be difficult or expensive to produce using other methods. The amount of heat removal between molten metal to mould is known as solidification. An essential procedure is the removal of heat to get a product from casting. The product obtained during the casting process is determined by the solidification time, manner of solidification, and so forth.

Solidification is vigorous to consider when making a product utilizing a casting technique. Solidification is vital in the casting process because it removes heat from molten material, resulting in a desired product with a superior surface polish.

Directional solidification

Directional solidification is just a faster solidification process than unidirectional solidification; in this system, cooling begins at the bottom of the mould and progresses to the top. Because of the rapid rate of cooling, the item formed has a rough surface. This method is used to make turbine blades. Directional solidification happens when solidification begins at the far end of the casting and progresses towards the sprue. Longitudinal solidification, also referred to as parallel solidification, is the process of solidification that begins at the casting's walls and advances perpendicularly from that surface

Unidirectional solidification

Unidirectional solidification is a slower solidification process than directional solidification; the cooling of molten metal in the mold begins from top to bottom, and the item produced has a smooth surface. This method is used to make turbine vanes.

Simple casting

Casting is a mechanical technique through which a molten metal or its mixture is put in a mould and allowed to harden. The thing will then take on the contours of the mold. Castings are made in a single movement from liquid metal, with no intermediary mechanical working procedures like as roll or forging.

Shrinkage in sand casting

Most metals, particularly aluminium, copper, zinc, and magnesium, shrink. The degree of contraction is determined by the material's freezing range. As an example, metal shrinks by almost 6% during solidification whereas copper shrinks by about 5%. Solidification happens in sand casting as the molten steel is poured into the steel mold. To limit shrinkage and remove faults, it is critical that this stage of the sand casting process be carried out in a carefully regulated way.

Solidification shrinkage

Solidification shrinkage because metals become less dense as liquids than solids. Risers and chills are employed to alleviate this problem.

Risers keep molten metal flowing into the foundry as it hardens. They serve a crucial function in facilitating directional crystallisation where the metal freezes at the distant point first before migrating towards the riser. Using this method, the hollow originates in the riser rather than the casting.

Pattern maker's shrinkage

When the castings is chilled to room temperature after solidification, pattern maker's shrinkage occurs. Thermal contraction causes this effect. A shrinkage tolerance must thus be included in the design at the outset of the procedure. To account for this form of shrinkage, the design is produced bigger than the target casting size. The shrinkage tolerance varies depending on the metal, however the design may need to be 2.5% bigger than the original item. Additionally, various portions of the cast may need different tolerances. So, assessing these allowances needs talent and experience to assure a high-quality completed result.

Shrinkage cavity

A shrinking cavity is a depression that forms in a casting during in the solidification process. When compared to the spherical surfaces of gas porosity, shrinkage porosity has angular edges. Cavities may also be accompanied with branching fractures or cracks. Shrinkage porosity is caused by the lack of metal in the mould. Small holes are left left throughout the casting when the material is cooled and shrinks. These holes are frequently jagged, in opposed to the smooth hovering holes and cracks created by gas. Cavities that shrink will reduce the casting's strength.

Sponge shrinkage

Sponge shrinkage often occurs in the thicker middle of the castings product and results in the formation of a thin lattice structure akin to filament or dendrites. Filamentary shrinkage creates a network interconnected continuous fractures of different diameters and densities, typically beneath a thick portion of material.

Filamentary Shrinkage

Filamentary shrinkage develops in a web of continuous fractures of varied diameters and densities, commonly under a thick part of the material. It can be challenging to recognize as the fracture threads tend to be linked.

Dendritic shrinkage

Dendrites diminish with age, their branches grow less complicated, and they lose pyramidal neurons, which are small brow ridges that receive chemical messages. The term "responsibility" refers to the act of determining whether or not a person is responsible for his or her own actions.

Shrinkage porosity

Shrinkage porosity flaws are voids inside elements which could also cause material degradation and, if located on surface, can decrease cosmetic quality and corrosion protection. Identifying the size, form, and surface of cavities is critical for determining which defect is occurring and determining its origin.

However, shrinkage porosity must be distinguished from oxygen entrapment: holes created by air entrapment possess rounded forms, whereas holes caused by shrinkage porous have angular faces.

Casting Defect

Casting Defect appear on the cast company's face as dips (caved areas) or holes (pipes). The air is sucked within the mould when the metals alloy shrinks evenly will generate an open shrinkage. Defects in Closed Shrinkage. These show as holes inside of the castings where the molten metal is heated unevenly

Pinholes

Pinholes, sometimes also described to as micropores, seem to be very tiny defects (about 2 mm) commonly found in the cope (upper) region of the mould, in poorly ventilated pockets. flaws in the casting They frequently appear in great numbers collectively, either at the level or slightly below the of the casting. The term "naked" refers to the act of looking at oneself in the mirror[2].

Subsurface blowhole

A subsurface blowhole emerges on the interior of a cast and is typically not apparent until after it has been machined. Subsurface tracheae can just be difficult to spot before grinding, requiring frequency, ultrasonic, electromagnetic or x-ray investigation.

Open holes

Open holes appear on the surface of the object as a form of blowhole. These flaws are generated by trapped air as metal is injected into the mould. There is also shallow form of open spaces called a scar. These blowholes show on the cast's surface and are simpler to spot than subterranean blowholes. Gas porosity causes and prevention and Cavity faults can be caused by a variety of factors.

1. Poor ventilation of mould and cores
2. Insufficient drying of mould and cores

Open Shrinkage Defects

If the material cools or shrinks with insufficient fluid available to fill any gaps, pipes may develop in the surface and descend into the interior of the castings. Similarly, surface faults that extend over the face are frequently referred to as cave defects or sinks. In both cases, the faults are exposed to the environment, and air replaces molten metal. Racks and hot tears are typically formed during the latter phases of crystallization and can be confined around rapid changes in stress concentration, such as a thin web linking two heavy areas. They can also arise in parts with insufficient ventilation and in heavier areas where heat pools.

Closed Shrinkage Defects

Porosity is a common casting fault induced by trapped air inside the molten metal as well as the casting shrinking during cooling. Shrinkage porosity is far and away the most frequent form, and it is generally apparent on the surface of either a cast object as tiny holes or fissures. These holes appear circular, but they are really angular in shape, with branching interior cracks. Thick multi-angled pieces are especially vulnerable to shrinkage, which happens as the iron cools and hardens in an uneven manner.

Porosity can happen in the inside of casting too, without necessarily displaying on the outside of a component. This happens when molten metal is encircled by hardened metal and cannot fill in between the liquid since it cooled down or shrinks. The casting sprue, as the route by which molten metal flows into a mould, is the most prevalent source of shrinkage. In some regions, such as the heavier parts of the mould, the metal takes much longer to compress and solidify, which lowers feed material flow and increases the chance of shrinkage, notably if the issue is too narrow for the quantity of flow. A suitably sized sprue linked directly towards the heavy portion could fill the shrinkage void and supply the feed material required to compensate for shrinkage as it cools.

Moreover, employing a rounded, as opposed to a rectangular or square, turnstiles on the sprue also can limit the chance of producing flaws. When using a thin or tapered sprue, the molten metal may be sprayed rather than spilled into the aperture. When this occurs, specific areas of the workpiece begins to harden before the entire mould is filled. The flow of molten material into the cavity needs to be as uniform as possible and a bigger central sprue or multiple-sprue arrangement can aid in this goal.

Temperature Affects Casting Shrinkage

Working within a defined temperature range can assist to decrease the possibility of metal casting shrinkage. Metal should be melted to obtain adequate molten properties, usually to 100°F well above flow point. Any overheating should really be avoided. A typical rule of thumb is to keep mould temperatures between 800-1000°F below the boiling point of the metal. Another essential factor to remember is the cast cooling rate, which may be as high as 100°D e per minute after the pouring process is complete.

Cuts and washes

Cuts and washing are regions of surplus metal. These occur as the molten metal dwindles the moulding sand. A cut shows as a low protrusion along the area of the drag face, reducing in altitude as it stretches from one corner of the molding to the other. Cuts and washes: causes and prevention Cuts and wash can be generated by liquid steel flowing at a fast velocity, enabling too much iron to flow through gate.

Fusion

When sand granules come into contact with molten metal, they fuse. It shows as just a thin crust with a hard, glassy look firmly adhering to the casting. The capacity of the moulding substance to withstand the the liquid's temperature so that it does not fuse with both the metal is referred to as refractoriness. Foundry sand has the greatest refractoriness. Improving the barrier properties of the moulding material and/or decreasing the pouring heat of the liquid steel will assist avoid fusion

Slag inclusions

Slag inclusions are nonmetallic particles trapped in the weld metal or at the weld interface. Slag inclusions result from faulty welding technique, improper access to the joint, or both. Sharp notches in joint boundaries or between weld passes promote slag entrapment.

To prevent producing pockets that trap the slag, use welding procedures that create smooth welding beads and enough inter-run fusion.

Use the proper current and traveling speed to prevent undercutting the sidewall, which will make removing the slag harder.

Forging

Forging, a metal reshaping method that uses compressive, localized forces, has been used since the times of the ancient Olmec's. Forging has evolved significantly since its inception in the Fertile Crescent, leading to more efficient, quicker, and more durable technique. This is because most forging nowadays is done with forged presses or striking tools that also are powered by hydraulics, or compressed air.

Purpose of forging

The goal of hammering is to make metal pieces. Metal forging creates some of the most durable produced components available when compared to other production processes. Minor fractures and empty spots in the metal are filled as heated and pressed. This drastically minimizes the number of flaws in the forged component. Inclusions are compound elements inserted into steel throughout manufacture that produce stress areas in the final forged pieces.

Forging also strengthens metal by alternating its structure, which corresponds to the grain flow of the metal substance as it deforms. A desirable grain structure may be generated by forging, giving the forged metal stronger.

The forging method is very versatile and may be utilised on small pieces just a few feet in size to huge elements that weigh upwards to 700,000 lbs. It is utilised to manufacture vital aviation parts as well as transportation equipment. Forging can also be used to strengthen hand tools like chisels, rivets, nails, and bolts.

Different types of forging

Forging's hammering action deforms and mounds the metal, resulting in uninterrupted grain flow. As a result, the metal retains its strength. The removal of flaws, inclusions, and permeability in the product is one of the ancillary impacts of this particular grain flow. Another advantages of forging is the comparatively cheap costs involved with moderate and large production runs. Products may be made at reasonably high rates with little downtime after the forging tools are established. Forging is classified into two types: hot and cold.

Hot Forging

This can require searing metals out to 900 degrees Fahrenheit. The fundamental advantage of hot pressing is the reduction in energy it takes to correctly shape the metal. This is because extreme heat reduces yield strength while increasing ductility. Chemical irregularities are also eliminated in hot forged items.

Cold Forging

Cold forging normally refers to forming a metal at room temperature, however any temperature below crystallisation is conceivable. Many metals, such as carbon-rich steel, are just too robust for cold forging. Despite this disadvantage, cold forging outperforms its warmer counterpart in terms of dimensional precision, product homogeneity, surface polish, and contamination. Cold forging comprises several forging processes, including bending, pressing, cold drafting, cashing, and cold heading. However, this enhanced adaptability comes at a cost, because cold forging needs more highest scientific and it may call for the use of intermediary anneals.

Different forging processes

Many specialized procedures exist in addition to basic both hot and cold forging. This diverse set of processes may be divided into three major categories: Draw shaping reduces the breadth of the product while increasing the length. Upset hammering increases the breadth of the goods and lowers length. Compression forming allows forging flow to be directed in many or customized directions. These three categories comprise numerous distinct specialized sorts of metal forging procedures.

Drop Forging Process

Drop forging is named from the technique of dropping a sledgehammer into the metal to form it in the shape of a die. The surface that gets into touch with the metal is termed as the die. Drop forging is classified into two types: open-die forging and closed-die forging. Die surfaces are normally flat, with some having uniquely shaped surfaces for specific processes.

Open Die Forging Process

When flat dies with no precut features engage in forging, the process is known as open die forging (or smith forging). The open structure enables the metal to flow throughout except for when it comes into contact with the die. To attain the best results, the item must be moved correctly. It should weigh over 200,000 pounds and be 80 feet long. It's helpful for brief art smiting or shaping ingots before secondary shaping. Open die forging produces products with greater fatigue strength and resistance while reducing the possibility of errors or holes. It can also produce finer grain sizes than conventional methods.

Closed Die Forging Process

Molds are used in closed die forging, also known as impression die forging. These moulds are linked to an anvil while a sledgehammer drives molten metal to stream into the slots of the die. Multiple blows and/or die voids are typically employed when forging complicated designs. High initial tooling costs and make closed die forging pricey for brief operations, but the tooling becomes cost-effective as components produced rises. Open die forging also delivers excellent strength over competing processes. Common uses of enclosed die forging have included the manufacturing of vehicle components and metal tools.

Press Forging Process

Compression is the primary forming force in press forging. The metal lies on a fixed die whereas a compression die provides constant pressure, creating the required form. The metal's contact time with the dies is significantly longer than in other forms of forged, but the forging process benefits from the ability to concurrently deform the whole product, rather than just a localized part? Another feature of press forged is the capacity of the maker to monitor and adjust the particular compression rate. Because there are few limitations on the size of item that may be made, press forging has a wide range of uses. Press forging could be either hot or cold formed.

Roll Forging Process

Roll forging is the technique of lengthening rods or wires. To shape the metal, the maker puts hot metal bars between cylinder wheels with grooves that revolve and provide progressive pressure. The finely designed pattern of these grooves tries to build a metal item to the appropriate form. The advantages of this forging procedure include the removal of flash and a good grain structure. While roll forging employs rollers to make components and components, it is nevertheless

regarded a metals forging process and not a roller process. Roll forging is widely used to manufacture automobile components. It is also utilized to forge objects such as knives and screwdrivers.

Upset Forging Process

Upset forging is a forged procedure that uses compression to expand the width of the metal. In upset forging procedures, crank presses, a type of high-speed equipment, are employed. Crank presses are often situated on a horizontal position to optimize efficiency and the rapid interchange of metal from one unit to the next. Hydraulic presses and vertical crank presses are also employed. The benefits of this technique include a high output rate of up to 4500 components per hr and full automation. It also generates very little to no trash.

Isothermal Forging Process

Isothermal forged is a method of forging in which the ingredients and the die are both warmed to a similar temperature. The term is derived from the Greek word "iso," which ans "equal." This type of forging is widely employed for striking aluminium, due to its lower forging temperatures than other metals like steel.

Forging temperatures for aluminium are about 430 °C, whereas steels and super alloys may reach temperatures ranging from 930 to 1,260 °C. The benefits include the near net forms lead to decreased machining needs and, consequently, lower garbage rates, and the workpiece is highly repeatable. Another advantages is that smaller machinery may be utilised to manufacture the forging because to the lesser heat loss.

Equipment Used For Forging

The hammer and anvil is the most common form of forging equipment. The principle underlying the hammer and table is still utilised today with drop hammered forging equipment. The hammer is lifted before being dropped or pushed into the anvil, which is supported by the anvil. The fundamental distinction between drop hammers is how the hammer is propelled, with air and steam hammers being the most popular. Drop hammers are usually used in a vertical posture. This is due to the fact that any surplus energy that is not emitted as heat or noise, i.e. energy that is not utilised to form the workpiece, must be transferred to the foundation. To absorb the effects, a vast machine core is also necessary.

To solve various disadvantages of the hammer, the counterblow device or reaction force is utilised. In a counterblow tool, the hammering and anvil both move with the work held between them. Here, extra energy generates rebound, allowing the equipment to function laterally and have a lower population. This reduces the amount of noise, warmth, and vibration. The term "electronic commerce" refers to the sale of electronic goods. These devices are used for exposed die or closed die forging. For press forging, a press is utilised. Mechanical and hydraulic crushers are the two primary kinds.

Mechanical presses use cams, crank, and toggles to produce repeatable hammer strokes. Because of the properties of this sort of mechanism, various forces are accessible at different stroke points. As a result, the presses are 50 strokes per minute quicker than their hydraulic equivalents. Their capacities range between three and 160 MN. Hydraulic presses employ fluid and a piston to create force. The flexibility and better capacity of a hydraulic over a mechanically are its advantages. The drawbacks include the fact that it is slower, bulkier, and more expensive equipment to run.

Upsetting forging

Upsetting is a basic deformation process which can be varied in many ways. Upsetting of metals is a deformation process in which a (usually round) billet is compressed between two dies in a press or a hammer. This operation reduces the height of a part while increasing its diameter. Upset Forging or Upsetting is described as 'free form', by which a billet or a section of a workpiece is decreased in height between normally plane, perpendicular. Upsetting is a fundamental deformation process that may be altered in a variety of ways. Metal upsetting is a compressive stress in which a billet (typically round) is squeezed with two dies in some kind of a press or hammer. This technique decreases a part's height while expanding its diameter. The procedure is typically employed as an intermediate stage in multiple element forging processes. The billet can be forged cold, heated, or hot.

Piston

Pistons are essential parts of internal combustion engines, rotary pumps, gas compressors, and pneumatic cylinders, among other things. It is the translational component which travels inside the cylinder and turns the reciprocating action into rotary movement or vice versa.

Forged Piston Vs Casted Piston

Gravity die casting' is the technical term. To keep things simple, a cast piston is made by pouring molten aluminum/silicon alloy into a mould. Forged pistons differ significantly in terms of production and intrinsic nature. , and so forth. In a nutshell, it's a win-win situation. Gravity die casting is the technical term.

However, for the sake of simplicity, a cast piston is made by pouring molten aluminum/silicon alloy into a mould. Forged pistons differ significantly in terms of production and intrinsic nature. , as a result of the aforementioned.

Casting and forging produce two types of pistons. A die for formed piston must be built so it may readily be withdrawn and, as both a result, the hammered blank (or unfinished engine) has a fairly basic shape. Casting can provide a more complicated blank, allowing for lighter fabrication. Furthermore, due to differences in production techniques, forged pistons are often more costly than cast goods. A cast pistons is more likely to splinter and harm the engine, in general more than a forging piston where as a key advantage with forged pistons that they normally result with a more elastic deformation, with the effect being the engine can sustain a higher amount of detonation before collapsing.

Manufacturing Forged Piston

During the piston manufacturing process, a billet of aluminium is obtained and a hot forging process is performed on it. The billet is warmed to 427 C before being placed on the lower die and completing the forging process over it. This results in the upsetting operation in the billet. The change in micro tends to improve the stiffness of piston.

Alloy Wheel

During the piston manufacturing process, a billet containing aluminum alloy is obtained and a hot forging process is performed on it. The billet is warmed to 427 C before being placed on the depressed mood and completing the forging process over it. This results in the upsetting operation in the billet. The change in structure tends to improve the force of piston.

High Pressure Die Casting

To clamp the die closed, a die is positioned in a huge machine with a strong closing force. The warm magnesium is pumped into a shot sleeve, which is a filler tube. The metal is pushed into the die at high speed and pressure by a piston, the magnesium hardens, and the die is opened, allowing the wheel to be freed. Wheels manufactured by this technology can offer savings in price and increases in corrosion protection but they are less bendable and of lesser strength because of the characteristics of HPDC.

The rolling process is a ductile material in which metal(s) in semi-finished or final form are moved between two opposed rollers, which compresses the metal and decreases its thickness. The rollers circle the material as it tries to squeeze between them. Where basic forms are to be created in big quantities, rolling is the most affordable procedure. Sheets, structural forms, and rails, as well as intermediary shapes enabling wire drawing or forging, are examples of rolled goods. Circular forms, 'I' beams and railroad rails are made using grooved rollers

Working Principle of Rolling

Rolling provides the most cost-effective method when making basic shapes in big quantities. Sheets, rails, and intermediate forms for electrical applications or forging are examples of rolled goods, as well as structural shapes and rails. Rolls with grooves are used to create circular forms, "I" beams, and railroad tracks. In comparison to any other rolling procedure, this one is heavily utilised. The metal is warmed well above temperature of recrystallization during this procedure. Because of the heat used during the hot production line, the metal's grain structure changes, resulting in a new set more strain-free grains. Because less force is used during this process, the metal's surface finish quality suffers as a result.

There is currently a cold rolling procedure, which is another type of rolling. Depending on the metal, ambient temperature may also be below the temperature at which recrystallization takes place during this rolling process.

Two High Reversing Mill

The rollers in this kind of mill are both movable. The two rollers of these mills rotate in two distinct directions. In this process, the metal is moved through two rollers that revolve in opposite directions but at the same speed. In addition to numerous other applications, it is utilised in plumbing, rail, slabbing, and plate roughing. As a reversing drive is required, this mill is less expensive than the others [3].

Two High Non-Reversing Mills

Smaller and less expensive motive power may be employed in two-high non-reversing mills since there are two rollers that continually rotate in the same direction. However, material must always be re-transported over the mill's top to enter the rollers again. In open train panel mills and mills where the bar only passes once, this configuration is employed.

Three-High Rolling Mills

The three rolls of this mill are arranged parallel to one another. The rolls are turning counterclockwise. The material in this mill travels in between the primary and second rolls. The bottom roll revolves in a different direction if the middle roll turns in a certain way. The material is produced in three high crankshafts both forward and backward.

It initially moves across the last and third roller before turning around and moving through the initial and second roller. In the mill, the material's thickness is decreased and becomes uniform with each pass. Here, a less powerful motor and transition mechanism are required.

Four High Rolling Mills

There are four parallel rollers stacked one on top of the other in this kind of mill. The first and fourth rolls in this procedure rotate inside the opposite direction from the second and third rolls. When stiffness is required, the third and fourth rolls are shorter to give it. These are referred to as back up sheets. It is employed in both the cold and hot rolling of sheets, strips, or plates as well as the hot rolling of armor.

Tandem Rolling Mills

It includes two or three roll stands aligned parallelly. Such that each one may be continuously passed through while changing the material's direction.

Cluster Rolling Mills

It consists of two or three rolls arranged in parallel alignment. in order to shift the material's orientation while making a continuous pass through each one consecutively.

Rolling (metalworking)

Rolling is a metal forming technique used in the metalworking industry. It involves passing a metal stock between one or more pairs of rollers to decrease thickness, make thickness uniform, and/or imparting a desired mechanical feature. The idea is comparable to how dough is rolled out. The heat of the metal being rolled determines the kind of rolling. Hot rolling is the term for a procedure when the metal is heated above its recrystallization temperature. Cold rolling is the method used when the metal is at a temperature below its recrystallization temperature. Hot rolling is the most widely used manufacturing process in terms of tonnage, while cold rolling is the most often used cold working technique.

Hot rolling

A metalworking technique known as hot rolling takes place above the material's recrystallization temperature. The granules recrystallize after deforming during processing, maintaining an equated morphology and preventing work hardening of the metal. Large chunks of metal, such as semi-finished casting products like ingots, slabs, flowers, and billets, are frequently used as beginning materials. In general, the mechanical characteristics or residual stresses brought on by deformation in hot-rolled metals are not very directed. Workpieces that are less than 20 mm (0.79 in) thick frequently have some directional characteristics, and non-metallic impurities can also sometimes impart some directionality. Many residual stresses will be created by uneven cooling, which typically happens in forms like I-beams that have an uneven cross-section. Although the completed product is of great quality, mill scale, an oxide that develops at high temperatures, has coated the surface. It is often eliminated by pickling or the SCS process, which displays a smooth finish. The typical range of dimensional tolerances is 2 to 5% of the total dimension.

Shape rolling design

Roughing, intermediate, and completing rolling cages are often used divisions in rolling mills. A round or square beginning billet with an edge diameter generally around 100 and 140 mm is

constantly bent during shape rolling to create a specific end product with a lower cross section size and geometry. A variety of sequences can be used to make a certain end product from a given billet. To minimise the frequency of rolling passes is a usual request due to the high cost of each rolling mill (up to 3.5 million euros). Numerous methods, including the use of numerical models, artificial intelligence tools, and empirical knowledge, have proved successful.

Sheet Metal Forming

Metal is made into sheet metal by being shaped into thin, flat pieces. One of the most practical methods for working with metal is sheet metal, which can be repaired and cut into a variety of forms and sizes.

Sheet metal is used in the production of a broad variety of items, making it a crucial component of the contemporary world. The thickness of sheet metal varies. Its gauge, a measurement, is used to determine how thick it is. If the gauge number is higher, the metal will be thinner.

Sheet Metal Material Used in the Process

Aluminum and stainless steel are the most often utilised materials in the production of sheet metal. The most popular stainless steel grades are 304, 316, and 410. One of the more popular grades is 304. It is not, however, offered in sheet form. The other wide range of steels are far more strong and resistant than 304. There are four recognized grades of aluminum: 1100-H14, 3003-H14, 5052-H32, and 6061-T6. Each grade is more powerful than the others and is utilised in a variety of tools, tools, and weapons.

Sheet Metal Forming Processes

This is a frequently employed manufacturing procedure that aids in producing parts for a huge variety of known and unidentified functions. The pieces are created between two dies during the sheet metal forming process, which is carried out on a press. Punches refer to the die there at top. Metal sheet is cold formed.

Bending

For the purpose of producing the metal components, this procedure involves bending sheet metal. The procedure involves using dies to bend little lengths of metal. Longer metal lengths are pressed using press brakes.

For complicated forms, repeated twisting is also employed. Additionally, sets of rollers are used for this.

Roll Forming

The sheet metal is bent repeatedly in preparation for roll formation. The sheet metal is supplied into a sheet metal forming line by a number of roll stations. Both on sides of the sheet, a roller die is provided at each station.

These rollers may be positioned on the sheet at various angles. The sheet flexes and deforms when it is pushed through the roller dies.

Spinning

High-speed rotation and pressure against an earlier mounted headstock spindle are applied to the sheet metal. The metal is supported while spinning by a tailstock. To get the metal into the desired shape, pressure must be applied to it using a specific tool.

Deep Drawing

The metal is placed in the die rather of being clamped. Cupping refers to the initial step in a deep drawing. While the punch goes downward and inserts the negative into the cavity, a pressure pad keeps the blank in place on the die. The metal is pulled over the edge and bent plastically until the cup is created. In the meantime, the pressure pad smoothest out all the creases. Repeated deep drawing allows for the formation of many deeper products.

Stretch Forming

Stretch forming is a compression molding technique used to create massive, curved pieces by simultaneously stretching and bending a piece of sheet metal over a die. On a stretching press, where a sheet of metal is tightly grasped along its borders by gripping jaws, stretch forming is carried out.

Hot Working

Hot working is the term used to describe a metalworking operation that is performed above the metal's re-crystallization temperature. The temperature at which any flaw in the metal generated by the working process may be fixed is known as the re-crystallization temperature. The material is heated until it reaches a plastic state in this process, and then pressure is used to produce a variety of sizes and forms. The pressure causes the metal particle size to change, which enhances the metal's mechanical capabilities.

Forging is referred to as hand and smith forging if pressure is exerted with a hand hammer. Hammer forging is the process that results when power hammers are used instead of hand hammers. Hot forging is the term used to describe this kind of hot metalworking. Forging, extrusion, drawing, and other processes may all be done in the heat. When metals are treated above the temperature at which they re-crystallize, they turn plastic and start to sprout grains.

Advantages of Hot Working

1. It may be used for work involving mass manufacturing.
2. It is simple to alter the metal's size and shape.
3. Because metalworking is performed at high temperatures, more deformation is possible.
4. The grain structure of metal will be improved.
5. It is possible to reduce stresses and other flaws.
6. Hot working produces uniform metal structures free of flaws and blowholes.
7. Metals can have good mechanical, physiological, and chemical characteristics.
8. All forms of flaws brought on by gas pores and compositional variations are eliminated during hot working.
9. The anisotropic behavior of metal is reached.
10. After the treatment, metal regains its softness and ductility.
11. Hot working is a quick, dependable, and affordable procedure.

Cold Working

A metalworking procedure is referred to as a cold working process if it is carried out below the re-crystallization temperature. Comparatively speaking, this procedure requires more power than hot working. Cold working makes it simple to deal with pliable, soft metals. However, this technique results in deformed grain structure and hardness. Rolling, bending, spinning, etc. all require the cold working technique.

The following mechanical characteristics of metals are also greatly impacted by the cold working procedure.

1. Difficulty.
2. Yield Power.
3. Dexterity
4. Strength in Tension.

Shearing

Shearing, commonly referred to as die cutting, is a method of cutting stock that doesn't result in chips or need the use of scorching or melting. Shearing is the correct term when the slicing blades are straight; shearing-type procedures are used when the chopping blades are curved. Stainless steel or plates are the materials that are sheared the most frequently. Rods can, however, also be sheared. Blanking, piercing, roll cutting, and trimming are examples of shearing-type processes. Metal, cloth, paper, and plastics are all utilised with it.

A workpiece is pushed against by the die (or static blade), which is fixed, using a punching (or moving blade). Depending on the material, the clearance between two is typically between 5 and 40 percent of the depth of the material. Clearance is the distance between the blades, calculated orthogonal to the direction the blade movement there at point where the cut action occurs. It influences the machine's power usage and cut quality (burr). Due to this, the material between both the die and the punch experiences very concentrated shear pressures.

Simple tool Shear machining differs significantly from standard machining. A one or several point instrument can be utilized in standard tool machining to remove a piece of metal from of the metal plate and/or blocking. The metal has to be pounded repeatedly in order to acquire the desired proportions. The cutting edge of the tool separates the metal from of the plate during shear machining. Maximum pressure is exerted while this is happening. But the tool only makes one contact with the metal.

Punching

Scrap is the substance forced through the die. The punch will be precisely the same size as the hole that has to be punched. To get the clearance, a small expansion of the die aperture is required. Through the stripper, the sheet metal is inserted between both the punch and die. As it descends, the punch punches a hole in the metal. The metal that has been punctured falls through the die aperture. The punch rises after penetrating. The punch surface may become adhered to by the metal sheet on the die. The steel plate from punch is removed by the stripper.

Blanking

Cutting a flat sheet into the desired form is the process of blanking. The needed product is the metal that was blanked through the die. Scrap metal has been left on the die. The blank has been further treated by being bent or drawn on. The width of the die affects the blank's dimensions. As a result, the blank size is the same as the die opening size. The punch is given the all-clear.

Cutting off is the process of removing a section from a metal sheet. Either a perfect line or perhaps a curve is used to make the cut. The machine frame is attached to the bottom blade. The ram is attached to the top blade. The movement is vertical. Between both the two blades is the workpiece. The sheet metal is severed when the higher blade descends. The blades' cutting edges

are separated by a little gap. The thickness of the material affects the clearance. Cutting off leaves no scrap behind.

Parting

Cutting the sheet metal separate two pieces is the process of parting. The machine frame is attached to the two bottom blades. The bottom blades' cutting edges are separated by a gap. The thickness of steel plate affects this gap. One can change the gap. The ram is attached to the top blade. Between the top and lower blades is where the workpiece is positioned. The higher blade descends and slashes through the sheet metal. This surgery involves some scarp removal.

Notching

The process of notching by rating agencies involves assigning several credit ratings to specific obligations and debts of a specific issuing company or of companies that are intimately connected to it. Rating distinctions are created between commitments based on variations in their stability or claim priority. Obligations may be raised or lowered with varied degrees of damages in the case of default. Therefore, although having an overall creditworthiness of "AA," business A may only have a "A" rating for its junior debt.

Working of Notching

Credit rating companies assess a company's creditworthiness and capacity to fulfil its financial obligations and other commitments. However, a business may also issue other debts (such as secured vs. unsecured obligations) or related debts (. Due to certain risks or limitations associated with those commitments, the credit rating for those specific debts or obligations may differ slightly from the producing company's overall credit rating.

The senior unsecured debt of an obligor (base = 0), or perhaps the corporate family rating, serves as the baseline upon which an instrument is graded in either direction (CFR). The structural dependency of bond raised by operational subsidiaries or holding businesses is also subject to notching, according to S&P. For instance, a holding company's debt can be observed to be lower than the indebtedness of its subsidiaries, which are the legal entities that actually own the company's assets and cash flow.

Machining

By carefully controlling the removal of material, a material (typically metal) is cut into the appropriate final form and size during the machining process. The procedures that share this characteristic are collectively referred to as subtractive manufacturing, which makes use of machine tools, as opposed to additive manufacturing (such as 3D printing), which adds material gradually.

Many metal goods are manufactured with machining, but it may also be used on materials including wood, plastics, ceramic, and composites. A machinist is a person who focuses in machining. The term "machine shop" refers to a space, edifice, or business where machining is carried out. The majority of current machining is done using computer numerical control (CNC),

Machining operations

In turning, material is removed from a spinning workpiece using a cutting tool with the a continuous cutting edge to create a cylindrical form. The workpiece's rotation provides the

primary motion, and the feed movement is produced by gently rotating the cutting tool in a direction perpendicular to the workpiece's axis of rotation.

Making a circular hole requires drilling. A spinning tool with generally two or four helical milling cutters is used to do it. To create the circular hole, the tool is inserted into the workpiece in a perpendicular direction to its axis of rotation.

One of the sizing procedures called reaming takes a little bit of metal out of a hole that has previously been bored. A rotating tool with many cutting blades is slowly moved in relation to the material during milling to produce a level or straight surface. The feed movement is in a direction that is anticlockwise around the rotational axis of the tool. The spinning milling cutter provides the speed action.

Cutting tool

A cutting tool is formed of a material that is tougher than the work material and contains one or much more sharp cutting edges. Chip is separated from the parental work piece material by the cutting edge. The two tool surfaces are attached to the cutting edge:

Rake face, and the side

The rake angle refers to the angle at which the rake face guides the flow of freshly created chips. In relation to the plane orthogonal to the work surface, it is measured. Both positive and negative rake angles are possible.

In order to prevent abrasion, which would damage the finish, the tool's flank creates a space between it and the freshly produced work surface. The relief angle refers to the angle formed by the work surface and also the flank surface. Two fundamental categories of cutting instruments exist:

Tools with a single point and many cutting edges

A single point tool is utilized for turning, boring, and planing and has only one cutting edge. The tool's tip penetrates beyond the workpart's initial work surface during machining. Sometimes the point is rounded to a radius known as the nose radius.

Tools with multiple cutting edges often use rotation to move in relation to the workpiece and have more than one cutting edge. Rotating tools with several cutting edges are used in milling and drilling. Although these tools don't have the same forms as single-point tools, they have many geometrical characteristics.

Stages in metal cutting

According to the intended use and the cutting circumstances, machining processes are often divided into two categories:

1. Rough cutting
2. Final touches

In order to produce a shape that is close to the desired form while still leaving some material on the portion for a subsequent finishing operation, roughing cuts are used to remove a massive amount of information from the starting workpart as quickly as possible i.e. with a large Tool Wear Rate (MRR). To complete the product and obtain the desired final size, tolerances, and surface polish, finishing cuts are employed. Jobs involving production machining.

Single Point vs Multi-point Tools

Single point and multi-point tools are the two fundamental categories of cutting tools. For turning, drilling, and planing, use single point tools. For milling and drilling, use cross tools. For purposes of quality, it is essential to operate and preserve the cutting equipment appropriately. Unfortunately, maintaining equipment and tools properly may be expensive.

A range of materials are available for tooling. High-speed steel and carbide are the most widely used. High-speed steel (HSS) is a possible material to employ for general milling. To manufacture stronger and harder tool steels, however, use carbide.

Cutting Speed, Feed Rate, Depth

When machining, it's important to take spindle speed, scanning speed, and cut depth into account. These characteristics will be influenced by the material of the workpiece, the tools, and the dimensions. Cutting speed is the rate at which the workpiece material is sliced by the cutting tool. Surface feet per hour are used to measure it. Cutting feed describes the rate at which the workpiece travels in the direction of the cutting tool. Inches per minute are used to measure it.

Machine Turning

While turning, the work item rotates while a cutting tool advances linearly. As a result, the form is cylindrical. The preferred tool for all turning activities is a lathe. Turning is either carried out manually or mechanically, like the majority of machining processes. The drawback of manual turning is that it needs constant observation. Turning on autopilot does not. Programme all the motions, speeds, and equipment changes into a computer using numerical control control, or CNC. The lathe will then be given these instructions to complete. High production run uniformity and efficiency are made possible by CNC. Turning single point cutting tools come in a variety of forms. They are positioned at various angles to provide a range of results.

Machine Drilling

A workpiece gets a circular hole thanks to drilling. Drilling is done with a drilling machine or tapping machine, however milling machines can also be used for this task. Chips are the little metal fragments left over after machining a workpiece. The drill bit's design encourages chips to disappear altogether from the surface, keeping it free of contaminants.

Drifting or leading-off are reduced when the drill bit is positioned parallel to the workpiece. Before drilling, a centre drill operation is frequently added for even greater accuracy. Angular drilling is required for several drilling procedures. Special work-holding tooling is needed for angular drilling. Other alternatives include using a CNC machine's numerous axes or rotating the blade on a mechanical machine.

Machining Innovation

It takes a lot of labour to machine a workpiece that is flawlessly smooth, accurate, and useful. It calls for a great deal of experience and attention to detail. The most popular machining techniques include turning, drilling, and milling. They have been around for a very long time. Fortunately, machining has greatly improved with the advent of CNC. While traditional machining still serves a function in the industrial industry, CNC machining is more prevalent. Large production runs may be made more effectively and consistently. American Machinist is an excellent resource if you're interested in staying current with the most recent developments and news. Numerous metal products are produced by machining, but other materials including wood,

plastic, earthenware, and composites can also be produced in this way. A person who focuses on machining is known as a machinist. Any space where machining is carried out is referred to as a machine shop. Modern machining makes extensive use of computer numerical control (CNC), it employs computers to direct the motion and usage of mills, lathes, and other cutting tools. By enabling the Cnc router to work unattended, this increases efficiency and lowers labour costs for machine shops. By gradually removing excess material from the blank solution in the form of chips with a cutting tool or tools that are driven through the work surface, jobs are generated to the proper dimensions and surface polished throughout the process of machining (s). A machine tool is a piece of powered machinery used to precisely size, cut, and process a production by removing superfluous materials in the form of chips. Lathe, drilling, shaping, and planer machines are some examples of machines.

Questions

1. What do you mean by manufacturing?
2. What are composite material?
3. Elaborate manufacturing process/
4. What is rolling?
5. What is Hardness?
6. Define Ductility And Malleability
7. Define Strength And Resilience
8. Define Brittleness
9. Define Toughness And Impact Power
10. Define Fracture of Material
11. Define Manufacturing Products
12. Define Forging

References for further study

1. "Manufacturing Science" by Ghosh A and Mallick A K
2. "Manufacturing Technology: Foundry, Forming and Welding" by Rao P N
3. "Introduction to Manufacturing Processes" by Schey J
4. "Materials and Processes in Manufacturing" by DeGarmo E P and Black J T and Kohser R A
5. "Injection Mold Design" by David O Kazmer
6. "Manufacturing Processes" by Kaushish J P
7. "Manufacturing Process for Engineering Materials" by KALPAKJAIN
8. "Manufacturing Processes" by S K Sharma and Savita Sharma
9. "Manufacturing Process" by Dhar
10. "Manufacturing Engineering" by SINGH K HIRANIYA
